LAND CORNER RECORDATION CERTIFICATE Filing Requirement of Act 74, Mich. P.A. 1970

For corners in Dickinson		1							
(County)	Located In:	Corner Code ≠≠							
Public Land Survey .	T <u>40N</u> R <u>30W</u> T R T R T R	_ £3							
Property Controlling In Section Miscellaneous	S T R S T R		-						
Property in Sec.			Regist	er of D	eeds St	amp & I	File N	umber	<i>.</i>
	Recorded Pial			A B	C D E	FG	нι	J K	L
5. Private Claims						-] 		1
I. Staphan J. Szyszkoski	, in a field survey on	a 15, 1994 . 19	4	-	╼┋╼╅╴	╺╿┼╌	訲	- - -	{a
do hereby certify that under requirements of P.A. 74, Michigan P.A. of 1970, the corner points mentioned in lines 1 and 2 above were in conformance with regulations and rules therefore as required in the current manual of survey instructions of the United States Department of the Interior, Bureau of Land			the	-13-	-17	10	15	-14	_ j_
Management or by a decree of a Court of Law and/or that the corner points mentioned in lines 3, 4 and 5 above were in conformance with the rules of the Michigan Board of Land Surveyors or by a Decree of a Court of Law; established, re-established, monumented, re-monumented, recovered, jound as			nd 5 s	-19	-20	-21] 	23	
expressed below:	re-essablished, including ter	incribinatiled, recoreted, toolig	10		<u>-</u> ;	- /-	<u>,, </u>	26	_ 5_
NOTE: Not more than 4 on this certificate	comers, all in the same town a: i.	nd range, may be recorded	11 12	ПП	- - 	***	 	35	-36-

- A. Description of original monument and accessories and/or subsequent restoration:
- [E3] Corner common to Sections 4-5-8-9. Corner resonasented in 1975 by A.C. Enger, RLS at the location of a found 1 1/4" iron pipe. Set 1"IDx34" iron pipe with 3 1/2" aluminum cap. 1975 MBTs were Red Maple 6 SBOW 8.2', Red Maple 7 S75E 27.4'. Found no subsequent
- B. Description of corner evidence found and/or method applied in restoring or reestablishing corner:
- (ES) Found the 1975 1° ID pipe projecting about 8° at record bearing and distance from both 1975 MBTs, blazes overgrown but in good condition. Also found 1 1/2" iron pipe - the previous monument - adjacent. The aluminum cap had been broken off of the 1975 monument but it's stem is still fixed firmly in the pipe. Left the monument as found and marked two additional witnesses as described below. Magnetic bearings to the 1975 MBTs are now \$84M and \$71E.

C. Description of monument for corner and accessories established to perpetuate locating the position of the corner:

(E3) Found 1" iron pipe with remains of aluminum cap in pipe. Blazed and scribed the following new bearing trees: 7° M. Birch 502W 14.4' "\$8 NBT" 8° Maple in clump of 3 N40E 27.7' (slope distance) "S4 N8T". Bearings are magnetic.



Surveyor's Michigan License No. 33986