## LAND CORNER RECORDATION CERTIFICATE

For corners in	Filing Requirement of Act 74, Mich. P.A. 1970									
Dickinson (County)	Located in:	Corner Code #								
1. Public Land Survey	T41N R T41N R T R	2911 110								
Property Controlling in Section Miscellaneous Property in Sec.	S TR S TR S TR S TR			Regist	er of Do	eds St	tamp (	L File	Numb	) <b>(</b>
4. Lot No, Recor 5. Private Claims	ded Plat		Ī	<u>A B (</u>	: D [	5 F (	5 H	ΙJ	ĸ	L
	I10 M11	Sep 09 1998 Sep 10 1998	2 3		-5-	- 4 -	3-		+	Ţ <del> </del>
conformence with regulations and United States Department of the in that the corner points mentioned	rules therefore se require nterior, Burseu of Land IV in lines 3, 4 and 5 above a Decree of a Court of	19 do hereby state to provide the points mentioned in lines 1 and 2 above do in the current manual of survey instructive lengement or by a decree of a Court of Lawre in conformance with the rules of the f Lawr, established, re-established, mon	one of the 5 W and for 6 Michigan	18-	-8- -17- -20-	— 9— —16—	-10- -15- -22-	14		13
NOTE: Not more than 2 com on this certificate.	ers, all in the same tow	n and range, may be recorded	9 10 11	30_		28 		26	- -	25
A. Description of original mo-	nument and accessor	es and/or subsequent restoration;	13	Ш		inal w				Ĺ

D. Buckler in 1954: "This corner was found by Forestry division survey crew, while making a partial resurvey of this area. 3 original B.T.'s still in place, in good condition. Corner was placed and witnessed July 26, 1954. Description of corner monument: I' pipe with 4" brass cap. Witnesses to corner 10" Cedar S60E 29 links, 12" Cedar \$85W 30 links,

(110) Quarter corner common to Sections 26-27. Established in 1849 by John Burt: "North between Sections 26 & 27...40.00 Set Cedar Qr. Sec. post. W. Pine 36 S80W 5, Hemlock 18 M67E 24."

## B. Description of corner evidence found and/or method applied in restoring or reestablishing corner:

(MII) Recovered the 1954 monument as described, a 1° ID iron pipe capped with a 4° dia. brass Michigan Dept. of Conservation tablet, in good condition, and at record bearing and distance from the two 1954 Cedar MBT's, found in good condition. Someone has placed measuring nails in the sides of the trees and also in two other nearby Cedars. The original Cedar BT's were found at record bearing and distance, burned and very rotten, with no visible marks. I accept the monument as a careful and faithful perpetuation of the position of the original corner. Left the monument in place and made measurements to the existing MBTs. Corner recovered and rewitnessed by D.Lampela and B. Wheeler, Baraga District Office.

(IIO) Original post and accessories were not recovered. Found no acceptable evidence of the position of the original corner on the ground. Reestablished the corner midway and on a line of mean true bearing between Section corners 2630.74° north and south. At the position for the corner I placed a 1°IDx32° iron pipe capped with a 4° dia. cast aluminum MDMR tablet, appropriately stamped. Corner placed and witnessed by D.Lampela and B.Wheeler, Baraga District Office.

C. Description of monument for corner and accessories established to perpetuate locating the position of the corner. (II) Found I pipe with 4 brass cap. (II0) Set I pipe with 4 HDNR cap. (MII) Found I pipe with 4 brass cap. Found nails in the sides of the Blazed and scribed the following:

following trees: 4" Spruce \$24W 16.15" "1/4S MBT" 18' Cedar \$56E 19.5' with old blazes 5" Spruce S40# 34.4" 5" Spruce NB5W 26.9"

ďο 14" Cedar West 20.1 do 12" Cedar N39W 19.5" 12" twin W.Pine S27E 88.0" do 13" Cedar N71E 41.2" Placed a squared cedar post adjacent.

Bearings are magnetic. Distances are to Bearings are magnetic. Distances are to the nails. notch in lower blaze.

OFMICH STEPHAN J SZYSZKOSKI LAND SURVEYOR

33986 Surveyor's Michigan License No

For the Michigan Department of Natural Resources - Forest Management Division