## LAND CORNER RECORDATION CERTIFICATE

For comers in	Filin	g Requirement of Act 74, Mich.	. P.A. 1970				
Dickinson	Located In:	Corner Code #					
(County)			Į.				
1. Public Land Survey	T <u>(I) </u> R T R T R						
Property Controlling     in Section     Miscellaneous     Property in Sec.	TR S26T411_R STR STR STR	291 5	R	egister of C	Deeds Stan	np & File	Numbe
4. Lot No, Reco	rded Plat		. 3_	BCD		ніј	71.
<del>- :</del>	-	Oct 20 1998	2	65-		3 2	
conformance with regulations and United States Department of the I that the corner points mentioned	, in a field survey on on P.A. of 1970, the come inules therefore as required interior, Bureau of Land Ma in fines 3, 4 and 5 above we a Decree of a Court of	Sep 03 1998	ne of the 5	76-	16	1011	112
NOTE: Not more than 2 corr on this certificate,	ners, all in the same town	and range, may be recorded	9	3029_	28	27——26	$+\bar{+}$
			11 3	132-	33-4-	34 35	36
<ol> <li>Quarter corner common to Meen two Section Corners and</li> </ol>	Sections 33-34. Rees d at 40.00 chains from	e and/or subsequent restoration: stablished in 1961 by Billy D. Buc south Section Corner. The North	1/2 mile is sh	ort because	e of error	in measu	ırina

bet 4° brass cap 2 links south of corner. Witnesses: 8° Soft Maple M28E 63.5 links, 7° Hard Maple S40E 82 links. (5-Sec. 26) North 1/16 corner Section 26. Corner not established in the original survey. Found no subsequent record.

## B. Description of corner evidence found and/or method applied in restoring or reestablishing corner:

(G12) Recovered the 1961 corner as described, a chiseled "+" on exposed rock face and the 1" iron pipe capped with a 4" brass Michigan Dept. of Conservation tablet, both in good condition, and the "+" being at record bearing and distance from the 1961 witnesses, both recovered in good condition, with the 1961 blazes overgrown. My measurements show the "+" to be 6.6' West and 3.5' South of the record 1961 position. I accept same as a careful and faithful reestablishement of the position of the original corner. Left the accuments in place and marked two new accessories as described below. Corner recovered and rewitnessed by D.Lampela and B.Wheeler, Baraga District Office.

(5-Sec. 26) Found no evidence of prior monumentation at the corner position. Established the corner midway and on a straight line between Quarter corner 1310.06' north and Center of Section 1310.06' south. At the position for the corner I placed a 1° IO x 32° iron pipe capped with a 4" dia. cast aluminum HDNR tablet, appropriately stamped. Corner placed and witnessed by B.Wheeler and D.Lampela, Baraga District Office.

C. Description of monument for corner and a	accessories established to perpetuate locating the p	colling of the name and the same
(G12) Fd. chiseled "+" on rock face.	(5) Set 1 pipe with 4 MDHR cap.	Obligon of the configuration
Blazed and scribed the following:	Blazed and scribed the following:	A OF MICH
4" M. Pine \$46W 37.3' "1/45 MBT"	15" R.Pine S06W 16.05" "1/16S BT"	
12° W. Pine W16W 37.0' do	9" R.Pine \$66E 27.8' do	* STEPHAN J.
the 1961 witnesses:	15" R. Pine N15E 38.5' do	* SZYSZKOSKI
12" Maple N33E 41.9' overgrown blazes	8" W. Birch M48N 33.35' do	# LAND
10" Sugar 837E 54.1' do	Placed a squared cedar post adjacent.	SURVEYOR
1" pipe with 4" brass cap 1.2'	Bearings are magnetic. Distances are to	No.
southerly. Bearings are magnetic.	notch in lower blaze.	33986
Distances to notch in lower blaze.	tionen en semoi pamen.	CARDEG
		AND DESCRIPTION OF THE PERSON
Signed by Stucking .	Smysypoli Date	7/20/00
	X mystychi Date	3/30/17
Surveyor's Michigan License NoV	33986	

for the Michigan Department of Natural Resources - Forest Management Division