## LAND CORNER RECORDATION CERTIFICATE

	Fil	ing Requirement o	f Act 74, Mich.	P.A. 1970	)						
For corners in				1							
Dickinson	Located In:	Corner Code	#								
(County)			•								
1. Public Land Survey	T 41N F T 41N F T F	R 30W 16									
Property Controlling     in Section     Miscellaneous     Property in Sec.	TF S TF S TF				Re	gister	of De	eds Sta	amp &	File N	umber
4 Lot No Book	ided Diet										
4. Lot No, Reco	ded Plat				. A E	3 C	D E	F G	н	I_J	KLN
C. / Hvate Claims					1	֓֞֞֓֓֓֓֓֓֓֓֓֓֓֓֓֓֓֓֓֓֓֓֓֓֓֓֓֓֓֓֓֓֓֓֓֓	_		Ţ	Ĺ	
		Jun 28 2000			3 6	, —	٦	-i-	_ j_		T-i-
[ Stephan J. Szyszkoski	in a fold armorran	. 19	da banaba aka ak								
requirements of P.A. 74, Michiga				were in	4   Ti	-	- 8 <del> </del>	- <u>9</u>	—10— 	11 	12-
conformance with regulations and	l rules therefore as requi	red in the current manual	of survey instruction	s of the	5		-  -		-	<u> </u>	•
United States Department of the that the corner points mentioned	Interior, Bureau of Land In lines 3, 4 and 5 abov	Management or by a dec e were in conformance w	ree of a Court of Law /th the rules of the M	lichigan	6  1	8	-17	-16-	—15 <b>—</b> €	14-	13-
Board of Land Surveyors or by	a Decree of a Court	of Law; established, re	established, monur	mented,	7 ├─┤		+++	-	_		+
recovered, found as expressed be	How:			1	8  1	9	-20	-21-	2'2	-23-	24
NOTE: Not more than 2 corr	ners, all in the same to	wn and range, may be	recorded	9	9			$\dashv$	-+-		
on this certificate.				1	.0—3	0	-29-	_2 <sup>1</sup> 8	27	26	25—
				1	1	-	++				<del>                                     </del>
				1	23	1	-32	_33	34	35_	36
A. Description of original mo (K5) Section corner common to undersigned. Found 1° pipe w (16) Quarter corner common to section corners 2628.90' N an	11-12-13-14. Rees ith 4" brass cap. : Sections 14-15. Re	tablished and record 12" Maple SO7W 60.3' eestablished in 1981	ed in 1953 by D.C , 4″ Balsam S50W by K.L.Sackett,	45.5', 4" RLS, by si	Maple ngle	S64W propo	34.5° rtiona	te mea:		it betw	een
B. Description of corner evidence (K5) The 1953 monument was restub. The maples are in good below.  (I6) Recovered the 1981 monualive with overgrown blazes, and faithful reestablishment below.	covered at record be condition with scr ment as described, i Verified the posit	earing and distance ibing visible. Left in good condition, a ion of the monument	from the 1993 wit the monument in nd at record bear with respect to t	tnesses. T place and ring and di the section	The 19 marke stanc	d two e from	new w m the nd acc	itness 1981 w epted :	es as ( itnesse same as	describ es, bot s a car	ed :h :eful
3" Maple N83E 64.3' The 1993 wits: 14" Maple S07W 60.3' scribin	ass cap. (1) ing: 8. \$14 MBT" 6 \$12 MBT" 1 g visible 1. do 10 earings are 80	sories established to r 16) Found 1 pipe will lazed and scribed the "Sugar S22E 31.5" 4" Maple West 99.2" the 1981 wits: 1" Maple NOTE 45.8" "Maple S64E 31.5" tearings are magnetic botch in lower blaze.	th 4° MDMR cap, e following: "1/4S HBT" do ovrgwn blazes do			STEP SZYS: L/ SUR	HAN ZKOS AND VEYO No. 3986	1	***		
Surveyor's Michigan License	No.	33986			<u>~_</u>						
- arroyor a mineringali Licelise											