LAND CORNER RECORDATION CERTIFICATE Filing Requirement of Act 74, Mich. P.A. 1970

For corners in				
Dickinson (County)	Located In:	Corner Code ≠#		
1. Public Land Survey	T 42N R 28W T R T R T R			
2. Property Controlling in Section	S T R S T R			
Miscellaneous Property in Sec.	S T R		Register of Deeds Stamp & File Number	
	Recorded Plat			ر T
				12
do hereby certify that under re in lines 1 and 2 above were it current manual of survey instr Management or by a decree of above were in conformance wi	, in a field survey on	A. of 1970, the corner points ment and rules therefore as required artment of the Interior, Bureau of her points mentioned in lines 3, 4 i of Land Surveyors or by a Decre	ntioned 6 18 17 16 15 14 19 16 15 14 17 16 15 14 17 16 15 14 17 16 15 14 17 16 15 14 17 16 15 17 16 15 17 16 15 17 16 15 17 17 16 15 17 17 17 17 17 17 17 17 17 17 17 17 17	13-24-
NOTE: Not more than 4 corners, all in the same town and range, may be recorded on this certificate.			17171717171	36-

- A. Description of original monument and accessories and/or subsequent restoration:
- K-1. NE section corner of Section 2. 1" pipe w/4" brass cap. Mich. Cons. Dept. 1952. 8" spruce, S43E, 16 lks.; 6" spruce, N72W, 37 lks.
- I-1. NW section corner of Section 2. w. birch post, John Burt, D.S., 1846. w.pine 22, N25E, 30 lks.; hemlock 22, N45W, 38 lks.; y.pine 24, S25E, 29 lks.; hemlock 14, S66W, 30 lks.
- J-1. N 1/4 corner of Section 2. Cedar post, John Burt, D.S., 1846. Cedar 5", N80E, 22 lks.; DO 5", N57W, 17 lks.
- B. Description of corner evidence found and/or method applied in restoring or reestablishing corner:
- K-1. Found brass capped Cons. Dept. monument. Both 1952 witnesses are in place but the SE one is dead and is now a broken off stub. Re-witnessed monument as found.
- I-1. Set by single proportion to the GLO record between the NE section corner of Section 2 and the N 1/4 corner of Section 3. Remains of w and y pine stumps in the area but mostly very fragmented. The area has also burned very hard at some time in the past. Could not identify OBT "S.
- J-1. Set MPOL between the NE and NW section corners of Section 2. Cedar remains down and very rotten in the area but could not identify OBT's.
- C. Description of monument for corner and accessories established to perpetuate locating the position of the corner:

K-1. Brass Cons. Dept. Monument. I-1. DNR Monument. J-1. DNR Monument. 4" spruce, S85W, 22.3' 14" w.pine, S16W, 104.8' 9" b.spruce, N55W, 26.35' 7" spruce, N24E, 23.3' 5" r.pine, S83W, 97.1' 7" b.spruce, N22W, 16.9' 7" spruce, S55E, 24.3' 4" w.pine, N60W, 95.2' 8" b.spruce, N32E, 19.7' 9" spruce, N69W, 24.3' (1952 NBT) 9" j.pine, S46E, 35.4' 6" b.spruce, S33E, 13.15'

Signed by favil B. Babbi	Date 11-28-89
Supreporte Michigan License No. 21558	

FORM APPROVED BY MICHIBAN STATE BOARD OF LAND SURVEYORS, JAN. 28, 1971 REVISED MAY 14, 1975

08