LAND CORNER RECORDATION CERTIFICATE Filing Requirement of Act 74, Mich. P.A. 1970

For corners in Dickinson		Located In:	Corner Code ##		
_	(County)				
1.	Public Land Survey	т <u>42М</u> в <u>28М</u>	A6		
		T R			
		T R			
		T R			
2.	Property Controlling	S <u>18</u> T <u>42N R 28N</u>	_6		
	in Section	S T R			
2	Miscollanoous	S T A			

Register of Deeds Stamp & File Number

4.	Lot No	Recorded Plat	

5.	Private	Claims	

Property in Sec.

January 30, 1995

Movember 09, 1994 I, Stephan J. Szyszkoski , in a field survey on A6 do hereby certify that under requirements of P.A. 74, Michigan P.A. of 1970, the corner points mentioned in times 1 and 2 above were in conformance with regulations and rules therefore as required in the current manual of survey instructions of the United States Department of the Interior, Bureau of Land Management or by a decree of a Court of Law and/or that the corner points mentioned in lines 3, 4 and 5 above were in conformance with the rules of the Michigan Board of Land Surveyors or by a Decree of a Court of Law, established, re-established, monumented, re-monumented, recovered, found as expressed below:

NOTE: Not more than 4 corners, all in the same town and range, may be recorded on this certificate.

	_	_	_	_		_	_	_	-	_		$\overline{}$
2	L		L!		_ :		L!		_,	,_	L .	ļЦ
3		Ī						Ĺ				
								[
		, —	'	_	_ '	i	י	0— 		<u>'</u>	ו—ו	
5		•										
٩	- 1		<u>ا</u>	7	-1	6-	1	' 5 I	-1	4—	-1	3—
7	\vdash	H		-	\vdash		\vdash			\vdash	\vdash	Н
	۱	. —	— 2	-	-2	1—	├ ─2	2	—2	3 —	├ -8	4
9	\vdash	 	\vdash			-	⊢	├	_	_	\vdash	Н
10	-,	<u>.</u>	L-₂	.	2 2	<u>'</u>	2	<u>-</u> ۔	-2	6-	⊢ ₂	5_
11	L	Ц.	<u> </u>	lacksquare		<u>Ļ</u>	L	<u> </u>		L.	\sqcup	Щ
12	L	<u> </u> _	L,	_		<u>. </u>	L,	4	L,	ا 	L,	6
13		Ĺ		Ī.	Ľ	Ĺ	_	Ĺ		Ĺ		Ш

CDEFGHIJKLM

A. Description of original monument and accessories and/or subsequent restoration:

(A6) Quarter corner common to Section 18 T42M-R28M, and Section 13 T42M-R29M. Corner established in 1846 by John and Austin Burt as follows: "40.00 Set cedar post. Fir 5 S24M 16, Cedar 5 M25M 12." Original line notes show: south 1.5 ch. swaap edge, south 4.21 ch. 60' cliff, north 2.0 ch. swamp edge. Found no subsequent record.

(6-Sec. 18) Northeast 1/16 corner, Section 18. Corner not established in the original survey. Found no subsequent record.

B. Description of corner evidence found and/or method applied in restoring or reestablishing corner:

(A6) Original post and accessories were not recovered. Found no evidence of the position of the original corner on the ground. Found no evidence of subsequent monumentation. Corner falls in an alder marsh. Recovered several small coder stumps and boles submerged in the mater at the corner location, but none with any markings. Reestablished the corner by proportionate measurement to the original record, on a straight line between Section corners 7923.1 ft. north and south. The line calls noted above all check very well - the cliff, a 60' vertical drop, is at record distance south of the reestablished corner. At the position for the corner, I placed a 1"1.0.x32" iron pipe capped with a 4" dia. cast aluminum HDNR tablet, appropriately stamped. (6-Sec. 18) Found no evidence of prior monumentation at the corner position. Established the corner at the intersection of straight lines connecting opposite 1/16 corners, all monumented. At the position for the corner, I placed a 1°I.D.x32° iron pipe capped with a

C. Description of monument for corner and accessories established to perpetuate locating the position of the corner:

[A6] Set a 1 iron pipe with 4 MDNR cap. Blazed and scribed the following witnesses: 20" Tamarack N77E 56.5" "1/45 MBT" "1/45 NBT" 16° B. Spruce M29E 63.5' "1/45 MBT" 6° 0. Spruce \$35E 55.4' a" spruce stump, frashly cut NI3E 31.5' marked "MBT" Set a squared spruce post adjacent. Bearings are magnetic.

(6) Set a 1" iron pipe with 4" MDMR cap. Blazed and scribed the following witnesses: B" Cedar N41W 5.8 "1/165 BT" "1/165 BT" 8" Cedar M47E 18.4" 8" Cedar SOIN 71.8" "1/16S 8T" 10° Cedar \$49% 43.2° "1/16S BT" Placed a location poster on a 12" W. Birch snag MSBE 5.5'. Bearings are sagnetic.



33986 Surveyor's Michigan License No.

4" dia. cast aluminum HDHR tablet, appropriately stamped.

FORM APPROVES BY MICHIGAN STATE BOARS OF LAND SURVEYORS, JAN. 26, 187