LAND CORNER RECORDATION CERTIFICATE

	Filinç	g Requirement of Act 74, I	Wich, P.A. 197	D				
For comers in Dickinson	Located In:	Corner Code #						
1. Public Land Survey	T_42NR_ TR_ TR_	28M F2						
Property Controlling in Section Miscellaneous Property in Sec.	TR_ S26 T_42NR_ S TR_ S TR_ S TR_		ţ	Register	of Deeds	Stamp &	File Nur	nber
4. Lot No, Reco	rded Plat		_	A B C	D E F	G H 1	ı j K	<u>L</u>
5.1 HARIO CIGINIO	2	Jun 17 1997 Jun 19 1997		2 6 3		3-	_ 2 _	— - -
Stephan J. Szyszkoski	in a field expression	19 do hereby or points mentioned in lines 1 and 2	state that under	4	- - - 9-		_11-	12-
conformance with regulations and United States Department of the that the corner points mentioned	d rules therefore as required Interior, Bureau of Land Ma 1 in lines 3, 4 and 5 above w	d in the current menual of survey intenegement or by a decree of a Cour were in conformence with the rules	structions of the t of Law and for of the Michigan	5 19 7	17—16	15	-14-	— - -13-
Board of Land Surveyors or by a Decree of a Court of Law, established, re-established, monumented, recovered, found as expressed below:			, monumented,	8 -19	20-21	22	_23_	-24-
NOTE: Not more than 2 corr on this certificate.	ners, all in the same town	and range, may be recorded		10 30	-2928	27-	-26	— —25-
				11 12 31	3233-	34	35	—36- —
f2) Center of Section 4. C	orner established in l	es and/or subsequent restoration 1989 by D.B.Babbitt, Ris: "Se Manie N44F 36 9". R" Manie S	et at the inters	ection of t	he N-S and	E-N 1/4 Ironwood	lines of N39W 38	f .3'".

(2-Sec. 26) East 1/16 corner between Sections 23-26. Corner established in 1962 by Billy D. Buckler, RLS: This corner was placed midway and on line between section corner and 1/4 corner. Corner monument: 1° iron pipe with 4° brass cap. Mitnesses to corner: 12° Balsan S63N 46 links, 10" Spruce NilN 51.5 links".

B. Description of corner evidence found and/or method applied in restoring or reestablishing corner.

(F2) Found the 1989 monument, as described, in good condition, and at record bearing and distance from the two remaining bearing trees: The maple and Ironwood ME and MM. The maples south of the road have been recently cut. This corner lies in the approximate center of an E-N road. Left the monument in place and marked two new accessories as described below. Corner recovered and remitnessed by 8. Wheeler and D. Lampela. Baraga District Office. MDMR. No measurements to other corners were made at this time. This corner is being rerecorded in order to update the accessories.

(2-Sec. 26) Found the 1962 monument, as described, in good condition, and at record bearing and distance from the 1962 mitnesses. The balsam is now a rotten stump, and the spruce is in good condition. Left the monument in place and marked three new accessories as described below. No measurements to other corners were made at this time. This corner is being rerecorded in order to update the accessories. Corner recovered and remitnessed by B.Wheeler and D.Lampela, Baraga District Office, MDNR.

C. Description of monument for corner and accessories established to perpetuate locating the position of the corner.

first today in hibs aren a unuv co	ıμ
buried. Blazed and scribed the	
following new bearing trees:	
12" Maple 507W 39.5'	
6" Maple S18E 30.1'	

Bearings are magnetic.

(2) Found 1" pipe with 4" MI. Dept. of

Conservation cap. The 1962 witness: 10" Spruce N11N 33.5"

Blazed and scribed the following:

10" Basswood S18E 13.8' "1/16S N8T"

5" Ironwood N79W 37.2" "1/165 NBT"

4" Ironwood M24.5E 53.5" "1/16S M81"

Bearings are magnetic.

STEPHAN J. SZYSZKOSKI L'AND STIRVEYOR

339*8*6 Surveyor's Michigan License No.

For the Michigan Department of Natural Resources - Forest Management Division