LAND CORNER RECORDATION CERTIFICATE Filing Requirement of Act 74, Mich. P.A. 1970

Filing Requirement of Act 74, Mich. P.A. 19	970
For corners in	
Dickinson Located In: Corner Code #	
1. Public Land Survey	
2. Property Controlling S T R	Register of Deeds Stamp & File Number
	Register of Deeds Stallip & File Nulliber
4. Lot No, Recorded Plat	ABCDEFGHIJKLM
J. Filivato Ciantis	2 6 5 4 3 2 1
Jul 20 2000	3
Stephan J. Szyszkoski in a field survey on	4 - 7 - 8 - 9 - 10 - 11 - 12
requirements of P.A. 74, Michigan P.A. of 1970, the corner points mentioned in lines 1 and 2 above were in conformance with regulations and rules therefore as required in the current manual of survey instructions of the	5
United States Department of the Interior, Bureau of Land Management or by a decree of a Court of Law and /or	6 18 17 16 15 14 13
that the corner points mentioned in lines 3, 4 and 5 above were in conformance with the rules of the Michigan Board of Land Surveyors or by a Decree of a Court of Law, established, re-established, monumented,	7
recovered, found as expressed below:	8 - 19 20 21 22 23 24 -
NOTE: Not more than 2 corners, all in the same town and range, may be recorded	9
on this certificate.	10 30 29 28 27 26 25
	11
	12 31 32 33 34 35 36 3
(J1) M1/4 corner of Section 2. Corner reestablished in 1989 by D.B.Babbitt, RLS using probability and the section 2. Spruce M22M 16.9', 8" B.Spruce M32E 19.7', 6" B.Spruce S33E 13.	oportionate methods. DNR monument. 9°
B. Description of corner evidence found and/or method applied in restoring or reestablishing co	orner:
(K1) Recovered the 1952 monument, a 1° ID iron pipe capped with a 4° dia. brass Michigan Dept. of Conservation tablet, in good condition and at record bearing and distance from the remains of the three 1989 NBT spruce trees, now all dead. The 1952 NBT spruce was recovered in good condition at record bearing and distance. Left the monument in place. (J1) Recovered the 1989 monument, a 1°ID iron pipe capped with a 4° dia. aluminum MDNR tablet, in good condition and at record bearing and distance from the 1989 witnesses, which, except for that NE, are all dead and down. Left the monument in place.	
C. Description of monument for corner and accessories established to perpetuate locating the position of the corner (KI) Found 1" ID iron pipe with 4" brass (J1) Found 1" ID iron pipe with 4" cap. Blazed and scribed: 8" B.Spruce N49E 24.2' "S36 MBT" 4" Balsam S70E 17.7' "1/4S NBT" 5" Balsam S63N 16.8' do 5" Balsam S63N 16.8' do 5" Balsam S63N 16.8' do 5" SZYSZKOSKI LAND 5" Spruce N69W 24.3' (1952 MBT) 9" B.Spruce N32E 19.7' (1989 MBT) Bearings are magnetic. Distances are to notch in lower blaze. 10" Spruce N69W 24.3' (1952 MBT) Bearings are magnetic. Distances are to notch in lower blaze.	
Signed by Stephen J. Syspholi Date_	5/2/01
Surveyor's Michigan License No. 33986	

For the Michigan Department of Matural Resources - Forest Management Division