LAND CORNER RECORDATION CERTIFICATE Filing Requirement of Act 74, Mich. P.A. 1970

For corners in						
_	Dickinson	Located In:	Corner Code ≠#			
	(County)					
1.	Public Land Survey	T R				
		T R				
		T A				
		T R				
2.	Property Controlling	S <u>22.</u> T <u>421</u> R <u>291</u> .				
	in Section	S T R				
3.	Miscellaneous	S T R				

Register of Deeds Stamp & File Number

4. Lot No. . , Recorded Plat

Property in Sec.

5. Private Claims

Nag 05, 1991 I, Stephen J. Seyerkozki , in a field survey on _ do hereby certify that under requirements of P.A. 74, Michigan P.A. of 1970, the corner points mentioned in lines 1 and 2 above were in conformance with regulations and rules therefore as required in the current manual of survey instructions of the United States Department of the Interior, Bureau of Land Management or by a decree of a Court of Law and/or that the corner points mentioned in lines 3, 4 and 5 above were in conformance with the rules of the Michigan Board of Land Surveyors or by a Decree of a Court of Law; established, re-established, monumented, re-manumented, recovered, found as expressed below:

NOTE: Not more than 4 corners, all in the same town and range, may be recorded on this certificate.

_		<u>. </u>	0	•	<u>, </u>	<u> </u>		, ,			N
C	Γ	L.	[_		<u> </u>	L	_			Ĺ	_
Γ	i –	Γ	Ĭ				i _				
Г	Ţ	Г		Г			Ĺ				
Γ	7 I	Τ.	• —		 	<u>ا</u>	۵ ا		'	ו –	<u>2</u> —
Г					Г						
┢	1 8 —	<u> </u>	7 		•	- '	•	<u>'</u>	•	-1	3
一	\vdash	Н			Н	Н	7	\neg		\vdash	
┝		-2	•	-2		-2	•	—2	3	-1	4-
┝	┢	\vdash	\vdash	-		Н	Н	\vdash	\dashv	-	
┝᠄	b	-2	•	— ≥	•	<u>_2</u>	יל	-2	6	<u> </u> -2	5
⊢	\vdash	Н	\vdash	\vdash		Н	Ш				_
Į,	<u>, </u>		2	s	3	J	₊⊢	3	5		6
ı	L	. 1	1	1	ìì	1 1	1 1	1	.	1	

A. Description of original monument and accessories and/or subsequent restoration:

[7-Sec. 22] North 1/16 corner between sections 22 and 23. Corner previously recorded in 1977 by Arthur O. Hager, RLS as follows: 1* 1.D. iron pipe with 3 3/4" aluminum cap. Witnesses: B. Ash 7 5628 6.0" "1/165 37"; Cedar 6 5648 34.1" "1/165 37"; Top center of 5. end of culvert #627 1.90'.

B. Description of corner evidence found and/or method applied in restoring or reestablishing corner:

[7-Sec. 22] Found monument as described above at record bearing and distance from the Cedar ST and the culvert. The S. Ash ST has been disturbed by earthwork. Marked two new bearing trees as described below.

C. Description of monument for corner and accessories established to perpetuate locating the position of the corner:

OF MICH STEPHAN J. SZYSZKOSKI LAND SURVEYOR

[7] Found 1" iron pipe with MODA cap. Blazed and scribed the following new bearing trees: 11" 8. Ash 5488 10.4" "1/165 BT" *1/165 BT* 8" B. Ash S12W 26.0"

33986

Surveyor's Michigan License No.

9-16-93