## **MICHIGAN** DEPARTMENT OF CONSERVATION

FORESTRY DIVISION

## LAND CORNER RECORD

T 43 NR \_ 27 W \_

			-	Dick	inson		(	COUNTY
DESCRIPTION	OF	CORNER	1/4 corner	between	sections	g and 9	· 	· • • •
DESCRIPTION	OF	CORNER	MONUMENT_1"	iron pi	pe with 4	n brass	cap	
WIT TNESSES	то	CORNER	Tamarack 4"	N 39 E	13 links	marked	_1/4 s	NBT
			Tamarack 5"	S 11 E	8 links	marked	1/4_s	NBT
							- <b></b> -	
								. – – -

Dostances measured from center of brass cap to NBT notch.

DESCRIPTION IN DETAIL AS TO HOW CORNER WAS LOCATED AND IDENTIFIED OR RESTORED.

This corner was replaced from one original tamarack bearing tree ( 16" S 81 E 25 links ). down, in poor condition, Found description blaze and BT blaze overgrowth with notches plain. Found remains of original cedar bearing tree ( 14 M 37 W 33 links ) in place with no identifying marks. Two old wood posts in place. Have good corner 1/2 mile north.

Corner found while cruising timber in this area.

Corner placed and witnessed on 23 September 1957 with Cla rence R. Ryberg.

SURVEYORS SEAL