LAND CORNER RECORDATION CERTIFICATE Filing Requirement of Act 74, Mich. P.A. 1970 as Amended

For corners in

Dickinson	Located In:	Corner Code #								
(County) WEST BRANCH TOWNSHIP	_									
Public Land Survey	T B									
	TR									
	TRR									
2. Property Controlling	S 25 T 43N R 28W	11	1							
in Section	S 25 T 43N R 28W	13								
3. Miscellaneous	STR S T R									
Property in Sec.	s T R		ļ							
			Re	gister o	f Deed	ls Stan	np & Fi	ile Nun	ber	
	corded Plat		A B	СЪ	E	F G	н	IJ	K 1	. м
5. Private Claims			1			TT	T		Ϊ΄	
	6/18/2013	BAD	2 6	— - <u> </u>	·	1-	-3-	— <u>2</u> —	 -	iH
, Jeremy J. Pipp , ii	n a field survey on 6/17/2013	BAD do hereby state	3			† †	+-		+-	
that under requirements of P.A. 74, Michigan P.A. of 1970, the corner points mentioned in lines 1 and 2				一门	'	• • • • • • • • • • • • • • • • • • • •	-10 	11 	 - 1	2
above were in conformance with regulations and rules therefore as required in the current manual of survey					_				+	
Instructions of the United States Department of the Interior, Bureau of Land Management or by a decree of				1	7	16	-15	14-	1-1	3—
a Court of Law and /or that the corner points mentioned in lines 3, 4 and 5 above were in conformance with the rules of the Michigan Board of Land Surveyors or by a Decree of a Court of Law; established,									1	Н
'e-established, monumented, recovered, found as expressed below:				2	$^{\sim}$	21	_22	23	+-2	4
,			9				\neg		+	
NOTE: Not more than 2 corners, all in the same town and range, may be recorded				} 2 	- -	28-	<u>-27</u>	26-	-2°	5
on this certificate			11							
			12-31	i		33	-34 	35 	┼ ³	36—
A Description of original or			13			<u> </u>		<u> </u>	-	

- A. Description of original monument and accessories and/or subsequent restoration;
- (11) Southwest One-Sixteenth corner of Section 25. Not set in original survey, no evidence of subsequent establishment.
- (13) Southeast One-Sixteenth corner of Section 25. Not set in original survey, no evidence of subsequent establishment.
- B. Description of corner evidence found and/or method applied in restoring or reestablishing corner:
- (11) Corner position established at the intersection of the South and West One-Sixteenth lines of Section 25. Monument falls +/-1 feet South of East-West fence line
- (13) Corner position established at the intersection of the South and East One-Sixteenth lines of Section 25.
- C. Description of monument for corner and accessories established to perpetuate locating the position of the corner:

DNR monument (11)N27E 14.98' (1/16S,BT) N82E 11.46' (- , -) 9" J. Pine Fence Post N56W 27.81' (1/16S,BT) 12" J. Pine 8" J. Pine N16W 14.60'(1/16S,NBT) All trees are blazed, scribed, painted, and signed. Measurements are to nail in side of tree, bearings-are magnetic,

DNR monument (13) N78E 30.57' (1/16S,BT) 4" Ironwood

\$43W 43.85' (1/16S,BT) N-5" Maple E-S Fence cor. N18W 19.28' (- , -)

All trees are blazed, scribed, painted, and signed. Measurements are to nail in side of trees, bearings are magnetic.

Date

JEREMY J.

August 08, 2013

Surveyor's Michigan License No.

50447

For the Michigan Department of Natural Res

PROFESSIONAL PROFESSIONAL OF SURVEYOR DIVISION PROFESSIONAL OF SURVEYOR PROFESSIONAL OF SURVEYOR PROFESSIONAL PROFESSIONAL

20229

Signed by