LAND CORNER RECORDATION CERTIFICATE Filing Requirement of Act 74, Mich. P.A. 1970 as Amended

For corners in

Dickinson (County)	_ Located In:	Corner Code #									
WEST BRANCH TOWNSHIP											
 Public Land Survey 	TR										
	TR TR										
2. Property Controlling	S 23 T 43N R 28W	14									
in Section	S 23 T 43N R 28W	16									
	S T R										
3. Miscellaneous	S T R										
Property in Sec.	S T R										
				Regis	ter of D	eeds s	Stamp	& File	a Num	ber	
4. Lot No. , Recorded Plat								_			
5. Private Claims			1	" `		ŤŤ	G H	1	<u> </u>	K L	_M
	6/11/201	3AD	2	- ხ— 	— ş—	┾┪	+-	ì÷	-2-	╁	_
, Jeremy J. Pipp , ir	n a field survey on 6/11/201	3AD do hereby state	3	\top		+			\top	†	_
that under requirements of P.A. 74, Michigan P.A. of 1970, the corner points mentioned in lines 1 and 2							2				
above were in conformance with regulations and rules therefore as required in the current manual of survey 5								_			
instructions of the United States D	f 6 -	18—	17	16	1	5	-14-	13			
a Court of Law and /or that the corner points mentioned in lines 3, 4 and 5 above were in conformance with 7							_				
the rules of the Michigan Board of Land Surveyors or by a Decree of a Court of Law; established					20	22	2	2	_23		_
e-established, monumented, recov	_ او							ФП			
			10	30	20_						
NOTE: Not more than 2 corners, all in the same town and range, may be recorded					ĺ	Τ'n	7-1	/	-26-	725	
on this certificate.									\neg	\vdash	
			12	31 	32 I	33	3	4	-35	 -3 6	-
			12	_1.	1 I		- } 1				

- A. Description of original monument and accessories and/or subsequent restoration:
- (14) South One-Sixteenth corner common to Sections 23 and 24. Not set in original survey, no evidence of subsequent establishment.
- (16) East One-Sixteenth corner common to Sections 23 and 26. Not set in original survey, no evidence of subsequent establishment.
- B. Description of corner evidence found and/or method applied in restoring or reestablishing corner:
- (14) Corner position established mid-point and on-line between the East One-Quarter corner and the Southeast corner of Section 23.
- (16) Corner position established mid-point and on-line between the South One-Quarter corner and the Southeast corner of Section 23.
- C. Description of monument for corner and accessories established to perpetuate locating the position of the corner:

painted. I side of tre	DNR monument N12E 17.30' (1/16S,BT) S40E 37.86' (1/16S,BT) S28W 12.63' (1/16S,BT) N59W 8.23' (1/16S,BT) are blazed, scribed, and Measurements are to nail in ee, bearings are magnetic.	(16) DNR monument 3" Ironwood N36E 19.83' (1/16S,BT) 4" Spruce S43E 26.01' (1/16S,BT) 6" Poplar S57W 14.35' (1/16S,BT) 6" Maple N32W 40.32' (1/16S,BT) Angle Iron N24E 22.6' All trees are blazed and painted. Measurements are magnetic.
Signed by	levener loss	JEREMY Date August 08, 2013

/50447

Surveyor's Michigan License No. For the Michigan Department of Natural Resource

E Division

20222

20223

ATE BOARD OF PROFESSIONAL SURVEYORS, JAN. 28, 1971 Revised May 14, 1975 Revised Jan., 1983 Rervised Oct., 1995