LAND CORNER RECORDATION CERTIFICATE

	Filin	g Requirement of Act 74	I, Mich. P.A. 197	70	
For corners in			l		
Dickinson	Located in:	Corner Code #			
1. Public Land Survey	T_43N R T_43N R TR	28W K9			
Property Controlling in Section Miscellaneous Property in Sec.	TR S TR S TR S TR S TR			Register of Deeds Stamp & File Number	
4. Lot No, Recor	ded Plat				
5. Private Claims	K9 19	Jun 26 2001 Jun 13 2001		A B C D E F G H 1 J K L 2 6 5 4 3 2 1 1 3	7
, Stephan J. Szyszkoski	= -		eby state that under	4 7 8 9 10 11 12]
requirements of P.A. 74, Michiga conformance with regulations and United States Department of the I that the corner points mentioned Board of Land Surveyors or by recovered, found as expressed be	in P.A. of 1970, the corn rules therefore as requir interior, Bureau of Land & In lines 3, 4 and 5 above a Decree of a Court of	er points mentioned in lines 1 are ad in the current manual of surver fanagement or by a decree of a 0 were in conformance with the ru	nd 2 above were in y instructions of the Court of Law and /or les of the Michigan	5 6 -18 -17 -16 -15 -14 -13 7 8 -19 -20 -21 -22 -23 -24	
NOTE: Not more than 2 corn on this certificate.	ers, all in the same tow	n and range, may be recorded	i	9 10 30 29 28 27 26 25 11	1
				12 31 32 33 34 35 36	1
een burned over and wash out oved from their original pla /16 cor., thence 1328.8° nor	t as this corner is a aces". 1922 Map of a rth to 1/4 22-23. ns 23-24-25-26. Per	near the Ford river, and the Proposed school site, for the proposed in the original properties.	he overflow of sai Ralph MI (File B-1 osition and record	Me found no bearing trees. Everything has id river has caused many of the trees to be 16 Mo. 4 at DCRC) shows 1328.8' north to ded by Dean C. DelaMater in 1952. 1" Pipe	
B. Description of corner evid	dence found and/or m	ethod applied in restoring or	reestablishing corn	ner:	
djacent. Existing old fence onumented I8. Distance nor occepted the monument as the osition, I note the distance K9) Recovered the 1952 monu	e intersection at 1/ th to 18 from this m best available evid es to monumented 1/4 ment as described, i	16 corner to north checks on. was found to be 2657.4 ence of the position of the corners: 2652.90' West, 2 on good condition, and at r	well for line and 7', only 0.13' sho e original corner. 633.70' East, 2651 ecord bearing and	ith old sq'd and scribed cedar post distance between this monument and orter than the 1922 plan noted above. I . As few witnesses are available at this 1.18' South, and 2657.47' North. distance from the rotting stump remains of ound at record bearing and distance.	
C. Description of monument 19) Found 1.25" dia. axle silazed and scribed a 15" Ced. 02.1' (scribed S26 HBT). 19'd cedar post north, 1.1'. learby witnesses available. lagnetic. Dist. to notch in f Cedar MBT.	ar S69E M Placed a a No other 5 Bearings 4 lower blaze 5 4 P	cories established to perpetus (9) Found 1"ID iron pipe w I Dept. of Conservation ca nd scribed: " N.Pine N26W 47.2' " W.Spruce S68E 32.4' " W.Pine S12W 42.8' " W.Spruce S79W 41.3' ' tall metal fnc post 0.8' laced sq'd cedar post 2' n earings are magnetic. Dis otch in lower blaze of tre	p. Blazed "S23 MBT" "S25 MBT" "S26 MBT" "S26 MBT" northerly. orth. tances to	STEPHAN J. SZYSZKOSKI LAND SURVEYOR No. 33986	
Signed by	and Send	Shast.	_ Date	7/18/01	_
Surveyor's Michigan License	No	33986	- 		