LAND CORNER RECORDATION CERTIFICATE Filing Requirement of Act 74, Mich. P.A. 1970

1. Public Land Survey T. 44N R. 27N J3 T. R. J. S.	
2. Property Controlling S T R T R Socion S T R R Repister of Deeds Stamp & File! 4. Lot No. Recorded Plat Socion S T R R Repister of Deeds Stamp & File! 4. Lot No. Recorded Plat S T R R Repister of Deeds Stamp & File! 4. Lot No. Recorded Plat S T R R Repister of Deeds Stamp & File! 5. Private Claims Oct 10 2001 L Paul R. Bressette in a field survey on 20 do hereby state that under requirements of PA 74 Michigan PA of 1970, the corner points mentioned in lines 1 and 2 and	
2. Property Controlling S T R S IN Section S In Section S S IN Section S S IN Section S In Section S S IN Section S In Section S S IN Section	
A. Lot No	
4. Lot No	
5. Private Claims Oct 10 2001 I. Paul R. Bressette In a field survey on 20 do hereby state that under requirements of P.A. 74, Michigan P.A. of 1970, the corner points meritioned in lines 1 and 2 above were in Conformance with regulations and rules therefore as required in the current manual of survey instructions of the United States Department of the Interior, Bureau of Land Management of by a decree of a Court of Law and/or that the corner points meritioned in lines 3, 4 and 5 above were in conformance with the rules of the Michigan Board of Land Surveyors or by a Decree of a Court of Law; established, re-established, monumented, recovered, found as expressed below. NOTE: Not more than 2 corners, all in the same town and range, may be recorded on this certificate. A. Description of original monument and accessories and/or subsequent restoration. (33) Quarter corner conson to Sections 2 and 11. 1850: John Burt, DS. Set wood post witnessed by: Tanarack 5 S43£ 16 lks.; Tanarack 4 M51W 14 lks. Found old wood post. B. Description of corner evidence found and/or method applied in restoring or reestablishing corner: (33) No evidence of original survey found. Found old squared wood post, down in poor condition. Measured east to a definite essapp, call fits fairly well (6L0 2.02 ch133*, neasured 14*). The terrain calls in this township were taken on the random lit at true distance from corner to call is not known. The distance west to corner set from original bearing trees measures 244.72 feet40.07 chs.; 6L0 40.48 chs2611.7*. Distance east to a found iron pipe neasures 2775.80-42.06 chs.; 6L0 40.48 chs2644.72 feet40.07 chs.; 6L0 40.48 chs2611.7*. Distance east to a found iron pipe neasures 2775.80-42.06 chs.; 6L0 40.48 chs2611.7*. Distance east to a found iron pipe neasures 2775.80-42.06 chs.; 6L0 40.48 chs2611.7*. Distance east to a found iron pipe neasures 2775.80-42.06 chs.; 6L0 40.48 chs2611.7*. Distance east to a found iron pipe neasures 2775.80-42.06 chs.; 6L0 40.48 chs2611.7*. Distan	lumber
Paul R. Bressette in a field survey on 20 do hereby state that under requirements of P.A. 74 Michigan P.A. of 1970, the corner points mentioned in lines 1 and 2 above were in conformance with regulations and rules therefore as required in the current manual of survey instructions of the United States Department of the Interior, Bureau of Land Management or by a decree of a Court of Law and for that the corner points mentioned in lines 3.4 and 5 above were in conformance with the rules of the Michigan P.A. of 1970, the corner of the United States Department of the Interior, Bureau of Land Management or by a decree of a Court of Law and for that the corner points mentioned in lines 3.4 and 3 above were in conformance with the rules of the Michigan P.A. of the corner of the United States Department of the Interior, Bureau of Land Surveyors or by a Decree of a Court of Law, established, re-established, monumented, recovered, found as expressed below. NOTE: Not more than 2 corners, all in the same town and range, may be recorded on this certificate. A. Description of original monument and accessories and/or subsequent restoration: (33) Quarter corner comeon to Sections 2 and 11. 1850: John Burt, DS. Set wood post witnessed by: Tamarack 5 S43£ 16 lks.; Tamarack 4 HSIW 14 lks. Found old wood post. B. Description of corner evidence found and/or method applied in restoring or reestablishing corner: (33) No evidence of original survey found. Found old squared wood post, down in poor condition. Measured east to a definite eswape, call fits fairly well (6LO 2.02 ch135', neasured 14'). The terrain calls in this township were taken on the random tia true distance from corner to call is not known. The distance west to corner set from original bearing trees measures 2244.72 feet—40.07 chs.; 610 40.48 chs2671.7'. Distance east to a found iron pipe neasures 275.80° -42.06 chs.; 610.40.48 chs2671.7'. Distance east to a found iron pipe neasures 275.80° -42.06 chs.; 610.40.8 chs2671.7'. Distance east to a found iron pi	K L
Paul R. Bressette in a field survey on	
requirements of PA 74. Michigan PA of 1970, the corner points mentioned in lines 1 and 2 above were in conformance with regulations and rules therefore as required in the current manual of survey instructions of the United States Department of the Interior, Bureau of Land Management of by a decree of a Court of Law and for that the corner points mentioned in lines 3, 4 and 5 above were in conformance with the rules of the Michigan Board of Land Surveyors or by a Decree of a Court of Law, established, re-established, monumented, recovered, found as expressed below. NOTE: Not more than 2 corners, all in the same town and range, may be recorded on this certificate. A Description of original monument and accessories and/or subsequent restoration: (13) Quarter corner common to Sections 2 and 11. 1850: John Burt, DS. Set wood post witnessed by: Tamarack 5 S43E 16 lks.; Tamarack 4 N5IW 14 lks. Found old wood post, B. Description of corner evidence found and/or method applied in restoring or reestablishing corner: (13) No evidence of original survey found. Found old squared wood post, down in poor condition. Measured east to a definite ensurance of the corner of th	
B Description of corner evidence found and/or method applied in restoring or reestablishing corner. B Description of corner evidence found and/or method applied in restoring or reestablishing corner. B Description of corner evidence found and/or method applied in restoring or reestablishing corner. B Description of corner evidence found and/or method applied in restoring or reestablishing corner. B Description of corner evidence found and/or method applied in restoring or reestablishing corner. B Description of corner evidence found and/or method applied in restoring or reestablishing corner. B Description of corner evidence found and/or method applied in restoring or reestablishing corner. B Description of corner evidence found and/or method applied in restoring or reestablishing corner. B Description of corner evidence found and/or method applied in restoring or reestablishing corner. B Description of corner evidence found and/or method applied in restoring or reestablishing corner. B Description of corner evidence found and/or method applied in restoring or reestablishing corner. B Description of corner evidence found and/or method applied in restoring or reestablishing corner. B Description of corner evidence found and/or method applied in restoring or reestablishing corner. B Description of corner evidence found and/or method applied in restoring or reestablishing corner. B Description of corner evidence found and/or method applied in restoring or reestablishing corner.	12-
NOTE: Not more than 2 corners, all in the same town and range, may be recorded on this certificate. A. Description of original monument and accessories and/or subsequent restoration: (J3) Quarter corner common to Sections 2 and 11. 1850: John Burt, DS. Set wood post witnessed by: Tamarack 5 S43E 16 lks.; Tamarack 4 NSIW 14 lks. Found old wood post. B. Description of corner evidence found and/or method applied in restoring or reestablishing corner: (J3) No evidence of original survey found. Found old squared wood post, down in poor condition. Measured east to a definite eswap, call fits fairly well (GLO 2.02 ch133', measured 147'). The terrain calls in this township were taken on the random lia a true distance from corner to call is not known. The distance west to corner set from original bearing trees measures 2644.72 feet40.07 chs.; GLO 40.48 chs2671.7'. Distance east to a found iron pipe measures 2775.80'42.06 chs.; GLO 40.48 chs2671 is places the possibility of a 2 chain error in the east half mile. Single proportion would place the corner 81 feet west of swaap edge, a difference of 52 feet from the record. This position was rejected. Based on the evidence found, the wood post was replaced with a DNR monument, witnessed, and is accepted as the best available evidence of the position of the original corner. C. Description of monument for corner and accessories established to perpetuate locating the position of the corner:	
A Description of original monument and accessories and/or subsequent restoration: (13) Quarter corner common to Sections 2 and 11. 1850: John Burt, DS. Set wood post witnessed by: Tamarack 5 S43E 16 lks.; Tamarack 4 M51W 14 lks. Found old wood post. B Description of corner evidence found and/or method applied in restoring or reestablishing corner: (13) No evidence of original survey found. Found old squared wood post, down in poor condition. Measured east to a definite evidence of original survey found. Found old squared wood post, down in poor condition. Measured east to a definite evidence from corner to call is not known. The distance west to corner set from original bearing trees measures 2644.72 feet-40.07 chs.; GLO 40.48 chs2671.71. Distance east to a found iron pipe measures 2775.80'42.06 chs.; GLO 40.48 chs2671.15 bistance east to a found iron pipe measures 2775.80'42.06 chs.; GLO 40.48 chs2671.15 bistance east to a found iron pipe measures 2775.80'42.06 chs.; GLO 40.48 chs2671.15 bistance east to a found iron pipe measures 2775.80'42.06 chs.; GLO 40.48 chs2671.15 bistance east to a found iron pipe measures 2775.80'42.06 chs.; GLO 40.48 chs2671.15 bistance east to a found iron pipe measures 2775.80'42.06 chs.; GLO 40.48 chs2671.15 bistance east to a found iron pipe measures 2775.80'42.06 chs.; GLO 40.48 chs2671.15 bistance east to a found iron pipe measures 2775.80'42.06 chs.; GLO 40.48 chs2671.75 bistance east to a found iron pipe measures 2775.80'42.06 chs.; GLO 40.48 chs2671.75 bistance east to a found iron pipe measures 2775.80'42.06 chs.; GLO 40.48 chs2671.75 bistance east to a found iron pipe measures 2775.80'42.06 chs.; GLO 40.48 chs2671.75 bistance east to a found iron pipe measures 2775.80'42.06 chs.; GLO 40.48 chs2671.75 bistance east to a found iron pipe measures 2775.80'42.06 chs.; GLO 40.48 chs2671.75 bistance east to a found iron pipe measures 2775.80'42.06 chs.; GLO 40.48 chs2671.75 bistance east to a found iron pip	24-
A. Description of original monument and accessories and/or subsequent restoration: (33) Quarter corner common to Sections 2 and 11. 1850: John Burt, DS. Set wood post witnessed by: Tamarack 5 S43E 16 lks.; Tamarack 4 M51W 14 lks. Found old wood post. B. Description of corner evidence found and/or method applied in restoring or reestablishing corner: (33) No evidence of original survey found. Found old squared wood post, down in poor condition. Measured east to a definite erswap, call fits fairly well (GLO 2.02 ch133', measured 147'). The terrain calls in this township were taken on the random life a true distance from corner to call is not known. The distance west to corner set from original bearing trees measures 2644.72 feet40.07 chs.; GLO 40.48 chs2671.7'. Distance east to a found iron pipe measures 2775.80'42.06 chs.; GLO 40.48 chs26 This places the possibility of a 2 chain error in the east half mile. Single proportion would place the corner 81 feet west of swamp edge, a difference of 52 feet from the record. This position was rejected. Based on the evidence found, the wood post wareplaced with a DNR monument, witnessed, and is accepted as the best available evidence of the position of the original corner. C. Description of monument for corner and accessories established to perpetuate locating the position of the corner:	25
A. Description of original monument and accessories and/or subsequent restoration: (J3) Quarter corner common to Sections 2 and 11. 1850: John Burt, DS. Set wood post witnessed by: Tamarack 5 S43E 16 lks.; Tamarack 4 N51W 14 lks. Found old wood post. B. Description of corner evidence found and/or method applied in restoring or reestablishing corner: (J3) No evidence of original survey found. Found old squared wood post, down in poor condition. Measured east to a definite erswamp, call fits fairly well (GLO 2.02 ch133', measured 147'). The terrain calls in this township were taken on the random liming a true distance from corner to call is not known. The distance west to corner set from original bearing trees measures 2644.72 feet40.07 chs.; GLO 40.48 chs2671.7'. Distance east to a found iron pipe measures 2775.80'42.06 chs.; GLO 40.48 chs267 his places the possibility of a 2 chain error in the east half mile. Single proportion would place the corner 81 feet west of swamp edge, a difference of 52 feet from the record. This position was rejected. Based on the evidence found, the wood post was replaced with a DNR monument, witnessed, and is accepted as the best available evidence of the position of the original corner. C. Description of monument for corner and accessories established to perpetuate locating the position of the corner:	
A. Description of original monument and accessories and/or subsequent restoration: (J3) Quarter corner common to Sections 2 and 11. 1850: John Burt, DS. Set wood post witnessed by: Tamarack 5 S43E 16 lks.; Tamarack 4 N5IW 14 lks. Found old wood post. B. Description of corner evidence found and/or method applied in restoring or reestablishing corner: (J3) No evidence of original survey found. Found old squared wood post, down in poor condition. Measured east to a definite erswamp, call fits fairly well (GLO 2.02 ch133', measured 147'). The terrain calls in this township were taken on the random liminating at rue distance from corner to call is not known. The distance west to corner set from original bearing trees measures 2644.72 feet-40.07 chs.; GLO 40.48 chs2671.7'. Distance east to a found iron pipe measures 2775.80'42.06 chs.; GLO 40.48 chs26 his places the possibility of a 2 chain error in the east half mile. Single proportion would place the corner 81 feet west of swamp edge, a difference of 52 feet from the record. This position was rejected. Based on the evidence found, the wood post was replaced with a DNR monument, witnessed, and is accepted as the best available evidence of the position of the original corner. C. Description of monument for corner and accessories established to perpetuate locating the position of the corner:	36
(J3) No evidence of original survey found. Found old squared wood post, down in poor condition. Measured east to a definite erswamp, call fits fairly well (GLO 2.02 ch133', measured 147'). The terrain calls in this township were taken on the random ling a true distance from corner to call is not known. The distance west to corner set from original bearing trees measures 2644.72 feet40.07 chs.; GLO 40.48 chs2671.7'. Distance east to a found iron pipe measures 2775.80'42.06 chs.; GLO 40.48 chs26 This places the possibility of a 2 chain error in the east half mile. Single proportion would place the corner 81 feet west of swamp edge, a difference of 52 feet from the record. This position was rejected. Based on the evidence found, the wood post was replaced with a DNR monument, witnessed, and is accepted as the best available evidence of the position of the original corner. CD Description of monument for corner and accessories established to perpetuate locating the position of the corner:	
(J3) No evidence of original survey found. Found old squared wood post, down in poor condition. Measured east to a definite erswamp, call fits fairly well (GLO 2.02 ch133', measured 147'). The terrain calls in this township were taken on the random ling a true distance from corner to call is not known. The distance west to corner set from original bearing trees measures 2644.72 feet40.07 chs.; GLO 40.48 chs2671.7'. Distance east to a found iron pipe measures 2775.80'42.06 chs.; GLO 40.48 chs26 This places the possibility of a 2 chain error in the east half mile. Single proportion would place the corner 81 feet west of swamp edge, a difference of 52 feet from the record. This position was rejected. Based on the evidence found, the wood post was replaced with a DNR monument, witnessed, and is accepted as the best available evidence of the position of the original corner. C. Description of monument for corner and accessories established to perpetuate locating the position of the corner:	
	1.7'.
7" B.Spruce S64E 14.3' (1/4S,NBT) 7" B.Spruce S02W 16.5' (1/4S,NBT) 5" B.Spruce N24W 5.7' (1/4S,NBT) LAND	CONTRACTOR A
All trees are blazed, scribed and painted. Measurements are to nail in side of tree, bearings are magnetic. SURVEYOR No. 37270	VI.O.
Signed by Taul R. Throuth Date	
Surveyor's Michigan License No	