LAND CORNER RECORDATION CERTIFICATE

For corners in		Requirement of Ac	t 74, Mich. P.A. 19				
Dickinson	Located In:	Corner Code #					
(County)	Located in.	Corner Code #					
1. Public Land Survey	T_44N R_ T_44N R_ T_R	27W K2 L3	<u> </u>				
2. Property Controlling in Section 3. Niscellaneous Property in Sec.	TR_ S TR_ S TR_ S TR_ S TR_		-	Registe	er of Deeds S	Stamp & Fil	e Number
4. Lot No, Record	led Plat						
5. Private Claims				A B C	D E F	G H I	J K L
**		0=+ 15 2001		2 6	54-	4-3	- 2 1 -
Paul R. Bressette	in a fold augustan	Oct 15 2001		3			+ +
requirements of P.A. 74, Michigan	P.A. of 1970, the corner	, 20 do points mentioned in lines	1 and 2 shove were in	4 - 7 -	8- 9- 	10	11-12-
conformance with regulations and r United States Department of the In	ules therefore as required terior. Bureau of Land Ma	in the current manual of sun	urvey instructions of the	5			
that the corner points mentioned in Board of Land Surveyors or by	n lines 3. 4 and 5 above w	ere in conformance with th	e rules of the Michigan	6 -18	-17-16-	15	14
recovered, found as expressed belo	DW:	Law, established, re-esta	iolisnea, monumentea,	819	2021	-22	23 24
NOTE: Not more than 2 come	ers, all in the same town	and range, may be reco	rded	9			1-1-1
on this certificate.	•		,	10 30	2928	27	2 6 2 5-
				11			
				12 -31	3233	34-	3536_
A. Description of original mon (K2) Quarter corner common to	ument and accessorie Sections 1 and 2,	s and/or subsequent re 1850: John Burt, DS.	storation; Set wood post witne	ssed by Spri	uce 12 S59W	77]ke •	Spruce 8
N17E 45 lks. (L3) Quarter corner common to Tamarack 8 S17E 22 lks.							
B. Description of corner evide	ence found and/or met	had applied in restoring					
(K2) No evidence of original feet, measured 92 feet). Line Corner position reestablished careful and faithful REESTABLI (L3) No evidence of original southeast and southwest corner corner.	survey or subsequent calls in this townsh by single proportion SHMENT of the position survey or subsequent	restoration found. Lip were taken on the between the northwesten of the original correstoration found. C	ine call south to s random lines so tru and southwest corn ner.	tream fits fa e distance fr ers of Section	rom corner to on 1, and is	call is naccepted a	ot known. s a
(C) Description of monument fo	or corner and accessor	es established to perpe	atuate locating the po	sition of the o	ornar:	TE OF MIC	
07" Balsam S15W 27.3' (1/45 10" Spruce S55W 23.6' (1/45	S,NBT) 7" B S,NBT) 7" B S,NBT) 5" B S,NBT) 9" B and All nail in pain	DNR monument Spruce N34E 35.0' Spruce S73E 39.15' Spruce S31W 17.05' Spruce N59W 27.35' trees are blazed, scrited. Measurements are of tree, bearings are	(1/4S,NBT) (1/4S,NBT) (1/4S,NBT) (1/4S,NBT) ibed and e to nail in	SHOULD ING CO	omer:	PAUL R. BRESSETTI LAND SURVEYOR No. 37270	E X
					40	TAND	N TO
Signed by	R. Ihm	u far	Data				
Surveyor's Michigan License No		270	Date				
		artment of Natural Re	 sources - Forest Mai	nagement Divi	sion		