LAND CORNER RECORDATION CERTIFICATE Filing Requirement of Act 74, Mich. P.A. 1970

For corners in	rining Requirement of Act 74, Mich. P.A. 19	70
Located In:	Corner Code #	
(County)		
	44h R 28h I12 44h R 28h I11 R R	
2. Property Controlling S T in Section S T 3. Miscellaneous S T	R	
Property in Sec. ST_	R	Register of Deeds Stamp & File Number
4. Lot No, Recorded Plat		
5. Private Claims		A B C D E F G H I J K L I
		2 - 6 - 5 - 4 - 3 - 2 - 1 -
! Stanhan I Szuszkoski in a fold aum	Nov 01 1999	3
requirements of P.A. /4, Michigan P.A. of 1970, the	yey on, 19 do hereby state that under the corner points mentioned in lines 1 and 2 above were in	4 - 7 - 8 - 9 - 10 - 11 - 12 - 12 - 12 - 12 - 12 - 12
conformance with regulations and rules therefore as required in the current manual of survey instructions of the United States Department of the Interior, Bureau of Land Management or by a decree of a Court of Law and /or		5 17 16 15 14 13
that the corner points mentioned in lines 3, 4 and 5	5 above were in conformance with the rules of the Michigan Court of Law; established, re-established, monumented,	7
recovered, found as expressed below:	Court of Law, established, re-established, monumented,	0 19 20 21 22 23 24
NOTE: Not more than 2 corners, all in the sar	me town and range, may be recorded	9
on this certificate.		10 30 29 28 27 26 25
		11
		12 31 32 34 35 36
(II2) Quarter corner common to Sections 34-35. Established in 1850 by John Burt: "39.98 Set cedar Quarter Section Post. Sugar 10 S38W 13, Y.Birch 14 M2BE 16." (II1) Corner common to Sections 26-27-34-35. Established in 1850 by John Burt: "79.96 Section Corner 26,27,34 & 35. Sugar 26 N30E 40, Y.Birch 16 S67W 35."		
B. Description of corner evidence found and	d/or method applied in restoring or reestablishing corr	ner:
(II2) The original post and accessories were not recovered. Found no acceptable evidence of the position of the original corner on the ground. Reestablished the corner midway and on a line of mean true bearing between Section corners 2631.26' north and south. At the position for the corner I placed a 1"I.D.x32" iron pipe capped with a 4" dia. cast aluminum MDNR tablet, appropriately stamped. (II1) The original post and accessories were not recovered. Found no acceptable evidence of the position of the original corner on the ground. Reestablished the corner by double proportionate measurement to the original record between section corners 1 mile to north, south, east, and west. At the position for the corner I placed a 1"I.D.x32" iron pipe capped with a 4" dia. cast aluminum MDNR tablet, appropriately stamped.		
(II2) Set 1" pipe with 4" MDNR cap. Blazed and scribed the following: 12" Sugar S29E 47.9' "1/4S NBT" 11" Sugar S35M 20.4' do 6" Sugar(SE'ly of 4) N67M 18.6' do 11" double Sugar N05M 24.3' do Squared cedar post adjacent. Bearings are magnetic. Distances to notch in lower blaze.	ccessories established to perpetuate locating the pos (I11) Set 1" pipe with 4" MDNR cap. Blazed and scribed the following: 6" Aspen N15E 64.7' "\$26 NBT" 10" Maple S11M 22.4' "\$34 NBT" 10" Sugar N77M 32.4' "\$27 NBT" 5" Sugar in clump N24W 13.8' "\$27 NBT" Squared cedar post adjacent. Bearings are magnetic. Distances to notch in lower blaze.	STEPHAN J. SZYSZKOSKI LAND SURVEYOR No. 33986
Signed by Surveyor's Michigan License No.	<u> 33986</u> Date	3/7/00