LAND CORNER RECORDATION CERTIFICATE

	Filing	g Requirement of Act /4, N	MCN. P.A. 19/U	1					
For corners in Dickinson	Located in:	Corner Code #							
(County)	Located III.	001101 0000 1							
1. Public Land Survey	✓ T_44H R_ T_44H R_ T R_	29) K5							
2. Property Controlling in Section	S T_R								
Miscellaneous Property in Sec.	S TR_ S TR_			Regist	er of De	eds Sta	mp &	File N	nwpe
4. Lot No, Recor	ded Plat		<u> </u>	, <u>A_B</u> _	C D E	F G	н	I J	<u>к</u> г
		Jul 16 1996 Jul 23 1996	:	2 - 6	- 5 -		_}_	_ ½ _	<u> </u>
requirements of P.A. 74, Michiga conformance with regulations and	, in a field survey on _ n P.A. of 1970, the come rules therefore as required	19 do hereby a r points mentioned in lines 1 and 2 d in the current manual of survey ine	ecove were in tructions of the	s	-8-	_	-10 	+	├ ¦
United States Department of the I	nterior, Bureau of Land Mi In lines 3, 4 and 5 above v	inegement or by a decree of a Court were in conformance with the rules of I Law; established, re-established,	of Law and for (of the Michigan	7 - 19-		-16-	-15-	-14-	
recovered, found as expressed be				19— 	20	21	_2'2 i	23_ 	1
NOTE: Not more than 2 com on this certificate.	ers, all in the same towr	and range, mey be recorded		-	_29_	_2 8	_27_	—26—	-2
				2 31-	32	33		_35	 3
			1	ـــــاډ			نــــــــــــــــــــــــــــــــــــــ		┸

- A. Description of original monument and accessories and/or subsequent restoration:
 (J4) Center of Section II. Corner not established in the original survey. Found no subsequent record.
- (K5) Corner common to Sections 11-12-13-14. Corner established in 1848 by John Burt: "Set sugar post corner of Sections 11,12,13,14. Sugar 12 S75E 25, Lynn 24 M40M 36". Found no subsequent record.
- B. Description of corner evidence found and/or method applied in restoring or reestablishing corner:
- (J4) found no evidence of prior monumentation. Established the corner at the intersection of straight lines connecting opposite quarter corners 2647.75' north, 2648.10' south, 2659.84' east, and 2659.84' mest. At the position for the corner, I placed a 1' I.D.x32" iron pipe capped with a 4" dia. cast aluminum MDNR tablet, appropriately stamped.
- (X5) Original post and accessories not recovered. Found no acceptable evidence of the position of the original corner on the ground. Reestablished the corner by double proportionate measurement to the original record between monumented corners 200.468 ch. south, 80.188 ch. north, 79.588 ch. east, and 80.600 ch. west. At the position for the corner, I placed a 1 I.D.x32 iron pipe capped with a 4" dia. cast aluminum MONR tablet, appropriately stamped.

(J4) Set 1" pipe with 4" MONR cap.	cessories established to perpetuate locating the (XS) Set 1 pipe with 4 MOHR cap. Blazed and scribed the following new	position of the corner
Blazed and scribed the following bearing	bearing trees:	
trees: 2" Maple SOSN 70.6'	8" W. Spruce M72E I5.7' "S12 MBT" 9" Sugar S53E 28.8' "S13 MBT" 6" dbl. Sugar S54M 16.7' "S14 MBT" 7" Sugar M41M 24.7' "S11 MBT" Placed 3" squared sugar post adjacent. Bearings are magnetic. Placed location poster on 5" poplar at S. side of E-W trail M20M 160' distant.	STEPHAN J. SZYSZKOSKI LAND SURVEYOR No. 33986
Signed by Stahe . Sage	1. hoshi Dete	Sept. 3, 1996

For the Michigan Department of Natural Resources - Forest Management Division