1998 GENESEE COUNTY REMONUMENTATION PROGRAM LAND CORNER RECORDATION CERTIFICATE

Filing Requirement of Act 74, Mich. P.A. 1970 For comers in				4013 PAGE 118
Genesee County	Located in:	Corner Code #	''	TO THE LETT
Public Land Survey Property Controlling S_ in Section S_ Miscellaneous S_ Property in Sec. S_	T <u>5N</u> R6E T R T R T R	A-5 SLEVEY & REMONIUMENTATION MAR L 7 1999		ter of Deeds Stamp & FIG
4. Lot No, Recorded I	Plat		1 (1 1	····Di ve ··· E ··· E ··· G ··· H · I ·· · · · · · · · · · · · · ·
I, Kevin B. Cleaver, in a field serequirements of P.A. 74, Michigan P.A. conformance with regulations and rules the United States Department of the International Action of the International Action of the International Michigan Board of Land Surveyors monumented, recovered, found as exp. NOTE: Not more than 2 corner.	survey on November 20 of 1970, the corner points in the terior, Bureau of Land Manad in lines 3, 4 and 5 above wor by a Decree of a Couressed below:	nentioned in lines 1 and 2 above we current manual of survey instructing gement or by a decree of a Court of vere in conformance with the rules into f Law; established, re-established.	vere in ons of flaw of the ished,	20 21 22 23 24 29 28 27 25 25
on this certificate.	o, un m mo oumo tomo	·	1	32 33 34 35 36
A. Description of original monume	ent and accessories and/	or subsequent restoration:		
4-15-1823 General Land Office corner M-5, T5N-R5E) 1965 Gould Engineering, Inc. (Control of the corner M-5, T5N-R5E) 1965 GEI records: unidentified 11-02-1976 PA 132 Certified Sugiven with township jog 11-22-1976 Land Corner Recorn w/four accessories 9-15-1989 LCRC, Liber 2380, P B. Description of corner evidence GLO corners and accessories in Recovered one accessory from Confirmed within acceptable tole Recovered corner as identified a Recovered corner as identified a Recovered corner as identified and the corner as identified a recovered corner as identified and the corner	GEI) records: iron w/for corner w/two accessor arvey, Liber 1957, Page offset from M-5, T5N-F dation Certificate (LCR age 998: 1/2" rerod in a found and/or method appears to found each of the two sets of the two sets of the and three accessories to and three accessories to the two sets of the two sets	ur accessories ries 2 791: half-mile measureme R5E to A-5, T5N-R6E C), Liber 1957, Page 975: monument box w/four acce plied in restoring or reestablish f 1965 GEI records fset dimension on the 1976 from 1976 LCRC	ents for adjacent to 1/2" rerod in monu ssories ning corner:	ownship
The monument found was ratified November 18, 1998	ed by the Genesee Cou	unty Remonumentation Pee	r Review Committ	U,
C. Description of monument for corner and accessories established to perpetuate locating the position of the corner:				
Set in concrete the standard Be Remonumentation Corner, 1998 NORTH 83.98' set concrete nail WEST 85.67' set Genesee Cour S 35° E 33.05' found nail/tag #3.	3, #29242" over 1/2" rei I in top of ROW marker nty Witness Tag in W fa	rod in monument box ace 10" twin oak	Ratified by accordance w	Peer Group in with P.A. 345, 1990
SOUTH 12.52 set Genesee Co NORTH 22.38 south edge of pa	unty Witness Tag in W		Date 11	18-48
Signed by	an little	Date	12/8/9	3
Kevin Banfield Cleaver, Surveyor's Michigan License No. 2	A T PROFESS	SIONAL YOR	MICHIGAN STATE BOARD	DF PROFESSIONAL SURVEYORS, JAN. 28, 1971
98-GCRM-DGR-2820	No 1 E S	510 PORM APPROVED BY	INAUG STATE BUAKU	REVISED MAY 14,1975 REVISED JAN., 1983 REVISED OCT., 1995