Ratified by Peer Group In accordance with P.A. 345, 1990

1995 REMONUMENTATION PROGRAM

LAND CORNER RECORDATION CERTIFICATED FINING Requirement of Act 74, Mich. P.A. 1970	9801 orde	1
Filing Requirement of Act 74, Mich. P.A. 1970	MUNTING	

Ço. Rep	0	No	حمل
		-012	

For corners in Corner Code # Located In: Genesee (County) 112 للعو 0 1. Public Land Survey 8N R SURVEY & R 2. Property Controlling Register of Deeds Stamp & File REWONUMENTAT in Section Miscellaneous

MAY 31 2000

, Recorded Plat 4 Int No. 5. Private Claims SECTION

I, <u>Jack N. Owens</u>, <u>Prof. Surveyor</u>, in a field survey on <u>September 26,1995</u>, do hereby certify that under requirements of P.A. 74, Michigan P.A. of 1970, the corner points mentioned in lines 1 and 2 above were in conformance with regulations and rules therefore as required in the in a field survey on September 26, 1995, current manual of survey instructions of the United States Department of the Interior, Bureau of Land Management or by a decree of a Court of Law and/or that the corner points mentioned in lines 3, 4 and 5 above were in conformance with the rules of the Michigan Board of Land Surveyors or by a Decree of a Court of Law; established, re-established, monumented, re-monumented, recovered, found as expressed below:

NOTE: Not more than 4 corners, all in the same town and range, may be recorded on this certificate.

Description of original monument and accessories and/or subsequent restoration:

GLO - H. Ball, DS set post and 2 accessories 1822

1866

GCSR - Stephen Matthewson C.S.; stake & stone, measured between corners L-5 and M-5, no accessories. 1907 GCSR - unknown county surveyor; pine root, measured between corners K-5 and L-5, and M-5 and L-5. 1906 1907 and 2 new accessories.

1920 GCRC - witnesses; stone with 6" fence post along side, and 2 new accessories. 1930

GCRC - witnesses; railroad spike, and 3 new accessories. 1967

1982 Cert. Surv. - 1972 L 1837 pgs 437-438, David T. Rowe PS11192; 1976 L 1960 pgs 988-989, 1977 L 1976 pgs 902-903, 1977 L 1978 pgs 129-130, 1978 L 2005 pgs 923-924, 1978 L 2016 p 193, 1978 L 2030 p 150, 1978 L 2030 p 154, 1979 L 2054 p 297, 1979 L 2057 pgs 432-433, 1982 L 2137 p 831, all by Jan S. Fokens PS21567; 1972-1978 fnd railroad spike, 1979-1982 re-rod w/cap RLS #11192, and 3 new accessories.

(Continued on back)

Property in Sec.

Description of corner evidence found and/or method applied in restoring or reestablishing corner:

1995 Fnd 1/2" re-rod and cap #11192 in mon. box, and 1 accessory from 1906-1907 (12" sugar maple to SW at 59 links (38.94')) and 2 accessories from 1967 (cor. hse to NNW at 71.75', and cor. hse to SE at 103.75') and 1 accessory from 1972-1982 Cert. Surveys (pk & washer in 36" maple to SW at 37.81') and 1 accessory from 1985 (back of curb to North at 14.95') and 1 accessory from 1987 (chiseled "+" on curb to North at 14.76') and 2 accessories from 1989 (tag #11192 in maple to SW at 39.88' and rod #33134 to NE at 30.70'), and 1 accessory from 1990 (chiseled "+" on top curb to NW at 56.83') In 1866, Stephen Matthewson C.S. recorded having found or set a stake and stone at L-5, he measured between L-5 and M-5 and noted no accessories. In 1906-1907 an unknown county Surveyor had found or set a pine root, measured between

(Continued on back)

Description of monument for corner and accessories established to perpetuate locating the position of the corner: Ratified by Genesee County Peer Group, November 29, 1995

ACCESSORIES:

\$45°W. Found pk in NE fc 36" maple 37.83 bent nail & tag #11192 in WNW fc 39.891 bent nail & tag #11192 in whw ic Cor siding, SE cor. hse #7266 Cor brick facing, Nw cor. hse #7259 Chisl "+" on top curb Chisl "+" on top curb at E side dry opening hse #7266 N05°W 71.38 S10°E 103.85

14.77° 56.77° North

N75°E,

Fnd 1/2" rod and cap 33134 off road shoulder

I set the standard Bernsten monument SS-A-5-BR-30 (3 1/4" D. brass cap stamped "Genese County Remonumentation Corner 20709,1995" with 30" x 2 3/8" O.D. stainless steel tube over 1/2" re-rod & cap #11192 in mon. box.

Date Signed by Surveyor's Michigan License No. 20709

Dec 28, 1995

FORM APPROVED BY MICHIGAN STATE BOARD OF LAND SURVEYORS, JAN. 28, 1971 REVISED

D

17

20

29

32

16

21

28

-33

ΙN

15

22

27

11

14

23

26

35

12

13

24

25

2 3

5

á

7

8

Q 10

11

12

13

18

19

30

8 JACK N OWERS LAND SURVEYOR No. 20709 CARD



Description of original monument and accessories and/or subsequent restoration:

- 1976
- 1978
- 1982
- REI Field sketch, SE cor. Sec. 12, pipe in mon. box, no accessories.

 REI Field sketch; NE cor Sec. 13 T8N-R5E, fnd 3/4" iron pipe, no accessories.

 REI Field sketch NE cor Sec. 13 fnd 5/8" iron in mon. box, no accessories.

 Cert. Surv. L 2230 pgs 684-686, by David T. Rowe PS 11192, 1985 L 2234 pgs 512-514, by 1985 Jack N. Owens PS 20709; fnd pipe in mon. box, and 3 new accessories.
- 1985 REI - Field Sketch; NE cor Sec. 13, pipe in mon. box, fit ties, measured between corners M-5 and L-5, no accessories listed.
- 1987 Cert. Surv. L 2305 p 252, by Jack N. Owens PS 20709; find iron rod in mon box, and 3 new accessories
- 1987 REI - Field sketch; fnd pipe in mon box, SE cor Sec 12, no accessories.
- Cert. Surv. L 2372 pgs 793-794, by Paul N. Brown PS 33134; fnd 3/4" pipe in mon box, and 2 1989 new accessories.
- REI Field sketch; NE cor Sec. 13, pipe in mon box, no accessories.
- REI Field sketch; fnd 3/4" pipe in mon. box, no new accessories. 1993

В. Description of corner evidence found and/or method applied in restoring or reestablishing corner:

accurately describe this monumentation in detail. As noted above for 30 years three accessories (US.P.B.M. to B at 22.7°, corner post to SW at 48.14°, and T/P to NW at 57.44°) from the 1952 GCRC witnesses were still in use and agree with both the pipe found in a mon box and the iron rod in a mon box over the time period of 1975-1983. The recorded surveys from 1985 to 1993, with the exception of the 1987 certified survey, all indicate finding a pipe (3/4° in 89 and 93) in a mon box. Upon review of this evidence, I conclude that the 3/4° pipe in a mon box we found during the 1995 Genesee County Remonumentation program is the same pipe in a mon box found in 1976, which is in the same position as the iron rod in a mon box in 1975, and the steel rod crock in 1952 found by the GCRC, which may possibly be the same monument found or set in 1906-1907, by Moses Middelton, C.S. and he had the 1866 Stephen Mathewson record of the use of the corner. Therefore, I accept its position as a careful and faithful reestablishment of the position of the original corner.

SURVEY & REMONUMENTATION

MAY 31 2000

SECTION