JAN 1 7 1996

COMMISSION

LAND CORNER RECORDATION CERTIFICATE Filing Requirement of Act 74, Mich. P.A. 1970

UBER 001 PAGE 76

GLADWIN Located In: Corner Code #	STATE OF MICHIGAN GLADWIN COUNTY
1. Public Land Survey	FILED-REMONUMENTATION 26 DEC 95 10:51 A.H.
T R	PONNIE K. HOUSE REGISTER OF DEEDS
Property in Sec.	Register of Deeds Stamp & File Number
4. Lot No , Recorded Plat 5. Private Claims	A B C D E F G H I J K L N
MAY—	3 3 2 1 1
I, PAUL B. LAPHAM, in a field survey on requirements of P.A. 74, Michigan P.A. of 1970, the corner points mentioned in lines 1 and 2 above were is conformance with regulations and rules therefore as required in the current manual of survey instructions of the United States Department of the Interior, Bureau of Land Management or by a decree of a Court of Law and // that the corner points mentioned in lines 3, 4 and 5 above were in conformance with the rules of the Michiga Board of Land Surveyors or by a Decree of a Court of Law; established, re-established, monumented recovered, found as expressed below:	n 5
NOTE: Not more than 2 corners, all in the same town and range, may be recorded on this certificate.	9 10 30 29 28 27 26 25
	11
1873 T. GALE MERRILL SET POST WIT.—(1)MAPLE 18" N16°E 33 (2)CEDAR 11" S71°W 20 1980 PAUL LAPHAM FIELD NOTES SET COR. MIDWAY & ON LINE 1/2" IRON WIT.—(3)N45°E CLUMP MAPLES 49.87' (4)S35°E 8" WOOD POST 49.40' (5)N50°W 8" POPLAR 57.85' 1983 PAUL LAPHAM #834761 1994 LEDY SURVEY #1002499 SET R/R SPIKE WIT.—(6)NW 58.82' TO SPIKE IN 8" POPLAR (7)E 42.2' TO PK IN 4" FENCE POST (8)SE 59.87' TO PK IN 8" FENCE POST (9)SW 62.0' TO PK IN 8" FENCE POST	
1980 PAUL LAPHAM L.C.R.C. #249 WITSAME AS (3), (4) & (5) B. Description of corner evidence found and/or method applied in restoring or reestablishing of	corner:
B. Description of corner evidence found and/or method applied in restoring or reestablishing corner: NO CORNER FOUND AT SURFACE, SET CORNER FROM WITNESS #(6), (7), (8) & (9) DID NOT MATCH WITNESS (5), RE-MEAS, EAST LINE SEC, AND SET CORNER MID-WAY & ON LINE-MATCHED WITNESS NO. (5), EXCAVATED BELOW ASHPHALT, FOUND 1/2" RE-ROD 3 1/2" DOWN, AT ANGLE, NO GOOD-HELD POINT MIDWAY AND ON LINE, SET RE-MON MARKER. PROFESSIONAL ON SURVEYOR	
	No. 9433 9435 OFESSION
This Corner established in Gladwin County Remonumentation Program.	Tanna Comment
See dossier for detailed report. C. Description of monument for corner and accessories established to perpetuate locating the	position of the corner:
G-10: CORNER COMMON TO SECTIONS 27 & 28 SET 5/8"x36" RE-ROD WITH GLADWIN COUNTY RE-MON CAP, MARKED P.S. #9433.	
WITNESSES: N50°W 8" POPLAR (SPIKE) 57.85' S20°W 8" FENCE POST P.K. NAIL 61.30' S30°E 8" FENCE POST P.K. NAIL 60.40' N85°E 76.55' - NAIL & TAG IN MAPLE CLUMP NORTH P.K. NAIL 2.0' EAST P.K. NAIL 2.0'	APPROVED LAND CORNER P.A. 34% of 1990 Gladwin County Co. Rep. Date 12/14/GG
Signed by Haull - John Date	12-22-95