LAND CORNER RECORDATION CERTIFICATE

	Filing Requirement of Ac	t 74, Mich. PA	A 1970
For Corners In: Gladwin (County)	Located In Corner Cod	e#	
1. Public Land Survey	T 19N R 2E M9		
Property Controlling in Section	S T R		
Miscellaneous Property in Section	S T R		Register of Deeds Stamp & File Number
4. Lot No:	Recorded Plat:		A B C D E F G H I J K L M
5. Private Claims:			2 - 6 - 5 - 4 - 3 - 2 - 1 - 1
requirements of PA 74, Mic and 2 above were in conforthe current manual of sur Interior, Bureau of Land Ma corner points mentioned in of the Michigan Board of	field survey on Feb. 2, 2005 do hereby state that chigan PA of 1970, the corner points mentioned in light mance with regulations and rules therefore as requivey instructions of the United States Department in agement or by a decree of a Court of Law and/or the lines 3, 4 and 5 above were in conformance with the factor Law and/or the monumented, recovered, found as expressed below	under nes 1 4 red in 5 of the at the rules 7 Law; 8	
NOTE: Not more than 2 corners, all in the same town and range, may be recorded on this certificate.		nay 10	10 30 29 28 27 26 25
		11	
		12 13	
M9 – GLO – N. 80 CH Set Post – L. Clase Aspen 8" S25°W 3 Y. Pine 15" N39°W - GLO Sub. – J. Mu Aspen 6" N42°E 1 Aspen 8" S55°E 2 - CCC Notes – 193 post. Post is 2.41	on – 1837 3 L. / 61 L. / 61 L. illett – 1846 3 L. 2 L. 0's – N. Random 160 CH Random E. and 0.73 S. of Random	CPC Notes - 19 N65°W 71.4' - 1 Fd. 1 1/2" pipe –	1967± (Edmands Eng.) Set iron; 12" Oak; N20°E 55.4' – 8" Oak. Also – 18" High – N44°22'W 82.26' – (Calc.)
B. Description of corner evidence found and/or method applied in restoring or re-establishing corner: M9 – Standard Corner common to Sec. 19 & 30, T19N, R3E and Sec. 24 & 25, T19N, R2E – No conclusive GLO evidence. Set 4" DNR Alum. Cap on 1" x 36" galv. iron pipe single proportion between 'M7' and 'M11' on line between 'M8' and 'M11' to fit historic N-S fence. Mon. falls in N-S Fence, North of swamp edge. South 25'± 5' to edge of swamp. East 80'± 3' (94' – GLO) to edge of swamp. Also found 1 ½" iron pipe N84° 45' W 36.39' from 'M9'. This 1 ½" pipe is consistent with monumentation fd. N & S apparently by CCC survey in 1930's. Felt 1 ½" pipe was to far West to be acceptable, probably due to 1 Chain Westerly blunder 1 mile north. GLO corners found N & S are within 4' of/or in fence. Also searched for Consumer's iron S44°E 82' (as calculated from their notes) from 1 ½" pipe. This position is in swamp which is inconsistent with GLO notes. Also East of N- S fence. No Consumer's iron found. DNR Mon. accepted as a careful and faithful re-establishment of the position of the original corner.			
C. Description of monun	nent for corner and accessories established to	perpetuate locat	ating the position of the corner:
S70°E 14.93' to se N25°E 36.51' to se N20°W 29.61' to se S60°W 59.96' to se	o on 1" x 36" galv. iron pipe. Set Blue Carsonite t N & T in S. side 13" R. Maple scribed 'XBT' t N & T in W. side 13" Tw. Oak scribed 'XBT' et N & T in E. side 13" Oak scribed 'XBT' et N & T in NW side 5" Oak to Fd. 1 1/2" iron pipe	Post 1' West.	CRAIG W. MCVEAN PROFESSIONAL SURVEYOR No. 39088
Signed by:	mig W. Ma Ven	Date: 5	5/9/2007

Surveyor's Michigan License No.: