LAND CORNER RECORDATION CERTIFICATE

Filing Requirement of Act 74, Mich. PA 1970

Corner Code #

Located In

For Corners In:

Surveyor's Michigan License No.:

39088

Gladwin

(County)		
1. Public Land Survey	T 20N R 2E M7	
Property Controlling in Section	S T R	
Miscellaneous Property in Section	S T R S T R S T T R R T T T T R T T T T	Register of Deeds Stamp & File Number
4. Lot No:	Recorded Plat:	ABCDEFGHIJKLM
5. Private Claims:		2 - 6 - 5 - 4 - 3 - 2 - 1
requirements of PA 74, Mi and 2 above were in confo the current manual of sur Interior, Bureau of Land Ma corner points mentioned in of the Michigan Board or	field survey on June 29, 2005 do hereby state that chigan PA of 1970, the corner points mentioned in ormance with regulations and rules therefore as recovery instructions of the United States Department an anagement or by a decree of a Court of Law and/or lines 3, 4 and 5 above were in conformance with the fund Surveyors or by a Decree of a Court , monumented, recovered, found as expressed belowere.	lines 1 uired in 5
NOTE: Not more than 2 corners, all in the same town and range, may be recorded on this certificate.		
pe recorded on this ce	runcate.	11 12 -31 -32 -33 -34 -35 -36 -
M7 - GLO - Set Post - Leaning Hemlock 1 S. Maple 10" N80° GLO Sub T20N, Maple 14" N62°E 3 Hemlock 6" S42°E Arenac CSR - F.B Marked W.P. Stub Arenac CSR - L. 1 Fd. post and witnee Gladwin CSR - L. Corner. Pine stub LCRC - #141 - and T. P. O'Brien - 197 4" Birch clump N21	14" S47°W 34 L. W 17 L. , R3E – J. Mullett – 1846 B1 L. 24 L. s. #'1B', p. 55 – Fd. Corner and witness. 30" S46°W 75 L 1901 , p. 34 – 36 – 1902 sses; W. Pine stub 30" S46°W 75 L.; 1, p. 105 – I. Knox – 1908 – Fd. stake for	ent restoration: Fd. ½" Sq. Shaft; South 33.29' to nail in fence post; NE 65.48' to nail in Bell Box post; SE 50.81' to nail in 24" Tw. Oak Rec. Sur. – L. 1, p. 605 – Arenac Co. Rec. – T. L. Lapham –1985; Fd. ½" Sq. Bar; . South 33.29' to nail in Fence Post; NE 65.48' to nail in Bell Box Post; SE 50.81' to nail in 24' Tw. Oal-LCRC #385 – Gladwin Co. Record – C. F. Roser – 1995 – Fd. ½" Square iron; 6" Cedar N20°W 96.57'; 6" Ash N35°E 75.15'; 10" Tw. Cedar S30°E 41.31'; 5" Ash S40°W 39.50' - Centerline of Gravel Rd. N is 2' ± W.; centerline of Gravel Rd. W. is 2' ± N. Cor in line with CTR B. Top Rd. east. Cor. fence post lean S. is 33' S
B. Description of corner	evidence found and/or method applied in res	coring or re-establishing corner:
M7 – Standard Corner common to Sec. 18 & 19, T20N, R3E and Sec. 13 & 24, T20N, R2E – Fd. Pk. Nail in Bit. 'T' intersection. Centerline of gravel rd. N. is 2'± W. Centerline of E-W Bit. Rd. is 2'± N. Falling Corner post for fences E, W & S is 33'± S. Fit 4 witnesses by Roser and others by Ledy, Lapham and O'Brien. ½" sq. iron apparently obliterated by Rd. Construction. GLO & CSR Wit's are gone. Pk nail accepted as the best available evidence of the position of the original corner.		
C. Description of monument for corner and accessories established to perpetuate locating the position of the corner:		
S40°W 39.49' to so S28°E 41.38' to Fo S7°W 27.80' to set N16°W 96.51' to F N36°E 75.11' to se	with 3" Arenac Co. Brass Cap on 5/8" x 34" re et N & T in NW side 8" Ash (CFR) d. nail in SW side Tw. 12" Cedar (TPO, CFR) t N & T in E. side light pole d. DBL Headnail in E. side 10" Cedar (CFR) et N & T in W. side 9" Ash (CFR) et N & T in NE side 32" Oak (TLL, DFL)	CRAIG W. MCVEAN PROFESSIONAL SURVEYOR

39088

AROFESSIONA