SURVEY & REMONUMENTATION

SEP 29 1994

Gogebic

For corners in

COMMISSION

LAND CORNER RECORDATION CERTIFICATE Filing Requirement of Act 74, Mich. P.A. 1970 Register's Office Gogetic County

Corner Code ##

polenic com	nty j
Rece	ived for record the day of Sapramean
16 7#	day of SEPTEMBER
	at 3:20 o'clock
P	a., and recorded in
18km 5	A CORNERS
Dage 4	Calling, Deput
hamone	Colling Deput
	Register of Fleeds

1. Public Land Survey Sec. 15 T 44N R 41W H-7

T R

T R

T R

2. Property Controlling S T R

in Section S T R

3. Miscellaneous S T R

R

Register of Deeds St

Register of Deeds Stamp & File Number

	Property in Sec.	S R	-		
4.	Lot No.	Recorded Plat	·		
5.	Private Claims				
	One-quarte	r corner common to Sect	ions 15 & 22. T	144N-R41W	

Located In:

February 2 94

I, ___John R. Garske____, in a field survey on ________, 19 ______,

do hereby certify that under requirements of P.A. 74, Michigan P.A. of 1970, the corner points mentioned in lines 1 and 2 above were in conformance with regulations and rules therefore as required in the current manual of survey instructions of the United States Department of the Interior, Bureau of Land Management or by a decree of a Court of Law and/or that the corner points mentioned in lines 3, 4 and 5 above were in conformance with the rules of the Michigan Board of Land Surveyors or by a Decree of a Court of Law, established, re-established, monumented, re-monumented, recovered, found as expressed below:

NOTE: Not more than 4 corners, all in the same town and range, may be recorded on this certificate.

A. Description of original monument and accessories and/or subsequent restoration:

Quarter section post set by Algemon Merryweather in July 1852 consisting of a 5" hemlock as the corner tree from which a 6" hemlock bears S10°W - 2 links (1.32 feet).

PEER GROUP
Richard L. Wealn

Approved

B. Description of corner evidence found and/or method applied in restoring or reestablishing corner:

No original survey information could be found. We found a 1" I.D. iron pipe with an old wood post in poor condition lying on ground. This corner position is shown on a 1927 survey by a D.S. Burnett, a 1960 survey map by W. Tuttle and in a 1972 survey by Joseph Harding. The iron pipe I found is historically in the correct location and is referenced in many deeds of record. It is in a harmonious location being used and accepted by area residents.

Record research on file with CountyRegister of Deeds office.

C. Description of monument for corner and accessories established to perpetuate locating the position of the corner:

Set a 3/4" x 30" rebar inside existing pipe with a 3 1/4" stamped aluminum county tablet. Established the following bearing trees and reference objects:

12" maple - N48°E - 56.07 feet 8" maple - N85°W - 18.64 feet 12" w. birch - N25°W - 18.34 feet P. pole #85-20577 - S21°E - 40.55 feet Steel sign post - S45°W - 2.00 feet

2-1

OF MICH

JOHN R. GARSKÊ

LAND SURVEYOR No. 28410

Signed by DUNEC

Surveyor's Michigan License No. 28410

Date