SURVEY & REMONUMENTATION

OCT 0 3 1996

COMMISSION

Register's Office \ Gogebic County |

•	LAND COR	NER RECORDATION CERTIFICATE	- ·
For corners in Good		uirement of Act 74, Mich. P.A. 1970	Received for record that
Goger	Located In:	Corner Code #	28th day of MALCH
(County)	,	·	A. D. 1996 at 11:25 o'clock
			A and recorded in
1. Public Land Survey	Sec. 15 T 45N R 391	<u> G-8</u>	Liber 5 OI CONNERS
•	T R		1 and 5 of Colombia
	T R		03 page 334
	T R		Ramora Collins Dasitte
2. Property Controlling	S T R		Register of Dads
in Section	S T R		-
3. Miscellaneous	ST R		
Property in Section	S T R	Re	gister of Deeds Stamp & File Number
4. Lot No,	Recorded Plat		
5. Private Claims			- ABCDEFGHIJKLI
			2 6 - 5 - 4 - 3 - 2 1 -
One-quarter co	r. to Sections 21 and 22, T45	3	
Tales D. Co. st		_	4 7 8 10 10 11 12
John R. Garske	; , in a field survey on	January 17 , 19,	5
do hereby certify that under requirements of P.A. 74, Michigan P.A. of 1970, the corner points mentioned			6 18 17 16 15 14 13
in lines 1 and 2 above were in conformance with regulations and rules therefore as required in the current			7
manual of survey instructions of the United States Department of the Interior, Bureau of Land Management or by a decree of a Court of Law and/or that the corner points mentioned in lines 3, 4 and			
5 above were in conformance with the rules of the Michigan Board of Professional Surveyors or by a			8 19 20 21 22 23 24
Decree of a Court of Law; established, re-established, monumented, re-monumented, recovered, found			9
as expressed below:			10 30 29 28 27 26 25
NOTE: Not more than 4 corners, all in the same town and range, may be recorded			11
on this certificate.			12 31 32 33 34 35 36

- Description of original monument and accessories and/or subsequent restoration:
 - Original survey by Wells Burt, D.S., in 1851. He set the 1/4 post from which: Y. birch 20" North 3 links and a W. pine 30" - S77°W - 27 links.
 - 1969 MDOT Highway 45 plans show approximately 1/4 cor.
 - 1979 Survey by Ewart Muller shows corner to be a 3/4" iron rod set by single proportion. Corner recorded 3-10-80 in L2, pg. 55 of land corners. Bearing trees/objects: Nail in centerline Highway 45 - Due West - 43.00 feet; conc. R/W post - Due East - 22.11 feet; power pole - N44°E - 40.23 feet.
- B. Description of corner evidence found and/or method applied in restoring or reestablishing corner:

I found a 3/4" iron rod at the 1/4 corner location as per Muller's Certificate. The iron rod is on line with two concrete R/W monuments and checks reasonably well with distance ties to the post and power pole. Measurements north and south to existing corners indicate that the iron is on line and at the midpoint.

(P.A. 74 Research on File)

C. Description of monument for corner and accessories established to perpetuate locating the position of the corner:

I set a 3 1/4" diameter aluminum cap on the 3/4" iron rod found and stamped it: T45N, R39W, 1/4 cor. S-21, S-22, 1996, RLS 28410, from which I established the following bearing trees and/or reference objects:

P. Pole - N44°E - 40.15 feet

Concrete R/W post - Due East - 23.353 feet

Concrete R/W post - Due East - 31.13 feet

Steel sign rail - Due East - 2.33 feet

Signed by 28410 Surveyor's Michigan License No.

LAND SURVEYOR No. 28410

LAND

JOHN R.

GARSKË

REVISED MAY 14, 1975