	LAND CORNER RECORDATION CERTIFICATI								WERTHRE LIBRIEW I									
Filing Requirement of Act 74, Mich. P.A. 1970 For corners in							,			,	P 150c	an mal	43.4					
Gogebic Located In: Corner Code #							Received for record the 26TH day of May A. D. 19 00 at 10:35 o'clock											
1. Public Land Survey		N R <u>44 W.</u> RR	SURVEY & SEMONUMENTATION JAN 0 5 2001	C-4 URVEY &- HIMENTATION		Uh	<u> </u>	7	6., 64	and	reco	rde	d in	t				
 Property Controlling in Section Miscellaneous Property in Sec. 	S T	R R R R		N 05 2001	F	Regis	De ter o	Te of De	Ri eds S	gist	7 9 p 8 F	ile I	Num	€ ber				
4. Lot No, R	ecorded Plat				_	_								_				
5. Private Claims					1 A	B	CE	E	F	G I		Ť	K	Ť				
1/4 Corner 7 & 8; T.46	3 N., R.44 W.				3	- 6	+:	5-1	-4- 	+	3	-2- - -	+	-1-				
I, Richard L. Drahn, in a field survey on May 6, 2000 do hereby state that under requirements of P.A. 74, Michigan P.A. of 1970, the corner points mentioned in lines 1 and 2 above were in conformance with regulations and rules therefore as required in the current manual of survey instructions of the United States Department of the Interior, Bureau of Land Management or by a decree of a Court of Law and /or that the corner points mentioned in lines 3, 4 and 5 above were in conformance with the rules of the Michigan Board of Land Surveyors or by a Decree of a Court of Law; established, re-established, monumented, recovered, found as expressed below:						- ⁷	1	7	⁹ 16		5	14		-12 -13				
						-19	2	0	21 	-2	2	_23 		-24-				
		·			10-	30	2	9	28	 2	7	2 ₆	+	-25-				
NOTE: Not more than 2 comers, all in the same town and range, may be recorded on this certificate.							3	2	33	 - -	4	35-	_	-36-				
A. Description of original	monument and a	ccessories and/o	or subse	quent restoration:	13					<u>l</u>		_						
Original corner establis																		
Fir Maple			nks links	(5.28') (22.44')														
B. Description of corner e	evidence found a	nd/or method ao	olied in	restoring or reestablishing	com	er.												
Corner research on file with			, ,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,	. socioning of rooting	00	nd nd												
Restored corner position at Maple stump decayed to w remains.	record bearing a ell below ground	nd distance from line. Old stump	n the rei has an	nains of the original Red N 11" Red Maple sprout. N	/laple o evic	bear dence	ing t err	ree. nains	It is of th	now ie Fi	a lai r bea	rge Iring	Red) tre	Ð				
C. Description of monume	ent for corner and	l accessories est	tablished	I to perpetuate locating th	e pos	ition	of ti	ne c	orner:									
At the corner location I set From the monument I set the	a 2" X 30" alum he following new	inum pipe monu , scribed bearing	ment w trees:	ith a 3 1/4" aluminum cap	stan	nped	to ir	ndica	ate th	e co	rner i	posi	tion					
Red Maple	8" N.5	8° W. 27.	41'					<u>.</u>	A S	S 2	-							
Red Maple Red Maple		2° E. 24. 6° W. 17.					1				Sec. 14							
Steel sign rail			53'				! *	/	RIÇ L. D	HARI RAH	_	1		į				
		Ric	Lord	ER GROUP APPROVE P. Drahn 05/2 Dum Brokensusting). 4/00	,			SUR 21	VEYC 10. 564	IR		* **					
Signed by Richard	L L. 20 2	calm 1	Date	May 12, 2000				Wife	0 1	6 H D								
Surveyor's Michigan Licens	e No	21564		FORM APPROVED BY MICHIGAN	STATE E	BOARD	OF PRO	OFESSI	ONAL SI		ORS, J							

USFS G-5

REVISED OCT., 1995