	LAND CORNER RECORDATION CERTIFICATE Filing Requirement of Act 74, Mich. P.A. 1970						Gogebic County Ss. Received for record the							
For corners in														
	Gogebic	Located In:	Corner Code ##		*****			•	ol _£					
	(County)				A. 1	9. 19	94	_at_:	4:10	0	'cloc	k		
1. Բւ	iblic Land Survey	т <u>47N</u> R <u>47</u> W	M-13			r	n	L., M	nd re	cerd	led i	20		
		T 47N R 46W	A-13		6	perte.	14	,	. مس		_			
2. Pr	operty Controlling	S (46N. R 47W.	M-1		Ka	M	one		olla ister		_			
in	Section	STR	<u> </u>								-			
Mi	scellaneous	s т <u>46м.</u> R <u>46w.</u>	<u>A-I</u>	Regist	er of D	eeds	Star	np &	File	Num	ıber			
	operty in Sec.	S T R Recorded Plat												
		Tecorded Flat			P		1	F G	H	ĖΫ	<u> </u>	7		
J. FI		orner common to Sections 36			3 — 6 — 3 — 1 —	5	_		-\frac{1}{3}	½	+	 		
_			June 20 94	4	۱ 	 		<u> </u>	-10-	11	+	-12		
_{I,} Joi	nn R. Garske	, in a field survey on	, 19	;	⁵├ ┈├ ━	+	-	├	+	╂╼┾	+	+-		
do hereby certify that under requirements of P.A. 74, Michigan P.A. of 1970, the corner points mentioned in lines 1 and 2 above were in conformance with regulations and rules therefore as required in the current manual of survey instructions of the United States Department of the Interior, Bureau of Land					6 — 1 8— 7 — —	17		16	15	├ 1¼	 	-13-		
Management or by a decree of a Court of Law and/or that the corner points mentioned in lines 3, 4 and 5					3	20		21	_ 22	1—23	,	-24		
above were in conformance with the rules of the Michigan Board of Land Surveyors or by a Decree of a					ـــــا					\sqcup				
Court of Law; established, re-established, monumented, re-monumented, recovered, found as expressed below:					30-	29		28	_27	 26	;-	-25		
NOTE	: Not more than 4 o	corners, all in the same town an	d range, may be recorded	1: 1:	2 31-	132		33	_34	3:	#	-36—		

On September 3, 1847, William A. Burt set a hemlock post at town corner from which a Y. Birch 16" bears S25°E, 25 links and a hemlock 18" bears S52°W, 21 links.

No original evidence found due to road construction.

A. Description of original monument and accessories and/or subsequent restoration:

PEER GROUP

Approved

Rand P. Dralin

B. Description of corner evidence found and/or method applied in restoring or reestablishing corner:

Found a 2' long x 2" diameter pointed iron pipe 4" below road surface. Pipe was found to be bent and in poor condition. I carefully dug up comer and replaced it at the mark the point of the pipe left in our excavation. I accepted the corner as being true due to the substantial pipe found, at the proper location within the intersection of South Davis and East Pioneer Road. This pipe has been used and accepted as the section corner for many years.

After restoring the corner position, I upgraded it as noted below to state and county specifications. Comer was found 0.50 feet west of the approximate centerline of South Davis Road and 1.50 feet north of the approximate centerline of East Pioneer Road.

Research record form on file with County Register of Deeds Office.

C. Description of monument for corner and accessories established to perpetuate locating the position of the corner:

I replaced found bent iron pipe with a 1" x 36" iron pipe with a 2 1/2" brass cap with a 2" stem on top of pipe set in anchoring cement 3" below road surface. I established the following bearing trees and reference objects: A reference monument consisting of a 2 1/2" x 30" aluminum pipe with a 3 1/4" aluminum cap stamped to indicate the corner position as follows: S47°E, 48.12 feet with a steel sign post 1.71 feet away; 14" R. pine - N20°E, 108.44 feet; P. pole #5 - 5/96 - S45°E, 39.82 feet; P. pole #1 - 94/93 - S52°W, 41.87 feet. OF HICE

Signed by Surveyor's Michigan License No. 28410

Date

GARSKE LAND SURVEYOR

JOHN R.

VEYORS, JAN. 28, 1971 EVISED MAY 14, 1975

FED. No. Z-25