## SURVEY & REMONUMENTATION

SEP 0 8 1998

SECTION	LAND CORNER RECO	ORDATION CERTIFICA of Act 74, Mich. P.A. 19	ATE Register's ( 70 Sogsbic Co	Miles des.	
For corners in	i mig ivedunement o	1 ACC 74, WIICH, P.A. 19	Re	ccired for remed th	P.
Gogebic Locate	ed In: Corner Code	#	2320	B at 11:35 o'cles	
1. Public Land Survey	747NR 44W K-	B	A. V. LULL	m., and recorded	ia
2. Property Controlling S	T R		Liber og page kumona	O CORN	
4. Lot No, Recorded Plat			ABCDE	FGHIJK	т.
5. Private Claims		<del></del>			Ť
Quarter corner common	to sec's 23 & 24,	, Т47N , R44W	3	-432	$\frac{-1}{\perp}$
requirements of P.A. 74, Michigan P.A. of 1 conformance with regulations and rules there United States Department of the Interior, Bur that the corner points mentioned in lines 3, 4 Board of Land Surveyors or by a Decree recovered, found as expressed below:	970, the corner points mentioned in la fore as required in the current manual eau of Land Management or by a deci and 5 above were in conformance w	lines 1 and 2 above were in of survey instructions of the ree of a Court of Law and /or ith the rules of the Michigan	5 6 18 17 7 8 19 20	-21 -22 -23 <b>•</b>	-12-  13-  24-
NOTE: Not more than 2 corners, all in the	he same town and range, may be	recorded	9	<del>             </del>	
on this certificate.			10 30 29 11 12 31 32 13	-28 -27 -26 -33 -34 -35	_25-    -36- 
Corner established by Original bearing tree On June 15, 1972, Don record bearing and di the Yellow Birch, and a capped 3" circular S-24; R.L.S. 12585; 1 objects: 10" Hemlock B. Description of corner evidence foun 6" Yellow Birch - N 8 He recorded said corn Found the stump of th Found Lappala monumen I updated the monumen	Yellow Birch 19 yellow Birch 19 ald D. Lappala, Ristance from decays natural feature to bronze tablet which 1971, from which he N 30° E- 21.5'; adand/or method applied in resto 7° W - 22.4; 4"x4" er in U.S. Forest e Hemlock S 58° Et and witnesses.	O" - S 58° E - O" - N 40° W - LS, USFS, restored hemlock wind ties. He set a ch reads: T.47 e established to 12" Hemlock - oring or reestablishing corner or Cedar sign por Service Liber - 32 links.	32 links (2 21 links (1 21 links (1 pred corner affall and st 2½ I.D. in N., R.44 W. the following S 07° W - 1 per S 75° P-21 on Aug	21.12') 13.86' position at tump hole of con pipe with ; 1/4; S-23, ag reference 12.4'  E - 2.8' gust 10, 1972	n ,
specification.		AS HOUSE DELOW		ind county	
Act 74 research on fi	)	Reclard R. Dra	122/90 1233-432113	?	
C. Description of monument for corner of From the found monument objects:  14" Hemlock 15" Hemlock 11" Yellow Birch 11" Hemlock 4"x4" Cedar Sign post (All measurement takes	N 30° E 21.59 S 07° W 12.45 N 87° W 22.21 Due East 36.29 S 75° E 2.45 n to nail in side	the following e  '  '  '  '  '  '  '  '  '  '  '  '  '	tion of the corner: existing and	JOHN P. GOSS LAND SURVEYOR No. 23509	C ××× Hn. Humber
Signed by Gohn P Loss Surveyor's Michigan License No		Date June	30, 1998	WHITE LAND STREET	
Surveyor's Michigan License No	23509				