JAN 2 2 1998

Signed by

Surveyor's Michigan License No.

· OFTH 10 10 10	-		;	į:	
SECTION	•		, 1	Register's Office	
		AND CORNER RECORDA		Received	for record the
For corners in		Filing Requirement of Act 7	74, Mich. P.A. 1970	22 42	DECEMBE
Gogebic		-		uay	امراءي ١١١٨
	Located In:	Corner Cade #	•	A. D. 19 97 at	0. Clock
(County)	•			Am.,	and recorded is
45161 15	Section 25 481			Liber 6	OF CORNER
1. Public Land Survey	<b>∠</b> T_48	NR_46WA-10		310	
	<u>_</u>	<u> </u>	ľ	page 3/0	Jim Diout
	<u> </u>	_R R		A. 001 P. 1. 247	
2. Property Controlling	s t	- <del>P</del> . ————		ŧ	legister of Debt
in Section	s †	- <del>R</del>			
3. Miscellaneous	s T	R			
Property in Sec.	ST	R	_		
• •			F	Registe pf Deeds Star	mp & File Numbe
4. Lot No, Reco	orded Plat		,		17 T T 12 Y
5. Private Claims			1 <u>^</u>		1 1 1 1
1/4 corner section	on 25 & 30, T48N	. R47-46W	2	- 64	- 3 - 2
,		,	3 -		
John R. Garske	. in a field survey	on December 11, 19 97do her	eby state that under 4	_789	_101
requirements of P.A. 74, Michig	gan P.A. of 1970, the	corner points mentioned in lines 1 a	and 2 above were in		
conformance with regulations ar	id rules therefore as re	equired in the current manual of surve	ey instructions of the		
that the corner points mentione	d in lines 3. 4 and 5 a	and Management or by a decree of a 6 bove were in conformance with the re	ules of the Michigan	-1 <del>0   17   16  </del>	-15141
Board of Land Surveyors or b	by a Decree of a Co	ourt of Law; established, re-established	shed, monumented,		
recovered, found as expressed t	elow:		8 -	_192021	-22232
NOTE: Not more than 2 co	mers all in the same	town and range, may be recorde	و ب <u>س</u>		
on this certificate.	more, est in the estine	will and failige, may be recorde	1	30 29 29	27262
	•			Ĭ	
		•	11		
			12	-31 $-32$ $-33$ $-$	-34353
			13		
A. Description of original m	onument and acces	ssories and/or subsequent resto	ration:		•
		liam A. Burt in 1847.			
He set a wood p					
Tamarack 18" Tamarack 7"	N81°W S36°E	41 links 46 links			
ramarack /"	330 E	40 links			
•			•		
B. Description of corner ev	idence found and/c	r method applied in restoring or	reestablishing corner:		
7 C 4 4.4					
1 Tound no evide	nce of the original	survey. The corner now falls in enter of the road opposite an an	in the middle of Bale Lar	ne, a gravel road. I fo	und a
on 1979 survey	notes by William	Riipi, RLS in a survey of the G	Fogebic - Iron Airport	Our distances check	IOWR
		North - 2624.70M, 2629.57R,			
			2002,20141, 20	054.5714.	
(Research on file	<b>:)</b>				
•			PEI	ER GROUP APPRO	
			Redon	L. Dealer 1	2/19/97
			<u></u>	THE PROPERTY AND PROPERTY OF	THE
N D == == t=4t === = 4 == = = = = = = = = =					•
Description of monument	for corner and acc	essories established to perpetua	ate locating the position of	f the corner:	
From the found	1/2" iron rod I set	two reference monuments con-	sisting of 3/4" dia. x 3' l	ong alum, rods with 3	3 1/4"
dia. alum. caps s			•	<b>5</b>	
R.M.	West	37.57 feet	• •	THE STATE OF THE S	
Steel sign rail		et, 39.38 ft. to corner	A.	E OF MICH	
R.M. Steel sign Rail	East	34.59 feet et, 36.32 to corner			
	1.73 fee on line with corner		BIT	JOHN R.	
Top of Steel Gat		168.62 feet	as a second	GARSKE X	λ
		other bearing objects available.		LAND THE	7
	-	Õ	7 <del>*</del>	SURVEYOR **	3

Date