1993

COMMISSION

4. Lot No.

Private Claims \_

## STATE OF MICHIGAN COUNTY OF LEELANAU RECEIVED FOR RECORD

## 1993 DEC 28 PM 4: 26

## LAND CORNER RECORDATION CERTIFICATE Filing Requirement of Act 74, Mich. P.A. 1970

For corners in Leelanau Located In: Corner Code ## REGISTER OF DEEDS (County) T 29N\_R 11W 1. Public Land Survey FILE #335 R \_\_ R LIBER 2 PAGE 32 R 2. Property Controlling \_\_\_ T \_\_ in Section Miscellaneous \_ T \_\_\_\_ R \_ Register of Deeds Stamp & File Number Property in Sec.

I, Steven P. Bye , in a field survey on December 13, , 19 93 , do hereby certify that under requirements of P.A. 74, Michigan P.A. of 1970, the corner points mentioned in lines 1 and 2 above were in conformance with regulations and rules therefore as required in the current manual of survey instructions of the United States Department of the Interior, Bureau of Land Management or by a decree of a Court of Law and/or that the corner points mentioned in lines 3, 4 and 5 above were In conformance with the rules of the Michigan Board of Land Surveyors or by a Decree of a Court of Law; established, re-established, monumented, re-monumented, recovered, found as

NOTE: Not more than 4 corners, all in the same town and range, may be recorded on this certificate.

- A. Description of original monument and accessories and/or subsequent restoration:
  - H-1: N 1/4 corner Section 3: G.L.O. "Set 1/4 section post" Beech 12 N 58 W 50 links Beech 10 N 06 E 33 links

- -B. Description of corner evidence found and/or method applied in restoring or reestablishing corner:
  - H-1: N 1/4 corner Section 3: 5/8" iron rod found 2.8' South of centerline McAllister Rd.

This corner was set by Theodore H. Weinert, November 7, 1974. He set it "33' North of found stone per record" on same line as found stone at center post. The County surveyor's notes state, "2 rods South of N 1/4 post drove section of sled shoe 2-1/2" wide 30" long"

- Description of monument for corner and accessories established to perpetuate locating the position of the corner:
  - H-1: N 1/4 corner Section 3: 5/8" iron rod accepted by the Leelanau County Peer Review Group November 29, 1993, and replaced with a 3/4" i.d. galvanized pipe 3' long with a brass cap.

FORM APPROVED BY MICHIGAN STATE BOARD OF LAND SURVEYORS, JAN. 28, 1971 REVISED MAY 14, 1975 REVISED JAN., 1983

STEVEN P BYE LAND SURVEYOR