## LAND CORNER RECORDATION CERTIFICATE Filing Requirement of Act 74, Mich. P.A. 1970 as Amended

For corners in

Houghton (County)	Located In:	Corner Code #					
1. Public Land Survey	T 51N R 3 T 51N R 3						
2. Property Controlling in Section	S T R S T R						
3. Miscellaneous Property in Sec.	S T R S		Re	egister of De	eds Stamp	& File Number	
4. Lot No. , Rec 5. Private Claims	orded Plat H9	05/20/2008	1 A F	B C D 1	E F G	H I J K	L M
I, Stephan J. Szyszkoski, in that under requirements of P.A. above were in conformance with rinstructions of the United States D. a Court of Law and /or that the court of Law and /or the court of	a field survey on 110 74, Michigan P.A. of 1970, the egulations and rules therefore a department of the Interior, Bureorner points mentioned in lines	05/20/2008 do here corner points mentioned in lines as required in the current manual eau of Land Management or by a 3, 4 and 5 above were in conform	decree of 6 nance with 7	8-17-	9-16	-1514	_12
the rules of the Michigan Board re-established, monumented, recover NOTE: Not more than 2 corner on this certificate.			9 10 3 11 3 13	0 29	28 33	-27 -26 -34 -35	25

- A. Description of original monument and accessories and/or subsequent restoration:
- (H9) Quarter corner common to Sections 22 and 27. 1848 Established by S.W.Higgins, Deputy Surveyor, midway and on the true line between Section corners 40.48 chains east and west. Set post. Hemlock 8" N57W 16 links, Sugar 8" N86E 12 links.
- (I10) Quarter corner common to Sections 26 and 27. 1848 Established by S.W.Higgins, Deputy Surveyor, midway and on the Section line between Section corners 40.00 chains north and south. Set post. Balsam 10" N43E 13 links, Sugar 24" S20E 27 links.
- B. Description of corner evidence found and/or method applied in restoring or reestablishing corner:
- (H9) The original post and accessories were not recovered. Found no evidence of the position of the original corner on the ground. Reestablished the corner midway and on the Section line between Section corners 2630.85' east and west, proportionate to the original record.
- (I1O) The original post and accessories were not recovered. Reestablished the corner midway and on the Section line between Section corners 2640.73' north and south.
- Description of monument for corner and accessories established to perpetuate locating the position of the corner:

(H9) Set 1"IDx32" I.pipe with 4" alum. MDNR cap. Set measuring nail with MDNR tag in the side of: 6" Ash NO9E 5.9' mrkd "1/4S NBT" 6" Sugar S67E 26.7' do 6" Sugar S19W 34.4' do 15" Hemlock N64W 36.2' do Set sq'd cedar post adjacent. Bearings magnetic.	(I10) Set 1"IDx32" I.pipe with 4" alum. MDNR cap. Set measuring nail with MDNR cap in the side of: 12" Sugar N03E 14.5' mrkd "1/4S NBT" 5" Maple N84E 4.0' do 11" Maple S06E 20.9' do 5" Y.Birch S45W 16.4' do Set sq'd cedar post adjacent. Bearings are
, , ,	magnetic.

Surveyor's Michigan License No.

08/11/2008

For the Michigan Department of Natural Resources, Office of Land and Facilities

16095

FORM APPROVED BY MICHIGAN STATE BOARD

SURVEYOR

STEPHAN J

SZYSZKOSKI

LAND

16105