LAND CORNER RECORDATION CERTIFICATE Filing Requirement of Act 74, Mich. P.A. 1970

Fo	r corners in Boughton	Located In:	Corner Code ≠#
	(County)		
1.	Public Land Survey	✓ т <u>580 гр</u> 360	J9
	·	T 51N R 35W	K9
		T A	
		T R	
2.	Property Controlling	S 23 T 518 R 350	15
	In Section	S T R	
3.	Miscellaneous	S T R	
	Property in Sec	e	

Register of Deeds Stamp & File Number

4. Lot No. Recorded Plat

5. Private Claims

K9 Warch 15, 1994 15 Warch 21, 1994

NOTE: Not more than 4 corners, all in the same town and range, may be recorded on this certificate.

A. Description of original monument and accessories and/or subsequent restoration:

[JS] Quarter corner common to Sections 23-28. Corner established in 1848 by S.W. Niggins and perpetuated as follows: Set 1/4 Section most on true line, Sugar 12 North 14, Spruce 10 \$400 23. Original line notes show stream crossings 11.87 ch. west and 2.59 ch. east of the corner, on the random. Found no subsequent record.

(K9) Section corner common to Sections 23-24-25-26. Corner restored in 1963 by Billy D. Buckler RLS, at a found old, scribed, cedar post. Corner was remonumented with a 1° pipe and 4° aluminum Mich. Dept. of Conservation cap and the following ABTs: 13° Hard Maple (825 MBT) 858E 67 links, 12° Y. Birch (828 MBT) 830W 59 links, 15° Soft Maple (823 MBT) N28W 77 links.

(15-Sec. 23) West 1/18 corner between Sections 23-26. Corner not established in the original survey. Found no subsequent record.

B. Description of corner evidence found and/or method applied in restoring or reestablishing corner:

(J9) Original post and accessories not recovered. Found no acceptable evidence of the position of the original corner on the ground. Reestablished the corner midway and on a straight line between monumented section corners 2586.84° east and west. From the reestablished position, the streem call east checks to a moderately well defined stream described as in the record. To the west, the stream meanders much, and does not check with the record, being 13.38 chains west of the corner. At the position for the corner, I placed a 1°1.8.x38° iron pipe capped with a 4° dia. cast aluminum MORR tablet, appropriately stamped.

(K9) Found and accepted Buckler's monument as described, at record bearing and distance from the 1963 bearing trees: the Y. Birch being a dead stub. The maple MBTs are in good condition. Marked two new bearing trees as described below.

[15-Sec. 23] Found no evidence of prior monumentation at the corner position. Established the corner midway and on a straight line between monumented Quarter and Section corners 1343.42' east and west. At the position for the corner, I placed a f'I.0.x36' iron pipe capped with a 4' dia. cast aluminum MDNR tablet, appropriately stamped.

C. Description of monument for corner and accessories established to perpetuate locating the position of the corner (J9) Set a 1" pipe with 4" MONR cap. (K3) Found 1' pipe with 4' MONA cap. (15) Set 1" pipe with 4" MDNA cap. Blazed and acribed the following new Blazed and scribed the following new Blazed and scribed the following bearing bearing trees: bearing trees: trees: 5" Sugar 8448 12.7" "1/45 HRT" 7' Sugar N52E 3.0' "S24 NBT" 10" Yellow Birch N88W 22.5" "1/165 BT" 4" Sugar M44E 9.1" "1/45 BET" 10" Cherry \$450 21.7" "\$26 BBT" 8" Sugar #45# 18.5" "1/165 8T" 1" Sugar 546E 9.1" "1/45 RBT" : Bearings are magnetic. 10" Yellow Birch \$45E 5.0' "1/16\$ 81" "1/45 RBT" of Bicare 4" Bugar 562W 18.4" 5' Sugar N78E 26.0' "1/16S BT" Bearings are magnetic. Distances are Bearings are magnetic. Placed a 4" herizontal distances. Placed a 4" squared sugar post adjacent. STEPHAN J. squared sugar post adjacent to the

SZYSZKOSKI

LAND SURVEYOR

Signed by Land Johnson No. 33986

COFRET.

3-21-94

FORM APPROVED BY INCHIGAN STATE DOADS OF LANS EUROPEONS, JAM. 28, 1871 REVISED MAY 14, 1975