## LAND CORNER RECORDATION CERTIFICATE Filing Requirement of Act 74, Mich. P.A. 1970

Fo	r comers in HOUSHTON	Located In:	Corner Code ≠#	1
•	(County)			
1.	Public Land Survey	T R	<u> 8</u> 7	
		T R		l
		T R		l
		T R		ł
2.	Property Controlling	S <u>30</u> T <u>51™</u> R <u>36₩</u>	<u> </u>	l
	in Section	S30_ T51N_R <u>36N</u>		l
3.	Miscellaneous	S T A		1

Register of Deeds Stamp & File Number

Recorded Plat 4. Lot No.

5. Private Claims

Property in Sec.

July 07, 1993 <u>Stephan J. Szyszkoski</u> in a field survey on \_ do hereby certify that under requirements of P.A. 74, Michigan P.A. of 1970, the corner points mentioned in lines 1 and 2 above were in conformance with regulations and rules therefore as required in the current menual of survey instructions of the United States Department of the Interior, Bureau of Land Management or by a decree of a Court of Law and/or that the corner points mentioned in lines 3, 4 and 5 above were in conformance with the rules of the Michigan Board of Land Surveyors or by a Decree of a Court of Law; established, re-established, monumented, re-monumented, recovered, found as expressed below:

NOTE: Not more than 4 corners, all in the same town and range, may be recorded on this certificate.

A. Description of original monument and accessories and/or subsequent restoration:

(P9) Quarter corner between Sections 19 and 30, TSIN-R36N. Corner established by U.S. Deputy Surveyor S.W. Miggins, 1948. Original bearing trees: Maple 8 MSIE 8, Sugar 8 MINU 13. Found no subsecuent record.

(3) North 1/16 corner between Section 30, TSIM-R36W and Section 25, TSIM-R37W. Corner not established in original survey. Found no subsequent record.

410) South 1/16 corner between Section 30, TSIN-R36W and Section 25, TSIN-R37W. Corner not established in original survey. Found no subsequent record.

## B. Description of corner evidence found and/or method applied in restoring or reestablishing corner:

(89) Original post and accessories not recovered. Found no monumentation or evidence of use at corner location. Determined corner to be lost and reestablished corner by single proportionate measure to the original record between adjacent recorded corners 2594.75° West and 2640.96' East.

(3) Established corner midway and on a straight line between recorded corners A9 and A10. Found no monumentation or evidence of use at this position.

(10) Established corner midway and on a straight line between recorded corners A10 and A11. Found a 1.5° dismeter iron page 4.1° Mest of the corner.

## C. Description of monument for corner and accessories established to perpetuate locating the position of the corner: (89) Flaced a 1\*x36\* iron pipe capped (3) Flaced a 1\*x36\* iron pipe capped (10) Flaced a 1\*x36\* iron pipe capped (89) Placed a 1"x36" iron pipe capped with a 4° die, cast aluminum MDMP

with a 4° dia, cast aluminum MGMR

tablet. Blazed and scribed the

Following new bearing trees:

12" Sugar \$54E 6.3" (1/45 MBT)

8° Sugar S13W 14.1' (1/45 NRT)

7" Sugar 8828 10.0" (1.45 HBT)

11" Sugar N26E 13.1" (1/45 NPT)

Squared a 3" Memlock North 1.3"

with a 4" dia, cast aluminum NDMR tablet. Blazed and scribed the

following bearing trees:

7" Sugar N38E 11.8" (1/16S BT)

9" Sugar SB7E 30.4" (1/165 BT) 6" Sugar S17E 4.8" (1/165 87)

12" Y. Birch SBIN 7.4' measured on slope 11/165 ET). Placed a 4° squared maple

sost South L'.

2.1

*33986* Surveyor's Michigan License No. \_\_

STEPHAN J. SZYSZKOSKI

£ 4 # 0 \$

tablet. Blazed and scribed the

11" Y. Birch 423E 4.8" (1/465 BT)

16" V. Birch STOS 14.2" (1/165 BT)

23" Hemlock | 952W 22.2" [1/165 BT]

24" Hemiock M29W 11.2" (1/165 BT)

Squared and scribed a 4" Hemlock S32E

following bearing trees: