LAND CORNER RECORDATION CERTIFICATE Filing Requirement of Act 74, Mich. P.A. 1970 as Amended

For corners in

Houghton (County)	Located In:	Corner Code #			
1. Public Land Survey	T 52N R 35W T 52N R 35W	E8 H9			
2. Property Controlling in Section	S T R S T R				
3. Miscellaneous Property in Sec.	S T R S T R	-	Register (of Deeds Stamp & File Num	nher
4. Lot No. , Res. 5. Private Claims	corded Plat		A B C	D E F G H I J	K L 1
above were in conformance with	n a field survey on H9 11/ 74, Michigan P.A. of 1970, the corner regulations and rules therefore as require	ed in the current manual of surve	y 5	5	112-
a Court of Law and /or that the	Department of the Interior, Bureau of Locorner points mentioned in lines 3, 4 and of Land Surveyors or by a Decree wered, found as expressed below:	f 5 above were in conformance wit	h 7 	20 21 22 2	3 24
NOTE: Not more than 2 corr on this certificate.	ners, all in the same town and range	, may be recorded	10 30 11 12 31	29 28 27 2 32 33 34 3	5 36

A. Description of original monument and accessories and/or subsequent restoration:

(E8) Quarter corner common to Sections 20-21. 1846 - Established by S.W.Higgins Deputy Surveyor. Set post. Sugar 14" N45W 30 links, Sugar 10" S53E 22 links. Notes of P.A. and M.C.Larsen: 1925 - B.T. Sugar S.E. Stdg - set post from same. 1963 - Billy D. Buckler RLS remonumented the corner at the position of a wood post set by M.C.Larsen, Hancock. Corner lies 40.40 chains South of Original Section corner and checks with stream and hill to North, 1/2 mile to South is short. Set 1"ID iron pipe with 4" aluminum cap. 11" Hard Maple N76W 41 links, 13" Hard Maple N54E 44 links.

(H9) Quarter corner common to Sections 22-27. 1846 - Established by S.W.Higgins, Deputy Surveyor. Set post. Sugar 8" N60E 20 links, Y.Birch 24" S62W 27 links. Notes of P.A. and M.C.Larsen state: "1963 - Found blaze and notch at base of rotted sugar and set cedar post in old blazed line - should be close". 1963 - Billy D. Buckler RLS remonumented the corner at the position of M.C.Larsen post. Set 1"Iron pipe with 4" aluminum cap. 6" Y.Birch N23W 23 links, 8" Y.Birch S57E 30 links.

B. Description of corner evidence found and/or method applied in restoring or reestablishing corner:

(E8) Found the 1963 monument in good condition and at record bearing and distance from the Sugar NBT NW, in good condition with overgrown blazes. The Sugar NBT NE was not found. Accepted the monument as a careful and faithful perpetuation of the position of the original corner.

(H9) Found the 1963 Buckler monument bent and with cap broken. The two Y.Birch NBTs are at record bearing and distance, and in good condition with overgrown blazes. Recovered the lower portion of the pipe monument plumb and placed a new monument at that position and in accord with the 1963 NBTs. Accepted the 1963 position as the best available evidence of the position of the original corner.

C. Description of monument for corner and accessories established to perpetuate locating the position of the corner:

(E8) Found 1"ID I.pipe with 4" alum. MI Dept. of Conservation cap. Set measuring nail with MDNR tag in the side of:
15" Sugar N72W 27.4' old blazes 1963 NBT
4" Sugar N34E 19.5' mrkd "1/4S NBT"
17" Maple S45E 19.6' do
15" Maple N32W 14.0' do
Sq'd cedar post adjacent.
Bearings are magnetic.

(H9) Set 1"IDx32" I.pipe with 4" alum. MDNR cap. Set measuring nail with MDNR tag in the side of: 11" Y.Birch S49E 19.8' old blazes 1963 NBT 9" Y.Birch N20W 15.4' do do 12" Sugar S83E 29.1' mrkd "1/4S NBT" 5" Hemlock S52W 30.05' do Set sq'd Cedar post adjacent. Bearings are magnetic.

Signed by	Stephen	Insplish.	Date	11/17/2009
- Surveyor's Mi	chigan License No.	33986		
	For the Michie	an Department of Natural Resource	es Office of Land and	Facilities

ce of Land and Facilities

FORM APPROVED BY MICHIGAN STATE BOARD

SZYSZKOSKI LAND SURVEYOR No.

TEPHAN J

(A N D Revised by 14, 1975

Rervised Oct., 1995

16352 16358