LAND CORNER RECORDATION CERTIFICATE Eiling Requirement of Act 74. Mich. P.A. 1970

For corners in Houghton		rung nedurement of Act 74, Mich.	
-	«County)	Localed In:	Corner Code ≠#
1.	Public Land Survey	T R T R	
		T R T R	
2.	Property Controlling In Section	S 15 T 52N A 35N S 15 T 52N A 35N	12

Register of Deeds Stamp & File Number

4. Let No. Recorded Plat

5. Private Claims

Property in Sec.

3. Miscellaneous

i, Stephan J. Szyszkoski , in a field survey on . July 25, 1994 do hereby certify that under requirements of P.A. 74, Michigan P.A. of 1970, the corner points mentioned in lines 1 and 2 above were in conformance with regulations and rules therefore as required in the current manual of survey instructions of the United States Department of the Interior, Bureau of Land Management or by a decree of a Court of Law and/or that the corner points mentioned in lines 3, 4 and 5 above were in conformance with the rules of the Michigan Board of Land Surveyors or by a Decree of a Court of Law; established, re-established, monumented, re-monumented, recovered, found as expressed below

NOTE: Not more than 4 corners, all in the same town and range, may be recorded on this certificate.

A. Description of original monument and accessories and/or subsequent restoration:

(8-Sec. 15) West 1/18 corner. Corner established and recorded in 1980 by Keith Sackett, RLS as follows: Set 1' E.D. x 38' iron pipe. 15' Sugar M81W 7.8', 9' Sugar M41E 25.8', 7' Hemlock S01W 16.8'. Found no subsequent record. (12-Sec. 15) South 1/16 corner, Section 15. Corner established and recorded in 1980 by Keith Sackett, RLS as follows: Set 1° 1.0. x 36' iron pipe. 6' Sugar M80E 17.0', 7' Sugar S70W 15.7', 9' Maple S27E 4.3'. Found no subsequent record.

B. Description of corner evidence found and/or method applied in restoring or reestablishing corner:

(8-Sec. 15) found the 1980 monument disturbed by heavy equipment. Removed the bent pipe and set a 1' 1.0.x 32' from pipe capped with a 4° dia. cast aluminum MDNR tablet at record bearing and distance from the two remaining 1980 BTs: the 15° Sugar, and the 7° Hemlock. Both are in good condition. The 9° Sugar MBT has been destroyed. Marked two new bearing trees as described below. (12-Sec. 15) Found the 1980 monument in good condition at record bearing and distance from two remaining 8Ts: the 8° Sugar, and the 7° Sugar, both in good condition. The S' Maple BT is missing. Left the monument in placed and marked two additional bearing trees as described below.

C. Description of monument for corner and accessories established to perpetuate locating the position of the corner:

(8) Set a 1' from pipe with MDNA cap. Blazed and scribed the following new bearing trees:

10" Maple \$70E 22.4" "1/16S BT" 7" Sugar #33E 40.9' "1/16S BT"

(12) Found 1" I.D. iron gips.

Blazed and scribed the following bearing

trees:

4' Sugar #10E 20,4' 4' Y. Birch Sole 18.0'

"1/16S BT" "1/165 BT" STEPHAN J SZYSZKOSKI LAND SURVEYOR

for the Michigan Department of Natural Resources - Forest Management Division.