LAND CORNER RECORDATION CERTIFICATE Filing Requirement of Act 74, Mich. P.A. 1970

Roughton Located In: Corner Code #	For corners in	Fili	ng Requirement of Act	74, Mich. P.A. 197	70							
1. Public Land Survey T 538R 348 E8 T R 1 S8 T R 2. Property Controlling S T R 3. Miscellaneous S T R 3. Miscellaneous S T R 4. Lot No. Recorded Plat 5. Private Claims E6 Jul 10 2005 1, Stephan J. Styrskoski , in a feel survey on												
1. Public Land Survey T 538 R 348 E5 T 539 R 348 E6 T 7 8 R 7 8 E6 T 8 E7 8 E		Located In:	Corner Code #	•								
2. Property Controlling S T R 3. Miscellaneous S T R Property in Sec. S T R 4. Lot No	• •	T_53NR	34N E6									
5. Private Claims E6 Jul 10 2003 E3 Jul 02 2003 I, Stephan J. Styszkośki, in a field survey on	in Section 3. Miscellaneous				Reg	jister (of Dee	ds Star	mp &	File	Num	ber
Stephan J. Szyskoski n a feld survey or requirements of P.A. 74, Mechigan P.A. of 1970, the corner points meritioned in lines 1 and 2 above were in conformance with regulations and nate burseline services are supported in the current manual of survey institutions of the United States Department of the interfet, Dursual of Land Management of the Activations of the United States Department of the interfet, Dursual of Land Management of the Activations of the United States Department of the interfet, Dursual of Land Management of the Activations of the United States Department of the Interfet Department Department of the Interfet Department Departme	4. Lot No, Recor	rded Plat		<u> </u>								
t. Stephan J. Stystkoski. In a feet survey on 20 do hereby state that under or registerented of PA. 74. Michigan P.A. of 1970 the corner points mentioned in lines 1 and 2 above were in conformance with regulations and raise therefore see against the termination of the lines 1 and 2 above were in conformance with requisitions and regulations are recovered, found as expressed below. A. Description of original monument and accessories and/or subsequent restoration: A. Description of original monument and accessories and/or subsequent restoration: (23) Corner cosson to Sections 4-5-8-9, 1846: Established by Sylvester Higgins: North between Sec. 8 & 980.00 Set post cor. sec. 4.8,9,9. Palsas 10 W/10/28, Relabolick 16 3252. Six Higgins records distances: 3.99 Sc. h. Most to 1/4 corner, 79.70 ch. North to township line, 33-945 East to 1/4 corner, and 40.00 South to 1/4 corner, 19)? Notes of P.A.Larson state 5 Cot. 1904 by P.A. Larson. 8.1. Resolut 16 5252. Set tron pipe in place of post. New 81 Healock 11 W/0w 28 links*. Distance of 2563* East to 174 corner, 1904 by P.A. Larson. 8.1. Resolution for the corner cossen to Sections 16-17. 1846: Established by Sylvester Higgins: North between 1641740.00 Set 1/4 Sec. post. Balsas 6 H60N 9, Y. Birch 12 345E 13. B. Description of corner evidence found and/or method applied in restoring or reestablishing corner: [E3] The original post and accessories were not recovered. Found a 1.5* ID iron pipe projecting 5* above ground. Distances to Mest and South to Found iron pipe sonuents are very sizal are significances East and South to Found iron pipe sonuents are very sizal are resorded. Found a 1.5* ID iron pipe projecting 5* above ground. Distances to Mest reasonably close to Larson's considering the rough terrain in this part of the township. Ny sur	5. Private Claims				1 A B	<u> </u>	D E	F G	H	i j	. к	- -
L Stephan J. Stystkoski in a fact sproyon or requirements of PA 7.4 Recipent PA of 1970, the come points mentioned in lone 1 and 2 above were in conformance with regulations and rules therefore as required in the current mental lens of the properties of the properties of the properties of the technique of the t						· 	<u> </u>	-	- 3-	<u></u>	!	- -
requirements of P.A. 74, Michigan P.A. of 1970, the corres ports meritioned in lines 1 and 2 above were in conformance with regulations and runs between services are queed in the current manual of survey instructions of the Conformance of the Intervity Survey of the Conformance of the Michigan P.A. of 1970, the Conformance of	ı Stephan J. Szyszkoski		-		- 1		 	1-1	+	\forall	+	\top
United Stries Department of the Interior, Dureau of Land Management or by a decree of a Court of Law and/or that the corner points mentioned in lines 3, 4 and 5 abow were in conformance with the uties of the Michigan Board of Land Surveyors or by a Decree of a Court of Law, established, re-established, monumented, re-established on This certificate. NOTE: Not more than 2 comers, all in the same town and range, may be recorded on this certificate. A. Description of original monument and accessories and/or subsequent restoration: (E3) Corner cosson to Sections 4-5-8-9, 1846: Established by Sylvester Riggins: North between Sac. 8 4 980.00 Set post cor., sac. 4,5,9,9,8 Balsas 10 W/00 28, Meslack 16 S255 235. Riggins records distances: 39,95 Ch. Nest to 1/4 corner, 79,70 ch. North to township line, 39,945 East to 1/4 corner, and 40,00 South to 1/4 corner, 1919; Hotes of P.A., Larson state "Set Oct. 1904 by P.A. Larson. 8.1. Resilock 16 "S256 22" stndg. Set iron pipe in place of post. New 81 Healock 11 H70W 28 links". Distance of 2563' East to F3 and 26/9.1' South to 24 are shown. (E5) Querter corner cosson to Sections 16-17. 1846: Established by Sylvester Riggins: North between 1641740.00 Set 1/4 Sec., post. Resilve Riggins: North Detween 1641740.00 Set 1/4 Sec., post. Resilve Riggins and South to found iron pipe sonusents are very sialiar in segnitude to indexed distances observed around sections 7, 8, and 17 in this corner for control. This record was prepared to provide public notice of the existence of this sonusent. I did not look for Larson's NOT apply found at the north end of a fence is 22.793 chains (3.99 chains longer than record). Neasured distances Seat and South to F3 and E4 are 2570.06' and 2647.99', both reasonably close to Larson's considering the rough terzain in this part of the township. Wy survey in Sacropades and South to F3 and E4 are 2570.06' and 2647.99', both reasonably close to Larson's considering the rough terzain in this part of the township. Wy survey in Sacropades and sout	requirements of P.A. 74, Michiga	In P.A. of 1970, the con	ner points mentioned in lines 1	and 2 above were in	- I I	\top	i	9-1-	-10 		1-+	-12-
that the corner points mentioned in lines 3, 4 and 5 above were in conformance with the rules of the Michigan Board of Land Surveyors of by a Decree of a Court of Law, established, re-established, monumented, necovered, found as expressed below. NOTE: Not more than 2 comers, all in the same town and range, may be recorded on this certificate. A. Description of original monument and accessories and/or subsequent restoration: (E3) forner cosson to Sections 4-5-8-9, 1846: Established by Sylvester Higgins: North between Sec. 8 4 980.00 Set post car. sec. 4,5,8,9. Balsan 10 N70W 28, Healock 16 S25£ 33. Higgins records distances: 39.95 ch. Nest to 1/4 corner, 79.70 ch. North to township line, 33,945 East to 1/4 corner, and 40.00 South to 1/4 corner. 1919: Notes of P.A.Larson state Set Oct. 1904 by P.A. Larson. 8.1. Healock 16 S25£ 22* strong be in place of post. New 81 Healock to 11 N70W 28 links*. Distance of S25£ Cast to 15 and 26/97.1* South to 64 are shean. (E6) Quarter corner cowson to Sections 16-17. 1846: Established by Sylvester Higgins: North between 1641740.00 Set 1/4 Sec. post. Balsan 6 N60M 9, Y. Birch 12 S45£ 13. B. Description of corner evidence found and/or method applied in restoring or reestablishing corner: (E3) The original post and accessories were not recovered. Found a 1.5* 10 iron pipe projecting 5* above ground. Distances to Nest township (both are about 1/2 chain longer than record). Distance North to a 1.25* iron pipe found at the north end of a fence is 82.793 chains (3.99 chains longer than record). Distance North to a 1.25* iron pipe found at the north end of a fence is 82.793 chains (3.99 chains longer than record). Measured distances East and South to F3 and E4 are 2570.06* and 26.1.99, both corner for control. This record was prepared to provide public notice of the existance of this sonueant. I did not look for Larson's NoT as his most were not in any spossession at the tias. (E6) The original post and accessories were not recovered. Reestablished the corner sidnay betwee	United States Department of the	Interior, Bureau of Land I	Management or by a decree of a	Court of Law and /or				16	15	Ħ		丁
NOTE: Not more than 2 comers, all in the same town and range, may be recorded on this certificate. A. Description of original monument and accessories and/or subsequent restoration: (3) Coner cosson to Sections 4-5-8-9, 1846: Established by Sylvester Higgins: North between Sec. 8 4 980.00 Set post cor. sec. 4,5,6,9. Balsas 10 W70/8 29, Realock 16 \$252 33. Higgins records distances: 39,95 ch. less to 1/4 corner, 79,70 ch. North to township line, 39,945 East to 1/4 corner, and 40.00 South to 1/4 corner, 1919: Notes of P.A.Larson state 5 Set oct. 1904 by P.A. Larson. 8.1. Realock 16 \$255 £22 * stndg. Set iron pipe in place of post. New 81 Realock 11 W70M 28 links*. Distance of 2563 £ast to 73 and 2279-1.* South to E4 are shown. (E5) Quester corner comen to Sections 16-17. 1846: Established by Sylvester Higgins: North between 16£1740.00 Set 1/4 Sec. post. Balsas 6 M60M 9, Y.Birch 12 S45E 13. B. Description of corner evidence found and/or method applied in restoring or reestablishing corner: (E3) The original post and accessories were not recovered. Found a 1.5 10 iron pipe projecting 5' above ground. Distances to Nest balsas 6 M60M 9, Y.Birch 12 S45E 13. B. Description of corner evidence found and/or method applied in restoring or reestablishing corner: (E3) The original post and accessories were not recovered. Found a 1.5 10 iron pipe projecting 5' above ground. Distances to Nest township (both are about 1/2 chain longer than record). Bistances Watch to 3 1.25 1 iron pipe projecting 5' above ground sections 7, 8, and 17 in this township (both are about 1/2 chain longer than record). Bistances Watch to 3 1.25 1 iron pipe found at the north end of a fence is 22.793 chains (3.09 chains longer than record). Measured distances beat of the township. My survey is considering the rough terrain in this part of the township. My survey is certion 8 did not require this corner for control. This record was prepared to provide public notice of the existance of this sonument. I did not look for Larson's M81 as his n	that the corner points mentioned	i in lines 3, 4 and 5 above	e were in conformance with the	rules of the Michigan	. ! !				-15			-19-
On this certificate. A. Description of original monument and accessories and/or subsequent restoration: (E3) Corner cosson to Sections 4-5-8-9. 1846: Established by Sylvester Higgins: North between Sec. 8 4 980.00 Set post cor. sec. 4,5,8,9. 8alsas 10 W70W 28, Healock 16 S25E 33. Higgins records distances: 39.95 ch. Hest to 1/4 corner, 79.70 ch. North to tomship line, 39.945 East to 1/4 corner, and 40.00 South to 1/4 corner. 1919: Notes of P.A.Larson state 5 Sci Oct. 1904 by P.A. Larson. 8.1. Healock 16 S25E 27 stndy. Set iron pipe in place of post. New 81 Healock 11 N70W 28 links. Distance of 2563 East to F3 and 2679.1' South to E4 are shown. (E6) Quarter corner common to Sections 16-17. 1846: Established by Sylvester Higgins: North between 16£1740.00 Set 1/4 Sec. post. Ralsas 6 M60W 9, Y. Sirch 12 S45E 13. B. Description of corner evidence found and/or method appked in restoring or reestablishing corner: (E3) The original post and accessories were not recovered. Found a 1.5' ID iron pipe projecting 5' above ground. Distances to Mest and South to found iron pipe nonuents are very sisilar in asgnitude to indexed distances observed around sections 7, 8, and 17 in this tomship (both are about 1/2 chain longer than record). Distances North to a 1.25' iron pipe found at the north end of a fence is 82.773 chains (3.09 chains longer than record). Measured distances East and South to F3 and E4 are 2570.06' and 2674.99', both reasonably close to Larson's considering the rough terrain in this part of the tomship. My survey in Section 8 did not require this corner for corner and in a ypossession at the time. (E6) The original post and accessories were not recovered. Reestablished the corner midway between Section corners 2656.79' north and south and in the reaalns of a very old and broken down N-5 fence line. The position for the corner is 15.02 feat Nest of a straight line between the section corners. C. Description of monument for corner and accessories established the corner midway between Section corners	recovered, found as expressed be	elow:	or Law, established, 18-establ	isneo, monumenteo,	8 19	;	20	21	 22 <u>-</u>		<u>.</u>	_2 4 _
A. Description of original monument and accessories and/or subsequent restoration: (E3) Corner cosson to Sections 4-5-8-9. 1846: Established by Sylvester Higgins: North between Sec. 8 4 980.00 Set post cor. sec. 4,5,8,9. Balsas 10 MYON 29, Healock 16 S255 33. Higgins records distances: 99,95 ch. Heat to 1/4 corner, 79.70 ch. North to township line, 39.945 east to 1/4 corner, and 40.00 Subt to 1/4 corner. 1919: Notes of P.A.Larson state 'Set Oct. 1994 by P.A. Larson. 8.1. Healock 16 S255 22' Standg. Set iron pipe in place of post. New 81 Healock 11 N7ON 28 links'. Distance of 2563' East to F3 and 2679.1' South to E4 are shown. (E6) Quarter corner common to Sections 16-17. 1846: Established by Sylvester Niggins: North between 16£1740.00 Set 1/4 Sec. post. Balsas 6 N6ON 9, Y.Birch 12 S45E 13. B. Description of corner evidence found and/or method applied in restoring or reestablishing corner: (E3) The original post and accessories were not recovered. Found a 1.5' ID iron pipe projecting 5' above ground. Distances to Mest and South to found iron pipe sonuents are very sisilar in aganitude to indexed distances observed around sections 7, 8, and 17 in this township (both are about 1/2 chain longer than record). Neasured distances cast and South to 73 and E4 are 250.6' and 2514.9', both reasonably close to Larson's considering the rough terrain in this part of the township. My survey in Section 8 did not require this corner for control. This record was prepared to provide public notice of the existance of this sonuent. I did not look for Larson's NST as his notes were not in my possession at the tise. (E6) The original post and accessories were not recovered. Resetablished the corner sidway between Section corners 2656.79' north and south and in the reasins of a very old and broken down M-5 fence line. The position for the corner is 15.02 feet Nest of a straight line between the section corners. C. Description of monument for corner and accessories established to perpetuate locating the position of the corn	NOTE: Not more than 2 con	ners, all in the same tow	wn and range, may be record	led	ل و			$\perp \perp$	4	\sqcup		\bot
A. Description of original monument and accessories and/or subsequent restoration: (E3) Corner caseon to Sections 4-5-8-9. 1846: Established by Sylvester Riggins: North between Sec. 8 & 980.00 Set post cor. sec. 4,5,8,9. Balsan 10 N70W 28, Healock 16 S25E 33. Higgins records distances: 39.95 ch. Nest to 1/4 corner, 79.70 ch. North to township line, 39.495 East to 1/4 corner, and 40.00 South to 1/4 corner. 1919: Notes of P.A.Larson state 5 sct Dct. 1904 by P.A. Larson. B.T. Healock 16 S25E 22' Stndg. Set iron pipe in place of post. New 81 Healock 11 N70W 28 links". Distance of 2563' East to F3 and 2679.1' South to E4 are shown. (E5) Quarter corner comeon to Sections 16-17. 1846: Established by Sylvester Higgins: North between 16£1740.00 Set 1/4 Sec. post. Ralsan 6 M60W 9, Y.Birch 12 S45E 13. B. Description of corner evidence found and/or method applied in restoring or reestablishing corner. (E3) The original post and accessories were not recovered. Found a 1.5' To Iron pipe projecting 5' above ground. Distances to Nest township (both are about 1/2 chain longer than record). Distance North to a 1.25' Iron pipe found at the north end of a fence is 82.793 chains (3.09 chains longer than record). Bustance North to a 1.25' Iron pipe found at the north end of a fence is 82.793 chains (3.09 chains longer than record). Measured distances a Set and South to F3 and £4 are 2570.06' and 2674.99', both reasonably class to Larson's considering the prough terrain in this part of the township. Ny survey in Section 8 did not require this corner for control. This record was prepared to provide public notice of the existance of this annuent. I did not look for Larson's N8I as his notes were not in any possession at the time. (E6) The original post and accessories were not recovered. Reestablished the corner midway between Section corners 2656.79' north and south and in the reasins of a very old and broken down N-S fence line. The position for the corner is 15.02 feat Nest of a straight line between the section corners.		•	3- 1,		10—30		9	28	_27	 -20	6	_25_
A. Description of original monument and accessories and/or subsequent restoration: (E3) Corner common to Sections 4-5-8-9. 1846: Established by Sylvester Riggins: Worth between Sec. 8 4 980.00 Set post cor. sec. 4,5,8,9. Balsas 10 N/OW 28, Realack 16 S25E 33. Higgins records distances: 39,95 ch. Nest to 1/4 corner, 79,70 ch. North to township ine, 39,945 East to 1/4 corner, and 40.00 South to 1/4 corner. 1919; Notes of P.A. Larson state. Sec Oct. 1904 by P.A. Larson. B.T. Nemlock 16* S25E 22' stndg. Set iron pipe in place of post. New BT Hemlock 11 N70W 28 links*. Distance of 2563' East to F3 and 2679.1.* South to E4 are shown. (E6) Quarter corner common to Sections 16-17. 1846: Established by Sylvester Riggins: North between 1681740.00 Set 1/4 Sec. post. Balsas 6 N60W 9, Y.8irch 12 S45E 13. B. Description of corner evidence found and/or method applied in restoring or reestablishing corner: (E3) The original post and accessories were not recovered. Found a 1.5* ID iron pipe projecting 5* above ground. Distances to Mest and South to Found iron pipe unnuents are very sizilar in asgnitude to indexed distances observed around sections 7, 8, and 17 in this township (both are about 1/2 chain longer than record). Weasured distances East and South to F3 and E4 are 2570.66* and 2674.99*, both reasonably close to Larson's considering the rough terrain in this part of the township. My survey in Section 8 did not require this corner for control. This record was prepared to provide public notice of the existence of this annuent. I did not look for Larson's NOT as his notes were not in my possession at the time. (E6) The original post and accessories were not recovered. Reestablished the corner midway between Section corners 2656.79* north and south and in the reasins of a very old and broken down N-S fence line. The position for the corner is 15.02 feet Nest of a straight line between the section corners. C. Description of monument for corner and accessories established to perpetuate locating the position of the					11	+		++	-	$\vdash \vdash$		-
AD Description of original monument and accessories and/or subsequent restoration: (E3) Corner common to Sections 4-5-8-9. 1846: Established by Sylvester Higgins: North between Sec. 8 & 980.00 Set post cor. sec. 4,5,8,9. 8alsaa 10 N70W 28, Realock is 6258 33. Higgins records distances: 39.95 ch. Mest to 1/4 corner, 79.70 ch. North to township line, 39.945 East to 1/4 corner, and 40.00 South to 1/4 corner. 1919: Notes of P.A.Larson state 'Set Oct. 1904 by P.A. Larson. B.T. Healock is '5252 22' stang. Set iron pipe in place of post. New 8T Healock 11 N70W 28 links'. Distance of 2563' East to F3 and 2679.1' South to E4 are shown. (E6) Quarter corner common to Sections 16-17. 1846: Established by Sylvester Higgins: North between 1681740.00 Set 1/4 Sec. post. Balsaa 6 N60W 9, Y.Birch 12 S45E 13. B. Description of corner evidence found and/or method applied in restoring or reestablishing corner: (E3) The original post and accessories were not recovered. Found a 1.5' ID iron pipe projecting 5' above ground. Distances to Mest and South to found iron pipe monuments are very sizilar in magnitude to indexed distances observed around sections 7, 8, and 17 in this township (both are about 1/2 chain longer than record). Distance North to a 1.25' iron pipe found at the north end of a fence is 82.793 chains (3.09 chains longer than record). Distance North to a 1.25' iron pipe found at the north end of a fence is 22.793 chains (3.09 chains longer than record). Distance North to a 1.25' iron pipe found at the north end of a fence is 82.793 chains (3.09 chains longer than record). Distance North to a 1.25' iron pipe found at the north end of a fence is 82.793 chains (3.09 chains longer than record). Distance North to a 1.25' iron pipe found at the north end of a fence is 8.21 and 10 miles are second to 1					12-31		2	3 3	_3 4	-3!	5	-36-
(E3) The original post and accessories were not recovered. Found a 1.5" ID iron pipe projecting 5" above ground. Distances to Mest and South to found iron pipe monuments are very similar in magnitude to indexed distances observed around sections 7, 8, and 17 in this township (both are about 1/2 chain longer than record). Distance Morth to a 1.25" iron pipe found at the north end of a fence is 82.793 chains (3.09 chains longer than record). Measured distances East and South to F3 and E4 are 2570.06' and 2674.99', both reasonably close to Larson's considering the rough terrain in this part of the township. My survey in Section 8 did not require this corner for control. This record was prepared to provide public notice of the existance of this monument. I did not look for Larson's NBT as his notes were not in my possession at the time. (E6) The original post and accessories were not recovered. Reestablished the corner midway between Section corners 2656.79' north and south and in the remains of a very old and broken down N-5 fence line. The position for the corner is 15.02 feet Nest of a straight line between the section corners. C. Description of monument for corner and accessories established to perpetuate locating the position of the corner is 15.02 feet Nest of a straight line between the section corners. C. Description of monument for corner and accessories established to perpetuate locating the position of the corner is 15.02 feet Nest of a straight line between the section corners. C. Description of monument for corner and accessories established to perpetuate locating the position of the corner is 15.02 feet Nest of a straight line. STEPHAN J. SZYSZKOSKI SZYSZKOSKI LAND SZYSZKOSKI LAND SURVEYOR 6" V.Birch S20M 9.5" "S8 MBT" 7" Cherry S05M 43.1 do SZYSZKOSKI LAND SURVEYOR A ND SUN LAND SURVEYOR A ND	(E6) Quarter corner common t	o Sections 16-17.	1846: Established by Sylv	vester Higgins: No	rth betw	een 16	&17	40.00 (Set 1	/4 Se	ec. po	ost.
and South to found iron pipe monuments are very similar in magnitude to indexed distances observed around sections 7, 8, and 17 in this township (both are about 1/2 chain longer than record). Distance Morth to a 1.25° iron pipe found at the north end of a fence is 82.793 chains (3.09 chains longer than record). Measured distances East and South to F3 and E4 are 2570.06' and 2674.99', both reasonably close to tarson's considering the rough terrain in this part of the township. My survey in Section 8 did not require this corner for control. This record was prepared to provide public notice of the existance of this monument. I did not look for Larson's NBT as his notes were not in my possession at the time. (E6) The original post and accessories were not recovered. Reestablished the corner midway between Section corners 2656.79' north and south and in the remains of a very old and broken down N-S fence line. The position for the corner is 15.02 feet Nest of a straight line between the section corners. C. Description of monument for corner and accessories established to perpetuate locating the position of the corner is 15.02 feet Nest of a straight line between the section corners. (E6) Set 1°IDX32° I.pipe with 4° alum. (E6) Set 1°IDX32° I.pipe with 4° alum. Scribed, and set measuring nails in: MDMR cap. Blazed, scribed, and set STEPHAN J. STEPHAN J. STEPHAN J. SZYSZKOSKI LAND SURVEYOR 6° Cherry SOSM 43.1 do 6° Cherry SOSM 43.1 do 6° Y.Birch S200 9.5' S8 NBT' 7° Cherry SOSM 43.1 do 6° Y.Birch S200 9.5' S8 NBT' 7° Cherry SOSM 43.1 do 6° Y.Birch S200 9.5' S8 NBT' 7° Cherry SOSM 43.1 do 80 8earings are magnetic. Distances are to with tag. Signed by Many A. Signed by Many A. Signed by Many A. Many A. Date Mall T. Date Mall T. SIGNED A. SIGNED A	B. Description of corner evi	dence found and/or n	nethod applied in restoring o	or reestablishing corr	ner:							
(E3) Found 1.5" dia. iron pipe. Blazed, scribed, and set measuring nails in: 6" Maple N16W 6.1' 9" Y.Birch S66E 9.1' 9" Y.Birch S66E 9.1' 9" Y.Birch S66E 9.1' 9" S9 NBT" 6" Cherry N74E 34.1' 6" Cherry S64E 32.3' 6" Y.Birch S20W 9.5' 58 NBT" 7" Cherry S05M 43.1 9" Ch	and South to found iron pipe township (both are about 1/2 82.793 chains (3.09 chains 1 reasonably close to tarson's corner for control. This re NBT as his notes were not in (E6) The original post and a south and in the remains of	e monuments are very chain longer than (conger than record). It considering the root was prepared to my possession at the coessories were not a very old and broke	similar in magnitude to i record). Distance North to Measured distances East ugh terrain in this part to o provide public notice of he time. recovered. Reestablished	indexed distances o to a 1.25" iron pip and South to F3 an of the township. M If the existance of the corner midway	bserved e found d E4 are y survey this mon between	around at the 2570. in Se ument. Secti	secti north 06' an ction I di on cor	ons 7, end o d 2674 8 did d not ners 2	8, a f a f .99', not r look	ence both equi- for I	7 in is he the the larso orth	this is in's and
Scribed, and set measuring nails in: 6" Maple M16M 6.1' "\$5 MBI" measuring nails in: 9" Y.Birch \$66E 9.1' "\$9 MBT" 6" Cherry N74E 34.1' "1/45 MBT" 6" Maple \$43E 17.2' do 6" Cherry \$64E 32.3' do SURVEYOR 6" Y.Birch \$20W 9.5' "\$8 MBT" 7" Cherry \$05M 43.1 do SURVEYOR 6" Y.Birch \$20W 9.5' "\$8 MBT" 7" Cherry \$05M 43.1 do Surveyor 33986 are magnetic. Distances are to nail Bearings are magnetic. Distances are to nail with tag. Signed by SIEPHAN J. SZYSZKOSKI LAND SURVEYOR No. 33986 The provided of the pro	C. Description of monument	for corner and acces	sories established to perpet	uate locating the pos	sition of t	he co	rej. e	FM	Marie			
	scribed, and set measuring of Maple M16M 6.1' 9" Y.Birch S66E 9.1' 6" Maple S43E 17.2' 6" Y.Birch S20W 9.5' Set sq'd Sugar post adjacent are magnetic. Distances are	nails in: "S5 MBT" "S9 MBT" do "S8 MBT" t. Bearings b to nail	MDNR cap. Blazed, scribed measuring nails in: 6" Cherry N74E 34.1' 6" Cherry S64E 32.3' 7" Cherry S05M 43.1 6" twin Cherries N25M 6.9 Bearings are magnetic. D	d, and set "1/4S MBT" do do do do			SZYS L SUR	SZKOS AND VEYO No.	iki R	00		· .
	7	had Szy	33986	Date	8/11/	103	· · · · ·			<u> </u>		