APPROVED LAND CORNER P.A. 345 OF 1990 **Houghton County**

SURVEY & REMONUMENTATION

LAND CORNER RECORDATION CERTIFICATE

JAN 0 9 1998

For corners in	Filing Requir	ement of Act 74, Mich. P.A.	1970
Houghton (County)	Located In:	Corner Code #	SECTION
Public Land Survey	T <u>55N R 32W</u> T R T R T R	E-1 HOUGH	Y FENILI 12/11/97 HTON COUNTY 11:24 3/ 456 PAU Fee: 9.00 Page 1 of 1
Property Controlling in Section	S T R S T R		
3 . Miscellaneous Property in Section	S T R S T R		Register of Deeds Stamp & File Number
4. Lot No, Re	corded Plat		
5. Private Claims			A B C D E F G H I J K L
Ronald S. Haata	ja	er , ₁₉ 97	2 - 6 - 5 - 4 - 3 - 2 - 1 - 3 - 4 - 7 - 8 - 9 - 10 - 11 - 12 - 1
do hereby certify that under requirilines 1 and 2 above were in commanual of survey instructions. Management or by a decree of a 5 above were in conformance with the conference of a Court of Law; estables expressed below:	irements of P.A. 74, Michigan P. nformance with regulations and of the United States Departn Court of Law and/or that the court the rules of the Michigan Brished, re-established, monumer	A of 1970, the comer points mention rules therefore as required in the currinent of the Interior, Bureau of Laborner points mentioned in lines 3, 4 a pard of Professional Surveyors or buted, re-monumented, recovered, fou	rent 7 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1
NOTE: Not more than 4 corn on this certificate.	ers, all in the same town and	I range, may be recorded	11

- A. Description of original monument and accessories and/or subsequent restoration:
 - E-1 North between Sections 4&5

79.90 Intersected South Boundary of Township 56N at corner of Sections 32&33 Sugar 10 S11E 25 Do 13 S40W 41

- B. Description of corner evidence found and/or method applied in restoring or reestablishing corner:
 - E-1 No evidence of original survey found. I found an old fence intersection at the Section corner location a measured distance of 2635.72 feet from the East 1/4 corner of Section 5.

I accepted the fence intersection as the Section corner and remonumented the corner by setting an $1\frac{1}{4}$ " Iron pipe at the fence Intersection and cemented in a brass remonumentation cap stamped:

T56-R32 S32| S33 S4 S5 T55-R32

C. Description of monument for corner and accessories established to perpetuate locating the position of the corner:

E-1 The 14" O.D. pipe was witnessed with brass survey tags PS39478 nailed to:

12" Maple N40°E 18.35' 6" Maple S83°E 30.82'

8 " W. Birch South 7.50'

2½" W. Pine West 21.60'

RONALD S. **HAATAJA PROFESSIONAL** SUNVEYOR No. 39478 OFESSION ESSIUM ESSIUM

November

Surveyor's Michigan License No.

URVEYORS, JAN. 28, 1871 REVISED MAY 14, 1975 **REVISED JAN., 1983**