SURVEY & REMONUMENTATION

REMONUMENTATION

LAND CORNER RECORDATION CERTIFICATE

Re-Man Lilier 1, Page 12

APR 2.7 1995 For Corners in	Filing Requirement of Act 74, Mic	ch. P.A. 1970
	ated in: Corner Code #	STATE OF NICHIGAN HURON COUNTY
. Public Land survey Sebewaing	T 15 N R 9 B T R T R	RECORDED 13 DEC 94 4:31 P.M.
Property Controlling S in Section S	T R	FRANCES L. HOLDWICK REGISTER OF DEEDS
. Miscellaneous S	TR	Register of Deeds Stamp & File Number
. Lot No, Ręcorded Pla Private Claims	ıt	A B C D E F G H J K L 2 5 5 5 4 3 2 1 1 3 3 2 1 1 1 1 1 1 1 1 1 1 1 1 1
James T. Meek , in a field surv	yey on <u>October</u> , 19 <u>94</u>	5 7 8 9 10 11 12 -
lines 1 and 2 above were in conformance with urrent manual of survey instructions of the Uni	A. 74, Michigan P.A. of 1970, the corner points mer h regulations and rules thereof as required in the ited States Department of the Interior, Bureau of La	ntioned 6 18 17 16 15 14 13 14 11 14 11 14 11 15

NOTE: Not more than 4 corners, all in the same town and range, may be recorded on this certificate.

above were in conformance with the rules of the Michigan Board of Land Surveyors or by a Decree of a Court of Law, established, re-established, monumented, re-monumented, recovered, found as

Description of original monument and accessories and/or subsequent restoration: Original survey, 1835, Harvey Parke, D.S.

H-13: South % Corner of Section 34

Post

Ironwood 67, N63°E, 7 links Sugar Maple 87,N60°W, 47 links

County Surveyor's Record: Axle Tuscola Survey L 486, Page 427: 1" axle shaft G-13: Corner of Sections 33 & 34 Lynn 30", N73°E, 28 links

Lynn 7", N73°W, 30 links

11

12

County Surveyors Record: Axle Tuscola Survey L 486, Pg 427: 1" axle shaft Huron Survey L 4, Pg 284: 1" axle shaft

Description of corner eyidence found and/or method applied in restoring or reestablishing corner:

H-13: South % Corner of Section 34,

Found 1%" iron bar, 2" below grd. 1' ± South of cl Huron Line Rd. Centerline of ditch (E-W), South, 25'±

Accepted as best available evidence of original corner position

G-13: Corner of Sections 33 & 34 Found %" iron bar in monument box At intersection of Huron Line Rd. (E-W) and Lange Rd. (N-S) from North

> Accepted as best available evidence of original corner position

C.	Description of monument for corner and	i accessories established	to perpet	uate locating	the position	1 of the corner:
	3. South W Corner of Saction 2			// // // // // // // // // // // // //		

1%" iron bar, 3" below grd.

from which:

Fence Post, N81°E, 144.50°

'Yield' Sign Post, S68°W, 110.65' Nail on NE side of PP, N84°W, 154.40'

%" iron(bent), N90°W, 119.62' G-13, %" iron, N89°57'18"W, 2633.77'

I-13, 1%" iron, \$89°50'26"E, 2635.91'

%" iron bar in monument box

from which:

Sign Post (Huron County), N13°E, 68.40'

East leg of direction sign, S12°E, 17.85' 'Stop' Sign post, N15°W, 68.85'

Nail on SE side of PP, N48°E, 46.17'

%" iron in monument box, N90°W, 123.38

H-13, 1%" iron, S89°57'18"E, 2633.77'

H-13, 1%" iron, N89°26'26"W, 2638,59"

Date _ Signed by Surveyor's Michigah License No. 39089 APPROVED AT PEER BOARD MEETING 12-10-94

MEEK SED LANDS

MAHHHHA