

HURON CO  
T18N, R12E

S 1/4 POST, SEC 9.

1" PIPE WITH 4" MARKER

18" BASSWOOD N50°E 22.50'

11" ASH S30°E 9.30'

6" ELM S5°W 24.30

FROM HWY PLANS (1932)

SE COR, SEC 9.

3' WOOD POST

6" JACK PINE N45°E 28.75'

12" NORWAY PINE N70°E 53.00'

12" NORWAY PINE S65°E 33.70'

NE. COR, NE. BRIDGE ABUT S10°W 45.20

FROM HWY PLANS (1932)

SE COR, SEC 8.

2" PIPE IN PLACE

SPIKE IN E. SIDE OF

8" TWIN MAPLE TREE, S25°E 59.1

SPIKE IN E. SIDE OF 4"

TWIN MAPLE TREE, S10°W 43.65'

W 1/4 COR, SEC 8.

CONC. MON. IN PLACE

NO WITNESSES

(CASE SURVEYING, 1976)

SW

~~SE~~ COR, SEC 8

CONC. MON IN PLACE

NO WITNESSES

(CASE SURVEYING, 1976)

S 1/8 POST BETWEEN SEC. 8+9

1" PIPE WITH 4" WOOD MARKER

14" W. OAK N85°W 49.80'

14" B. OAK S45°W 39.40'

12" B. OAK S10°E 7.00'

SEC COR 2-3-10-11

6" SQUARE FURNACE GRATE 4"

ABOVE GROUND.

FOUND 1" IRON PIPE N. SIDE GRATE

N48°W 24.08' 20" MAPLE SPIKE

S31°W 28.92' 12" CEDAR SPIKE

S58°E 5.27' 15" W PINE SPIKE