A01 – Dwight Twp. – T18N-R13E M01 Hume Twp. - T18N-R12E

> Re-Mon. Leher 2, Page 44 1999 REMONUMENTATION

LAND CORNER RECORDATION CERTIFICATE Filing Requirement of Act 74, Mich. P.A. 1970

For	Corners	in	PORT	AUSTIN	Township
-----	---------	----	------	--------	----------

Tor Comers in TORT ACCTIN	TOWNSHIP	į		
Huron (County)	Located in: Co	orner Code#	STATE OF MICHIGAN HURON COUNTY	
1. Public Land Survey	<u>T</u> 19N R 12E	M - 13	RECORDED	
	T R T R		30 DEC 99 2:17 P.H.	
Property Controlling S in Section S Miscellaneous S	T R T R R		FRANCES L. HOLDWICK REGISTER OF DEEDS	
3. Miscellaneous S Property in Sec. S	T R	viet ou 2008	Register of Deeds Stamp & File Number	
Lot No, Recorded Pl Private Claims	at	SECTION	1 A B C D E F G H J K W	

I, Russell L. Brown, in a field survey on Dec. 10, 1999 do hereby state that under requirements of P.A. 74, Michigan P.A. of 1970, the corner points mentioned in lines 1 and 2 above were in conformance with regulations and rules therefore as required in the current manual of survey instructions of the United States Department of the Interior, Bureau of Land Management or by a decree of a Court of Law and/or that the corner points mentioned in lines 3, 4, and 5 above were in conformance with the rules of the Michigan Board of Land Surveyors or by a Decree of a Court of Law; established, re-established, monumented, recovered, found as expressed below:

NOTE: Not more than 2 corners, all in the same town and range, may be recorded on this certificate.

A. Description of original monument and accessories and/or subsequent restoration: 1834 G.L.O. H. Parke D.S. Set Post Corner Tp. 18 and 17N Rs 12 and 13 East,

Sugar 16 S1E 15 1/2, Hemlock 18 N50 1/2W 22

County Surveyors Records - None

County Road Commission Records Cedar Post 10.6' due East of this point; Fence Post due South 45.40' Corner Fence Post N45°W 38.50'; Corner Fence Post N60°E 66.75'

L.C.R.C. - None

Recorded Surveys Sept. 29, 1972 Stewart G. Case P.S. 15399; Found remains of Cedar Post, placed 1" Pipe in Cedar Post and raised with 1/2" Steel Pin WITNESSES Spike S.E. Side of Corner Post N43°E 46.0'; Spike E. Side of power pole S25°E 37.0'; 1/2" Steel Pin N40°W 47.0' Unrecorded Surveys - None

B. Description of corner evidence found and/or method applied in restoring or reestablishing corner: No evidence of original corner or accessories found.

Found 1/2" Steel Stake in 1" Pipe and pieces of wood post

Accepted Found 1/2" Steel Stake in 1" Pipe as best evidence of original corner position.

C. Description of monument for corner and accessories established to perpetuate locating the position of the corner:

M-13, Southeast Corner Section 36, T19N-R12E

Found 1/2" Steel Stake in 1" Pipe Centerline Knoblock and Larned Roads

WITNESSES

W 10.55' to 3/4" Re-Rod

N35°W 59.16' to Spike in Southwesterly face of Power Pole

S15°W 36.94' to Spike in East face of Power Pole

S70°W 111.90' to P.K. Nail in North face Power Pole

S45°W 44.97' to Concrete Nail in West end 12" Plastic Drive Culvert

East 2739.92' to B-13, South 1/4 Corner Section 31, T19N-R13E

West 2635.83' to L-13, South 1/4 Corner Section 36, T19N-R12E

Dussell Signed by Surveyor's Michigan License No. 24588

Date

NOTE:

This corner common with

A-1, T18N-R13E

A-13, T19N-R13E

M-1, T18N-R12E

BROWN LAND SURVEYOR

OF MICH

24588

Peer group approved at meeting held 12 - 27 - 99. RLB