

## LIBER 3 PAGE 68 REMONUMENTATION

PECORDED 97906 MILLSDALE CO. MICH.

## LAND CORNER RECORDATION CERTIFICATE, Filing Requirement of Act 74, Mich. P.A. 1970 94 DEC 14 AM 11 58

,	HILLSDALE	Located I	n:	Corne	r Code ##	Ju	ay Va	mjandt EDS	
1.	Public Land Survey	T 5S	R <sup>1W</sup>	(D1) D3	D5	) R	EG. OF DE	EDS	
			В			·			
		т	R		SURV	EY&			
		т	. R		-REMONUM	ENTATIO	N		
2.	Property Controlling	S T							
	in Section	S T	R		~ a α <del>απ</del>	400F			
3.	Miscellaneous	' S T			APR 27	Redister o	of Deeds Sta	mp & File Number	
	Property in Sec.	S T	. R				· · · · · · · · · · · · · · · · · · ·		
4	Lot No,	Recorded Plat			COMMI	SSICIN			
	Private Claims					<u>^</u> _	BCDE	FGHIJKL	
					···	2	65	4	
		•		•	•	3		1 1 1 1 1 1	
						4	78	9 10 11 12	
۱,	John E. Maxson	, in a field survey or	n4!	lovember	, 19 <u>94</u>	, 5			
	hereby certify that under re	equirements of P.A. 74, N	dichigan P.		orner points mentione				
in lines 1 and 2 above were in conformance with regulations and rules therefore as required in the current manual of survey instructions of the United States Department of the Interior, Bureau of Land Management or by a decree of a Court of Law and/or that the corner points mentioned in lines 3, 4 and 5  above were in conformance with the rules of the Michigan Board of Land Surveyors or by a Decree of a								10-15-1-14-13	
								21-22-23-24	
Court of Law; established, re-established, monumented, re-monumented, recovered, found as							<del>1 1 1 1 1 1 1</del>		
exp	ressed below:					10	30-29-	28272625-	
NOTE: Not more than 4 corners, all in the same town and range, may be recorded							+	<del>}-}-</del> }-	
	on this certificate	<b>).</b>				12	3132	3334-35-36	
Α.	Description of original	I monument and acce	essories a	nd/or subsec	juent restoration:	13 🖳			
	D-1			D-3			D~5		
	GLO did not set this corner		GLO, 1824, 24"W.Oak, N81W. 34 1ks			GLO, 1	GLO, 1824, 20"W.Oak, S17E, 1.18 lks		
	Ringenberg Survey, 1978, L1, P595		7"W.Oak, 832E, 1.08 lks				6"W.Oak, \$87E, 60 1ks		
	1/2" Iron		Ringenberg Survey, 1978, L1, P596				LCRC, 1978, Ringenberg, L1, P5\$9 Steel Fence Post		
	vanGieson Survey, 1987, L558, P848		VanGieson Survey, 1987, L558, P848 3/4" Pipe			,			
В.	Description of corner evidence found and/or method applied in restoring or reestablishing corner: D-3 D-3 D-5								
	D-1		D-3						
	Found iron from Recorded Surveys and accepted as the best available evidence of the position of the original Corner			Found iron from Recorded Surveys			Found post from Ringenberg LCRC and accepted as the best available evidence of the position of the original Corner		
			with 1 1/2" pipe below and						
				accepted as the best available					
			evidence of the position of the original Corner			origin			
			47.5	<b></b>				•	
	·			•					
							•		
	December 1				<b>.</b>	·- ••			
).	Description of monume	ent for corner and ac	cessories	established	to perpetuate locati	ing the posit	ion of the co	rner:	
	D-1.		D~3			D-5	D~5		
	Reset 5/8 x 36 rebar W/cap		Reset 5/8 x 36 rebar w/cap			Reset	Reset 5/8 x 36 rebar w/cap		
		35"Walnut	N25E	44.40'	20"Hickory	N50W	20.37'	10"Maple	
		36"Walnut	S47W	50.22'	12"Oak	1165E	49.67'	16"Hickory	
		18"Walnut	Seow	43.82'	36"Tw.Oak	N62W	17.55'	10"Maple	
	NO5W 24.62'	12"Walnut	N48W	51.51'	24"Tw.Oak	\$34E	32.67	20"Maple	

Signed by .

West

137, 23'

Surveyor's Michigan License No.

Con .Mon. D-13, T48-R1W

27454

12 Danashan

Date

JOHN E. MAXSON SURVEYOR

No. ard of Land Surveyors

HIGHT SPATE-TOARD OF CAMB SURVEYORS JAN 28, 1977 BRISTO NOT 14, 1975 GEVISEO JAN., 1983