CCEPTED BY THE HILLSDALE COUNTY EURVEY PER GROUP AS THE OFFICIAL CORNER UNDER MICHIGAN PUBLIC ACT 345 PF 1960 AT MEETING HELD ON AL RINGENBERG, CO. REP

LIBER 3 PAGE 65

RECORDED HILLSDALE GO. MICH.

REMONUMENTATION LAND CORNER RECORDATION CERTIFICATE Filing Requirement of Act 74, Mich. P.A. 1970

'94 NOV 28 AM 11 09

10	r corners in			,
	Hillsdale	Located In:	Corner Code ##	and Dangonde
	(County)			Jury Vanzonds REG. OF DEEDS
1.	Public Land Survey	т <u>5S.</u> _R 4W. т R	SURVEY 8	ķ
		T R T R	REMONUMENT	ATION
2.	Property Controlling in Section	S T R S T R	<u>APR</u> 2 7 1995	· ·
3.	Miscellaneous	S R		Register of Deeds Stamp & File Number
	Property in Sec.	S T R	COMMISSI	Register of Deeds Stamp & File Number
		Recorded Plat		— ABCDEFGHIJKLM
5.	Private Claims			
	•			
1.	Frederick J. Cutcher	, in a field survey onJu	ıly 29	5
do	hereby certify that under re-	quirements of P.A. 74, Michigan P.A.	of 1970, the corner points mentioned	6 18 17 16 15 14 13
in	lines 1 and 2 above were i	in conformance with regulations and ructions of the United States Depart	d rules therefore as required in the	7
Gu Ma	rrent manual of survey man	a Court of Law and/or that the corne	r points mentioned in lines 3, 4 and 5	8 19 20 21 22 23 24
ab	ove were in conformance wi	ith the rules of the Michigan Board o	Land Surveyors or by a Decree of a	
	ourt of Law; established, pressed below:	re-established, monumented, re-n	nonumented, recovered, found as	10 30 29 28 27 26 25
NO	OTE: Not more than 4 o	corners, all in the same town an	nd range, may be recorded	11
	on this certificate			12 31 32 33 34 35 36

A. Description of original monument and accessories and/or subsequent restoration:

Survey #383, Dec. 1857, R. Bullard, Co. Surveyor: W. Oak 16" N. 4 1/20 E., 24 1/2 links N. bearing.

A.E. Ringenberg, Jan. 17, 1974: Found 3/8" iron rod. Set 1"x30" iron pipe over 3/8" iron rod.

M. Mahien, LCRC Liber 716, Page 629, Oct. 17, 1994: Found 1" iron pipe in the centerline of Adams Road in line with E/W fenceline.

B. Description of corner evidence found and/or method applied in restoring or reestablishing corner: Found 1"x30" iron pipe over 3/8" iron rod and replaced with 3/4"x36" County remonumentation bar and is accepted as a careful and faithful reestablishment of the position of the original corner.

C. Description of monument for corner and accessories established to perpetuate locating the position of the corner: 3/4"x36" County remonumentation bar

2' ± East of centerline of N/S gravel road, 6" below road surface, in line with tree row E/W

Nail & spotter with #28414 W. side 30" Maple S. 220 E., 49.30'

Nail & spotter with #28414 W. side 30" Maple S. 230 W., 56.95'

S.E. corner house foundation N. 450 W., 73.28'

Nail & spotter with #28414 S. side 30" Maple S. 880 E., 28.54"



Signed by	Frederick J.	atcher
orginos sy		24592

November 15, 1994

Date