1883

RECORDED 88327 FILLUALE CO. MICH.

IBER	3	PAGE	25		COMMISSION	REMONUMENTATION
------	---	------	----	--	------------	-----------------

## LAND CORNER RECORDATION CERTIFICATE '93 DEC 22 PM 2 22

	COMMENTALEOS, IDA HOLL GENTLE	•		 -	
iling	Requirement of Act 74, Mich. P.A. 1970		١.	_	

For corners in	1 mily riequ	incline (it of Aut 14, infolia 1.	11			
			Speaky Varyands			
<u> Hillsdale</u>	Located In:	Corner Code ##	Judy Vanjands			
(County)		-	REG. OF DEEDS			
1. Public Land Survey	T <u>7S.</u> R <u>4</u> W. T R	•				
•	T R T R					
Property Controlling     in Section	S T R S T R		•			
<ol><li>Miscellaneous Property in Sec.</li></ol>	S T R S T R	,	Register of Deeds Stamp & File Number			
	Recorded Plat		2 6 5 4 3 2 2 1 1 3 K L M			
do hereby certify that under red in lines 1 and 2 above were in	quirements of P.A. 74, Michigan P n conformance with regulations	ecember 22 , 19 93. A. of 1970, the corner points mention and rules therefore as required interment of the Interior, Bureau of	oned 6 18 17 16 15 14 13 nthe			
above were in conformance wi	th the rules of the Michigan Boar	rner points mentioned in lines 3, 4 a d of Land Surveyors or by a Decre e-monumented, recovered, foun	e of a			
NOTE: Not more than 4 con this certificate.	· ·	and range, may be recorded	11 12 31 32 33 34 35 36			

A. Description of original monument and accessories and/or subsequent restoration:

Stone, earthen & glass found in a survey by Geo. A. Mark, recorded in Book 9, Page 33, County Surveyors Records for Hillsdale Co. MI.

LCR Liber 1, Page 165, Jul. 20, 1972 by Robert E. Burris, Sr.: Found R.R. Spike 6" below surface of road.

Description of corner evidence found and/or method applied in restoring or reestablishing corner:

On this date I found a R.R. Spike below surface of pavement as found and used by Burris. Two of Burris' references remain.



C. Description of monument for corner and accessories established to perpetuate locating the position of the corner:

Replaced R.R. Spike with 3/4" x 36" steel rod with cap (County issue) in monument box.

2.3'± South of board fence to East

S.E. cor. brick garage N 84° W 89.35'

S.E. cor. brick house #720 N 60° W 91.65' S.W. cor. house S 33° E 92.30'

N.E. cor. house S 58° E 91.20'

And is accepted as a careful and faithful reestablishment of the position of the original corner.

Signed by Frederich J. artcher	Date December 22, 1993
. 24592	
Surveyor's Michigan License No.	FORM APPROVED BY MICHIGAN STATE BOARD OF LAND SURVEYORS, JAN. 28, 1971