## mer 1 7 1999

DEC = ( 1990	·	
	LAND CORNER RECORDATION CERTIF	
For corners in	Filing Requirement of Act 74, Mich. P.A	. 1970 
INGHAM (County)	Located in: Corner Code # WHEATFIELD TOWNSHIP	
1. Public Land Survey	T_3N_R_1E	

Liber

333 9 Page

-	_		_	-
		15		
	na/	<b>X47</b>	122	
09/18	/1:	//8	13:	20:29
REGI	STI	:R 0	FÐ	EEDS

FII FN

& File Number

T R	Paula Johnson INGHAM COUNTY, MI
3. Miscellaneous       S T R	Register of Deeds Stamp & F
4. Lot No, Recorded Plat	A B C D E F G H I  2 - 6 - 5 - 4 - 3 - 3
I, RON HELSEL, , in a field survey on JULY 1, , , 19 98 do hereby certify that under requirements of P.A. 74, Michigan P.A. of 1970, the corner points mentioned in lines 1 and 2 above were in conformance with regulations and rules therefore as required in the current manual of survey instructions of the United States Department of the Interior, Bureau of Land Management or by a decree of a Court of Law and for that the corner points	4 7 8 9 10 5 6 18 17 16 15 7

NOTE: Not more that 4 corners, all in the same town and range, may be recorded on this certificate.

re-monumented, recovered, found as expressed below:

Description of original monument and accessories and/or subsequent restoration: ORIGINAL MONUMENT: POST SET BY JOSEPH WAMPLER, U.S. DEPUTY SURVEYOR, MAR., 1826. WITNESSED AS: BEECH 18", S70W, 2 LINKS; BEECH, 17", S84E, 19 LINKS 1) A MARGIN NOTE IN THE INGHAM COUNTY COPY OF THE G.L.O. NOTES CALLS FOR A STONE. NO DATE GIVEN AND INITIALED ILLEGIBLY.

mentioned in lines 3, 4 and 5 above were in conformance with the rules of the Michigan Board of Land Surveyors or by a Decree of a Court of Law; established, re-established, monumented,

I DID NOT FIND ANY RECORDS PUBLIC OR PRIVATE THAT CALLS FOR THIS CORNER.

10 13

B. Description of corner evidence found and/or method applied in restoring or reestablishing corner: FOUND A 3-WAY FENCE TO THE NORTH, SOUTH AND EAST WITH A 2" BY 2" ANGLE IRON ANCHOR POST ENCASED IN A 5 FOOT DIAMETER CONCRETE BASE. FOUND A PLOW POINT AND A 15" X 8 " DIAMETER POINTED BLUE STONE LYING ON THE GROUND NEXT TO THE ANCHOR POST, ALONG WITH SEVERAL SMALLER STONES POSITIONED IN A CIRCLE AROUND IT. ALSO FOUND THE ROTTED REMAINS OF AN OLD WOOD ANCHOR POST AND A PIECE OF OXIDIZED PIPE ABOUT 4" LONG. I BELIEVE THAT THE STONE, SECTION OF PIPE, AND PLOW POINT WAS REMOVED WHEN THE ANGLE IRON ANCHOR POST WAS SET. ACCEPTED THE POSITION OF THE NORTHWEST CORNER OF THE STEEL POST AS FAITHFUL PERPETUATION OF AN UNRECORDED COUNTY SURVEYOR MARKER. SET A 3/4" FORM PIN AND DISK STAMPED P.A. 345, P.S. 18994, 2.84 FEET WEST OF THE ANCHOR POST TO CONFORM WITH P.A. 74.

Description of monument for corner and accessories established to perpetuate locating the position of the corner: NORTHWEST CORNER OF A 2" x 2" STEEL ANCHOR POST AT INTERSECTION OF FENCES TO EAST, NORTH, AND SOUTH 3/4" BY 24" FORM PIN AND ALUMINUM DISK, WEST, 2.84 FEET

SET NAIL & TAG #18994 ON N/SIDE OF 10" MAPLE, AZ. 87°, 57.5 FEET
SET NAIL & TAG #18994 ON N/SIDE OF TWIN 18" OAK, AZ. 95°, 9.35 FEET
SET NAIL & TAG #18994 ON E/SIDE OF 6" ELM, AZ.04° 6.40 FEET
SET NAIL & TAG #18994 ON E/SIDE OF 4" THORN APPLE, AZ. 339°, 12.95 FEET

OF MICHIE RON HELSEL LAND SURVEYOR No STERED 18994 LAND

Signed by \( \) Surveyor's Michigan License No. 18994

Date

FORM APPROVED BY MICHIGAN STATE BOARD OF LAND SURVEYORS, JAN. 28, 1971