

1993

REMONUMENTATION CORNER

COMMISSION

LAND CORNER RECORDATION CERTIFICATE

For corners in	Filing Require	ement of Act 74, Mich. P.A	1970	REGIS	∞	STATI STATI
Ionia (County)	Located In:	Corner Code ##		TER OF	SEP 21	
1. Public Land Survey		<u>C-1</u>		O. Struck	P3:23	N RECORD
 Property Controlling in Section Miscellaneous Property in Sec. 	S T R S T R S T R S T R		Register of D	eeds Stamp 8	k File Nu	ımber
f. Marinus Mulder do hereby certify that under red in lines 1 and 2 above were in current manual of survey instru Management or by a decree of a above were in conformance with Court of Law; established, rexpressed below: NOTE: Not more than 4 co	in a field survey onJule Jule guirements of P.A. 74, Michigan P.A. on conformance with regulations and suctions of the United States Departs a Court of Law and/or that the corner the the rules of the Michigan Board of re-established, monumented, re-moreoners, all in the same town and or the corners, all in the same town and the corners, all in the same town and the corners, all in the same town and the corners.	y 30 , 19 93 of 1970, the corner points mention of rules therefore as required in to ment of the Interior, Bureau of La r points mentioned in lines 3, 4 and f Land Surveyors or by a Decree of conumented, recovered, found	2 6 3 4 7 7 5 1 1 8 1 1 9 1 1 9 1 9 1 9 1 9 1 9 1 9 1	C D E F C	3 H 1	J K L M
S. Deptuty Surveyor ost witnessed by:	monument and accessories and r, Orange Risdon set to (1) 12" Elm S 56° E 37	his closing corner Marianks (2) 12" Oak	S 85° W 109	links		

- U.
- D.C. Crawford former Ionia County Surveyor perpetuated this corner in 1891 whose with found as marginal notes on a copy of the County Surveyor's G.L.O. notes. He stated: (1) 14" White Oak N 60° W 152 links (2) 10" Elm S 37° E $68\frac{1}{2}$ links.
- B. Description of corner evidence found and/or method applied in restoring or reestablishing corner:

Found 1/2" rod 8" below bituminous road surface. excavated further and found boat spike. Excavated deeper hoping to find clay cyliner but did not find. This area is located in a crossroad.

Although the Road Commission has no witnesses, more than likely they set the boat spike

during road construction. Crawford's witness trees are gone. The position fits the government jog distance within reason from the standard Southeast corner of Section 31, T8N-R5W. This is accepted as the best available evidence of the position of the original corner.

C. Description of monument for corner and accessories established to perpetuate locating the position of the corner:

Removed 1/2" rod & boat spike and set 30" long fiberglass monument with a 4" diameter brass cap stating "Ionia County Survey Monument" with the following witnesses:

Nail & tag East side 8" Elm S 17° E 54.53' Nail & tag North side 4" Hickory S 67° E 106.31'

S.W. Corner 8" x 4' Concrete box culvert N 75° E 64.77'

Nail & tag North side power pole N 65° W 123.88'

LINES 003 PAGE 21

Signed by Mand Mulde	Date August 30, 1993
Surrayor's Michigan License No. 25863	