		CORDATION CERTIFICAT	
	Filing Requirement of Act	74, Mich. P.A. 1970 as Ame	nded
For corners in			
Iron	Located In:	Comes Code #	
(County)	_ Localed III.	Corner Code #	
1. Public Land Survey	T R T R		
2. Property Controlling in Section	S 4 T 41N R 31W S T R S 3 T 41N R 31W	6 (GCDB 360660)	
3. Miscellaneous Property in Sec.	S 3 T 41N R 31W S T R R	H2 (GCDB 440640)	
4. Lot No. Red	corded Plat		Register of Deeds Stamp & File Number
5. Private Claims  1, Stephan J. Szyszkoski , ir that under requirements of P.A. above were in conformance with a significant conformance with a significan	n a field survey on 01/74, Michigan P.A. of 1970, the corner pregulations and rules therefore as require	21/16 do hereby state	1 B C D E F G H I J K L 2 6 5 4 9 10 11 12 12 15
a Court of Law and /or that the c	Department of the Interior, Bureau of La corner points mentioned in lines 3, 4 and d of Land Surveyors or by a Decree	nd Management or by a decree of 6 5 above were in conformance with 7 of a Court of Law; established, g	7 8 —19 — 20 — 21 — 22 — 23 — 24 — 9
NOTE: Not more than 2 corn on this certificate.	ers, all in the same town and range,	may be recorded	2 31 32 33 34 35 36
A. Description of original m	onument and accessories and/or s	ubsequent restoration:	3
	1/16 corner, Section 4. N		ed.
(H2) Center of Section Rec. in 1979 Liber 1 : Birch 8" N35°E 15.2'.	rage 5/6. Set I" iron bip	r E.Kazianka RLS at the se with plastic cap. M	e intersection of 1/4 lines. Maple 9" N80°W 22.1', Yellow
B. Description of corner evid	dence found and/or method applic	ed in restoring or reestablishir	ng comer:

- (6-Sec. 6) Established the position for the corner at the intersection of straight lines connecting opposite 1/16 corners. Of those, only 1/16 corner #9 is currently monumented.
- (H2) Found the 1978 monument in good condition but with deteriorated plastic cap. The position conforms to monumented G2 and 1/16 #8 to the west and to 1/4 corners H1 and H3. The 1978 witnesses are at record bearing and distance. The Y.Birch is in good condition, the Maple is a stump. I accept the position of the monument as a careful and faithful establishment of the position of the
- C. Description of monument for corner and accessories established to perpetuate locating the position of the corner:

(6) Set 1"IDx28" I.pipe with 2" alum. MDNR cap. Set measuring nail with MDNR tag in the side of: "Spruce N55°E 27.9' mrkd "1/16S BT"  O" Spruce S74°E 17.9' do  "Balsam S83°W 7.6' do  O" Spruce N42°W 12.85' do  Set sq'd spruce post adjacent. "= 7908204.856 N= 133934.087	(H2) Found 1"ID Iron pipe of record. Splastic cap #33986 in the top of same. Set measuring nail with MDNR tag in the 9" Y.Birch N38°E 15.25' old blazes (14" Maple N73°E 20.35' mrkd "C14" Sugar S33°E 11.5' 5" Sugar S79°W 12.6' E= 7909406.386 N= 133511.430	side of:
---	--	----------

Bearings are magnetic. Coordinates are MCS83 in meters, NAD83(2011) Epoch 2010.00 de Coord. Ref.=NGS PID RL0240: N= 145070.966 m. E= 7907633.632 m. OF MICH

02/25/2016

Surveyor's Michigan License No.

For the Michigan Department of Natural Resources, Forest Resources Division

<del>YSZKOSKI</del> LAND SURVEYOR

levised Oct., 1995

STEPHAN J

FORM APPROVED BY MICHIGAN STATE BOARD O