			ER RECOR									
For corners in	r.ii	ing Kequii	rement of A	Ct /4, Mici	h. P.A. 19	70						
Iron	I acated Inc	0										
(County)	Located In:	Cor	ner Code#									
1. Public Land Survey	TF TF	₹ <u>32</u> ₹ ₹										
Property Controlling in Section Miscellaneous Property in Sec.	S 29 T 42NF		16			Re	egister	of De	eds St	amp &	File N	lumber
4. Lot No, Record	ded Plat					A	B C	D E	F G	. н	I J	K L I
						2 <u> </u>	6-	- 5	- 4	<u> </u>	2-	- - -
Otaskas 7 Oswaskaski		Jul 30				3 —	╁╌╁╴	+	-		├	
I, Stephan J. Szyszkoski, in a field survey on, 20 do hereby state that under requirements of P.A. 74, Michigan P.A. of 1970, the corner points mentioned in lines 1 and 2 above were in								- 🛊	_ {-	<u>1</u> 0	 -1¦1-	12-
conformance with regulations and rules therefore as required in the current manual of survey instructions of the United States Department of the Interior, Bureau of Land Management or by a decree of a Court of Law and /or								++			\vdash	
United States Department of the li that the corner points mentioned	nterior, Bureau of Land in lines 3, 4 and 5 abo	l Management ve were in con	t or by a decree	of a Court of the rules of the	aw and /or e Michigan	6	' 8 	-1 7	-16	-15	14-	13
Board of Land Surveyors or by recovered, found as expressed be	a Decree of a Court	of Law; est	ablished, re-es	stablished, mo	numented,	7	 				\vdash	
recovered, found as expressed be	iow.		1			81	وَ.	-20	-21-	<u>2^2</u>	23-	24-
NOTE: Not more than 2 corners, all in the same town and range, may be recorded on this certificate.						9	-					
on this certificate.							30	-29 	28 	27 	1—26- 	25-
						11		32	_33_	- 34	35	36
						13						
Set 1"IDx36" I.pipe with 4" a 79.2 links. (16-Sec. 29) East 1/16 corne Quarter corners. Set 1"IDx3a	r between Sections	29-32. Est	tablished in	1971 by A.O).Enger, RL	S, midw	ay and	on li	ne bet	ween Se		
B. Description of corner evid		• •		•	•							
(C9) Found the 1970 monument good condition with scribing was not recovered. Accepted (16-Sec. 29) Found the 1971 record bearing and distance. position between Section and	(S30 NBT) and noto the corner position monument as describ The power pole wi	ch visible. on as found bed but wit itness has b	The W.Pine h a broken a been removed	SW is in go luminum cap. . The monu	ood conditi . Found th ment is 0.6	on with e R.Oak	overs	irown l In good	olazes. I condi	The tion a	08T st t subs	tump SE stantial
C. Description of monument	for corner and acce	ssories esta	blished to pe	rpetuate loca	iting the pos	sition of	the co	rner:	15. A.			
5" W.Pine S45E 34.1' "S	Blazed, ails in: rown blazes 20 NBT" 29 NBT" 30 NBT" adjacent.	cap, broke measuring 14" Oak S3 8" W.Pine 4" W.Pine Set nail/t Placed a s	BE 54.7' ov S60E 63.4' S38W 27.2' ag in Power q'd cedar po re magnetic.	scribed, and ergrown bla: "1/16S do pole N71W 80 st adjacent	i set res. BT" 6.3'	** 1100	SZ	YSZK LAN JRVE No. 3398	OSKI D YOR	100		
Signed by Stephen	- Szygh	el'			Date	3/6/	03					
Surveyor's Michigan License	No	33986										