## LAND CORNER RECORDATION CERTIFICATE

| For corners in  | Filing Requireme   | nt of Act 74, Mich. P.A. 197   | 0 as Amended   |  |
|---|--|--|--|--|
|   |  |  |  |  |
| [County)  | Located In:  | Corner Code #  |  |  |
| 1. Public Land Survey   | T <u>42N</u> R <u>35N</u><br>T <u>42N</u> R <u>35N</u><br>T R  |  |  |  |
| 2. Property Controlling in Section 3. Miscellaneous Property in Sec   | S T R<br>S T R<br>S T R<br>S T R   |  | Registe<br>Number  | of Deeds Stamp & File  |
| Property in Sec.  | 2  | THE LOCAL COMPLETE OF THE COMPLETE COMP | ARCDE  | FGHIJKLM   |
| 4. Lot No, Recor  | ded Plat   |  | ֓֓֓֓֓֓֓֓֓֓֓֓֓֓֓֓֓֓֓֓֓֓֓֓֓֓֓֓֓֓֓֓֓֓֓֓֓  |  |
| 5. Private Claims   |  |  | 2 - 6 - 5 -  | -1-3-1-2-1-1-1   |
|   | Sep 21   | 2006   | 4 - 7 - 8  | 9-10-11-12   |
| that under requirements of P.A. 7<br>above were in conformance with<br>survey instructions of the United<br>decree of a Court of Law and /o                         | 74, Michigan P.A. of 1970, the or<br>regulations and rules therefor<br>States Department of the Interior<br>that the corner points mention<br>e Michigan Board of Land Surve | , 20 do hereby s<br>corner points mentioned in lines 1 a<br>e as required in the current manu-<br>or, Bureau of Land Management or<br>oned in lines 3, 4 and 5 above wer<br>eyors or by a Decree of a Court of I<br>expressed below:   | nd 2<br>al of 6<br>by a 7  | 16151413<br>21222324   |
| NOTE: Not more than 2 co  | rners, all in the same towr  | and range, may be recorded   | 10 30 29   | 28 27 26 25  |
| on this certificate.  |  | , aa., aa., a.a.   | 11   |  |
| A. Description of original mo   | nument and accessories and   | d/or subsequent restoration:   | 12 31 32   | 33-1-36-35-1-36-1  |
| (I12) The original post and ac<br>record distance south of Secti<br>trail. I produced the Section<br>corner at said intersection.<br>(I10) The original post and ac | cessories were not recovere<br>on corner III (GLO-2640', I<br>line between Sections 26 a<br>I also found remains of and<br>cessories were not recovere                       | d applied in restoring or reestabled. At the corner position, I deas = 2640.95'). This fence and 27 and intersected it with other old fence on the section ed. Found no acceptable evide   | found an old E-W fenceruns east along the southis fence, reestablishing to the north, because of the position of | uth side of a meandering<br>shing the position for the<br>tween corners III and II2.<br>the original corner on the |
| ground. Reestablished the cor<br>south. There exists an old fe<br>the corner monumented.  | ner by single proportionatonce and field line which ro   | e measurement to the original and sins from the corner III location  | record between Section<br>on to a point which is   | corners 2041.07 north and 193' south and 69' east of   |
| 9" Spruce S09M 45.6'<br>10" Spruce N39M 28.9'   | 4" alum. (I10) Set in: MDNR cap. 1/4S MBT" 3" Tamarad do 5" Tamarad do 3" Tamarad do 3" Tamarad Searings Set sq'd d  | established to perpetuate locating 1"IDx60" I.pipe with 4" alum.  Set measuring nails in:  ck NO3E 14.2' mrkd "1/4S NBT"  ck S66E 23.4' do  ck S18E 15.0' do  ck S76M 9.1' do  cedar post adjacent. Bearings  tic. Distances are to nail   | STEPHA<br>SZYSZK<br>LAN<br>SURVE<br>No.<br>3398  | OSKI<br>D<br>YOR   |
| Signed by Steph   | Sappled.   | 986  | Date   | 10/10/06   |
| Surveyor's Michigan License N   | <u> </u>   |  | o of Land and Fastists   |  |
|   | ror the Michigan Departm   | ent of Natural Resources, Offic  |  | S<br>OF PROFESSIONAL SURVEYORS, JAN. 28, 1971<br>Revised May 14, 1975<br>Revised Jan., 1983<br>Rervised Oct., 1995 |