## LAND CORNER RECORDATION CERTIFICATE Filing Requirement of Act 74, Mich. P.A. 1970

For corners in		rining troquirement of Not 74, when h	
	Iren	Located In:	Corner Code =##
	(County)		
1.	Public Land Survey	T 43N R 31N T 43N R 31N	<u> </u>
		T R	_=!
		T R	
2.	Property Controlling	S T R	

Register of Deeds Stamp & File Number

4. Lot No. \_\_\_\_\_, Recorded Plat \_\_\_\_\_\_

5. Private Claims \_

Property in Sec.

in Section
Miscellaneous

NOTE: Not more than 4 corners, all in the same town and range, may be recorded on this certificate.

A. Description of original monument and accessories and/or subsequent restoration:

(M1) Corner common to Townships 43-44K, Ranges 30-31M. Corner previously recorded by Meal Sperhake in 1983 as restored by proportionate measurement. Corner was monumented by a 1°1.0.x38° iron pipe with aluminum Kimberly-Clark cap and the following MBTs:
Balsam 5 S58M 82 links, W. Birch 5 S30E 84 links, Black Ash 12 N78E 175 links, Black Ash 4 M40M 87 links. Corner also recorded in 1977 by Thomas P. O'Brien who found Sperhake's monument. Also recorded in 1988 by Kinth Sackett who found the Sperhake monument.

(M3) Saction corner common to Sections 1-12, T43M-R31M and Sactions 8-7 T43M-R30M. Corner previously recorded by Meal Sperhake in 1982 L.2(vol.8)-P.247 as monumented by a 1°x36° iron pipe with aluminum Kimberly-Clark cap and the following M8Ts: B. Ash 11 M33W 37 links, Spruce 7 S51W 32 links. Corner subsequently recorded by Thomas P. O'Brien in 1977 as: Found pipe with Kimberly-Clark cap, 12° Twin Spruce S47W 20.8°, 12° Maple M34W 24.0°.

B. Description of corner evidence found and/or method applied in restoring or reestablishing corner:

(M1) Found the 1963 monument slightly disturbed by road construction, Paning southeasterly. Forced monument into upright position so that it was in accord with the two remaining 1953 MBTs: Balsam 5 S56W 62 links, now a 9° standing anag, and Black Ash 4 M40W 87 links, now 6° in good condition. The other two 1983 MBTs are gone - the birch dead and down, the ash destroyed by road construction. Also checked the 1988 MBTs as shown below.

(M3) Found and accepted a 1° pipe with K-C cap as described above, in good condition. Remeasured to the 1982 NBTs (The spruce now a 14° stump with measuring notch visible) and marked 3 new NBTs as described below. Did not identify the Maple NBT by O'Brien.

C. Description of monument for corner and accessories established to perpetuate locating the position of the corner;

(MI) Found 1° pipe with aluminum Kimberly-Clark cap. Remeasured to the previously established 1988 NBTs: 7° balsam NBIW 28.1' 12° Maple 803W 40.8' 4° Ash 876E 25.5' (M3) Found 1° iron pipe with aluminum Kimberly Clark cap.

12° 8. Ash M31W 23.7' scribing visible 14° Spruce stump 852W 20.8' Blazed and scribed the following new bearing trees:

10° Spruce M20E 29.8' "88 MBT" 5° Spruce 847E 28.4' "\$7 MBT" 12° Balsam 860W 45.8' "\$12 MBT" A 6° black ash with champion poster bears, M60W 8.9'

STEPHAN J.
SZYSZKOSKI
LAND
SURVEYOR
No.
33986

6-16-94

Surveyor's Michigan License No. 33986

FORM APPROVED BY MICHIGAN STATE BOARD OF LAND SURVEYORS, JAN 28, 1971 REVISEO MAY 14, 1975 BEYISEO JAN , 1983