LAND CORNER RECORDATION CERTIFICATE

Filing Requirement of Act 74, Mich. P.A. 1970

For corners in			•	
	(Caunly)	Localed In:	Corner Code ≠#	
1.	Public Land Survey	T 43H R 32W	£6	
		T 43N R 32W	,C6	
		T R		
		T R		
2.	Property Controlling	S T R		
	in Section	S T R		
3.	Miscellaneous	S T R		
	Property in Sec.	S T R		

Register of Deeds Stamp & File Number

__ , Recorded Plat _____

5. Private Claims

C6 June 08, 1994

I, Stephan J. Szyszkoski . in a field survey on 55 March 30 1934 do hereby certify that under requirements of P.A. 74, Michigan P.A. of 1970, the corner points mentioned in lines 1 and 2 above were in conformance with regulations and rules therefore as required in the current manual of survey instructions of the United States Department of the Interior, Bureau of Land Management or by a decree of a Court of Law and/or that the corner points mentioned in lines 3, 4 and 5 above were in conformance with the rules of the Michigan Board of Land Surveyors or by a Decree of a Court of Law, established, re-established, monumented, re-monumented, recovered, found as expressed below:

NOTE: Not more than 4 corners, all in the same town and range, may be recorded on this certificate.

A. Description of original monument and accessories and/or subsequent restoration;

(E6) Quarter corner common to Sections 16-17. Corner established in 1849 by 2.8. Searles as follows: Set spruce post, Y. Pine 12 S236 7, Y. Pine 12 NTOW 17. Original line notes show swamp edge calls 5.00 chains south and 3.00 chains north of this corner. Found no subsequent record.

(C6) Quarter common to Sections #8-17. Corner established in 1849 by 2.8. Searles as follows: Set spruce post, W. Birch 8 5655 20, W. Birch 6 N25W 22. Corner shown on surveys by Gary L. Pisoni, PS dated 4-04-92 and 4-07-92, being surveys within Govt Lots 3 & 4. Found no other record.

B. Description of corner evidence found and/or method applied in restoring or reestablishing corner.

[E6] Original post and accessories not recovered. Found no evidence of prior monumentation. Found no acceptable evidence of the position of the original corner on the ground. Reestablished the corner midway and on a straight line between monumented section corners 2644.76° morth and south, being the position proportionate to the original record. From this position, both swamp edge calls noted above check well. At the position for the corner, I placed a ITLD.x32 from pipe capped with a 4 dia. cast aluminum MDNR tablet, appropriately stamped.

(C6) Original post and accessories not recovered. Found a 3° dia, cast iron pipe with a spike driven in it's center below the gravel surface of Paint River Road, at the easterly extension of an ancient wire fence line, and in accord with Pisoni's surveys. Distance to monumented corners north and south check fairly well with the original record. Accepted the pipe as the best available evidence of the position of the original corner.

C. Description of monument for corner and accessories established to perpetuate locating the position of the corner:

(E6) Set 1"1.0, pipe with 4" WONR cap. Blazed and scribed the following new bearing trees:

21 Double R. Pine N30E 54.2' 1/45 NBT 9" R. Pine 846E 32.3" 1/45 NBT" 1/48 NBT" 11 R. Pine S66W 29.2' 9° R. Pine N56W 34.6' 1/45 MBT"

Bearings are magnetic.

(CB) Found spike driven into center of 3 cast iron pipe chis "+" on top NE cor. transformer nousing #84E 32.50' Fd. 1/2' rebar \$88E 33.07' 12" Aspen \$80E 35.38' Fd. nail in side.

12" Aspen \$36E 64.96' Fd. nail in side. 3" choic cherry \$86% 25.0' marked "1/4\$ MBT*. Bearings are magnetic. Corner falls 4.5'W. of centerline gravel road.

SZYSZKOSKI LAND SURVEYOR