LAND CORNER RECORDATION CERTIFICATE Filing Requirement of Act 74, Mich. P.A. 1970

For corners in		/ ming rioquii	,	
_	[FBN (County)	Located In:	Corner Code ≠#	
1.	Public Land Survey	T 43h R 32W	05	
2.	Property Controlling in Section	T R L R S 17 T 43N R 12W S 17 T 43N R 32W	5 WC west of 12	

Register of Deeds Stamp & File Number

5. Private Claims

3. Miscellaneous

Property in Sec.

D5 June 08, 1994 WC May 18, 1994

I. Stephan J. Szystkoski , in a field survey on 5 klay 17, 1994 , 19 do hereby certify that under requirements of P.A. 74, Michigan P.A. of 1970, the corner points mentioned in lines 1 and 2 above were in conformance with regulations and rules therefore as required in the current manual of survey instructions of the United States Department of the Interior, Bureau of Land Management or by a decree of a Court of Law and/or that the corner points mentioned in lines 3, 4 and 5 above were in conformance with the rules of the Michigan Board of Land Surveyors or by a Decree of a Court of Law, established, re-established, monumented, re-monumented, recovered, found as expressed below

NOTE: Not more than 4 corners, all in the same town and range, may be recorded on this certificate.

A. Description of original monument and accessories and/or subsequent restoration:

(05) Quarter corner common to Sections 8-17. Corner established by Z.B. Searles, 1849 as follows: Set cedar post, W. Pine 28 S26# 23, Cedar 18 H15E 11. Survey drawing by Donald Lappala dated 2-24-1980 at Iron County Equalization office show corner monumented by From pin midway and on a straight line between section corners 2606.72' east and west. Survey recorded by Gary L. Pisoni 1.1-P.112 shows iron pin found and used in survey in Section 8. Also survey by Pisoni dated 4-07-92 shows 1/4 corner used to control survey of part of Govt Lots 3 and 4. Found no subsequent record.

15-Sec. 17] Morth 1/15 corner Section 17. Corner not established in the original survey. Found no subsequent record.

(MC west of 12) Witness corner between the South 1/16 corner 18/17 and the South 1/16 corner of Sec. 17. Corner not established in the original survey. Found no subsequent record.

B. Description of corner evidence found and/or method applied in restoring or reestablishing corner:

(05) Original post and accessories not recovered. Found no acceptable evidence of the position of the original corner on the ground. Recovered the 5/8° from pin below the surface of Rock Crusher Road and determined it to be 0.3° North and 0.14' East of the proportionate position. Accepted the monument as recovered as being a careful and faithful reestablishment of the corner position. Roted several RBTs marked with upper and lower blazes and measuring nails placed by unknown surveyor.

45-Sec. 17) Found no monumentation at the corner position. Established the corner midway and on a straight line between Quarter corner 1318.84' north and Center of Section 1318.84' south. At the position for the corner, I placed a 171.0.x32' iron pipe capped with a 4' dia. cast aluminum MDNR tablet, appropriately stamped.

(MC west of 12) Found no monumentation at this position. Established the corner at a convenient distance east of the Paint River (being 50' east of the edge of the wet tag alder marsh bottomlands) and on a straight line between corners #10 and #12 of Section 17. Corner #12 being a monumented 1/16 corner, and corner #10 being an unmonumented computed postion midway between adjacent government corners. At the position for the corner, I placed a 1"I.D.x32" from pipe capped with a 4" dia. cast aluminum MDNR tablet, appropriately stamped. From the monument, the monumented south 1/16 corner of Section 17 is 1892.48' east along the 1/16 line.

C. Description of monument for corner and accessories established to perpetuate locating the position of the corner.

(05) Found 5/8° rebar in Rockcrusher (5) Set 1° I.D. pipe with 4° MDNR cap. (WC w. of 12) Set 1" I.D. pipe with 4" road. Made an unmarked upper blaze and Blazed and scribed the following bearing MONR cap. Blazed and scribed the set measuring nail in side blaze in: trees: following bearing trees: 11" R. Pine N48W 50.20" 8° Balsam N46W 12.2' "1/16S BT 8° Maple in clump N29W 30.5' 2' Maple N73E 31.7' Measured the existing NBTs: "1/16S BT" 34" White Pine N65E 58.3" "WC BT" 12" J. Pine N86E 23.99' 5' Maple S66E 26.1' "1/165 BT" 24' White Pine \$49E 54.4' "WC BT" 12" R. Pine S13E 34.26" 5' Maple \$73W 20.8' "1/16S BT" 6" B. Ash S54W 14.0" WC BT 14" R. Pine #82# 42.59' Set a 3" squared maple post adjacent. Tag alder marsh is 50' West Rearinos Iron is 2 ft. W'ly of E, edge road. Bearings are magnetic. are magnetic. Bearings are magnetic.

Signed by Stephan J. Syngholi

Date 6-14-94

SZYSZKOSKI – SZYSZKOSKI – LAND DRM APPROVED BY MICHIGAN S DE SOMRO OF JAND SUNVEYING JAN